RESOLUTION NO. 12-30

A RESOLUTION OF THE MAYOR AND THE CITY COUNCIL OF THE CITY OF DORAL, FLORIDA ADOPTING THE ROADWAY MAINTENANCE CAPITAL IMPROVEMENT PROGRAM (RMCIP) AS PRESENTED BY C3TS IN CONJUNCTION WITH THE PUBLIC WORKS DEPARTMENT; AND PROVIDING FOR AN EFFECTIVE DATE

WHEREAS, the Public Works Department has been implementing a 5-year Roadway Maintenance Capital Improvement Program (RMCIP) which was adopted by Council in 2007 and developed for the pavement maintenance and rehabilitation of local roads; and

WHEREAS, the City's consultants, Castella, Carballo, Thompson and Salman (C3TS), conducted an update of the RMCIP by evaluating the present condition of the pavement on our local roads; and

WHEREAS, Staff respectfully requests that the City Council adopt the RMCIP as presented by C3TS (Exhibit "A") in conjunction with the Public Works Department.

NOW, THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DORAL AS FOLLOWS:

<u>Section 1</u>. The City Council of the City of Doral hereby adopts the RMCIP as presented by C3TS (Exhibit "A") in conjunction with the Public Works Department.

Section 2. This Resolution shall become effective immediately upon adoption.

The foregoing Resolution was offered by Vice Mayor DiPietro, who moved its adoption. The motion was seconded by Councilmember Boria and upon being put to a vote, the vote was as follows:

Mayor Juan Carlos BermudezYesVice Mayor Michael DiPietroYesCouncilmember Luigi BoriaYesCouncilmember Pete CabreraYesCouncilmember Ana Maria RodriguezAbsent

PASSED AND ADOPTED this 14th day of March, 2012.

JUAN CARLOS BERMUDEZ, MAYOR

ATTEST:

BARBARA HERRERA, CITY CLERK

APPROVED AS TO FORM AND LEGAL SUFFICIENCY:

JIMM

CITY OF DORAL

PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT









MARCH 2012



PROFESSIONAL ENGINEER CERTIFICATE

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

I hereby certify that I am a registered professional engineer in the State of Florida practicing with C3TS, P.A., a corporation, authorized to operate as a an engineering business (EB 5022), FEID No. 65-0039493, by the State of Florida, Department of Professional Regulation, Board of Professional Engineers, and that I have reviewed or approved the evaluation, findings, opinions, conclusions, or technical advice hereby reported for:

Project:	2011 CITY WIDE PAVEMENT EVALUATION AND FIVE-YEAR
	MAINTENANCE & REHABILITATION PLAN

FIN:	<u>N/A</u>
C3TS No:	00426-011-0001-03
Location:	Miami Dade County, Florida
Client:	CITY OF DORAL, FLOIRDA

This Engineering report includes a summary of data collection efforts and an engineering analysis for the City of Doral Pavement Evaluation 2011 and Five-Year Maintenance & Rehabilitation. I acknowledge that the procedures and references used to develop the results contained in this report are standard to the professional practice of engineering and planning as applied through professional judgment and experience.

Name:	Dave E. Clarke, P.E.
Signature:	
P.E. Number:	66553
Date:	1







TABLE OF CONTENTS

1.0 2.0	EXECUTIVE SUMMARY
2.1	Consultant Role2
2.2	Pavement Management Systems Concept3
2.3	Purpose4
3.0	METHODOLOGY
3.1	Roadway Network Inventory5
3.2	Data Collection
3.3	Pavement Condition and Rating5
4.0	DATA COLLECTION RESULTS 11
4.1	Pavement Inventory
4	.1.1 History12
4.2	Pavement Condition Index14
4	.2.1 PCI Results 2007 versus 2011
5.0	DATA CONDITION AND PREDICTION MODELS 16
5.1	Prediction/Deterioration Models16
5.2	Condition Analysis24
6.0	MAINTAINANCE AND REHABILITATION POLICES AND UNIT COSTS 27
6.1	M&R Planning Based on Minimum PCI
6.2	M&R Planning Based on Critical PCI Method30







LIST OF APPENDICES

6.3

APPENDIX A	MAPS OF THE CITY OF DORAL
APPENDIX B	PAVEMENT CONDITION RESULTS
APPENDIX C	RECOMMENDED PROJECTS
APPENDIX D	SCOPE OF SERVICE
APPENDIX E	REQUESTED DORAL PROJECTS FOR 2011/2012

LIST OF FIGURES

Figure 1-Pavement Life Cycle
Figure 2-Pavement Condition Index Rating Scale
Figure 3-ERoadInfo Data Collection Vehicle
Figure 4-Pavement Area Distribution by Section Rank
Figure 5-City of Doral Pavement Section Age Since Last Major R&R
Figure 6-City of Doral Pavement Rating 2011
Figure 7-Family Prediction Model "S"
Figure 8-Revised Family Prediction Model "S"
Figure 9-Review of Family Model Data "S"



Figure 10-Review of Family Model Data "P"

Figure 11-Review of Family Model Data "T"

Figure 12-Predicted PCI for Primary "P" Pavement Sections

Figure 13-Predicted PCI for Secondary "S" Pavement Sections

Figure 14-Predicted PCI for Tertiary "T" Pavement Sections

Figure 15-M&R Budget for Doral Based on Minimum PCI of 86

Figure 16-Average Weighted PCI after Improvement Based on Minimum PCI of 86

Figure 17-Revised M&R Budget for Doral Based on Minimum PCI of 71 to 91

Figure 18- Revised Average Weighted PCI after Improvement Based on Minimum PCI of 71 to 91

Figure 19-M&R Budget for Doral Based on Critical PCI Method

Figure 20-Average Weighted PCI After improvement Based on Critical PCI Method

LIST OF TABLES

Table 1-Asphalt-Surface Distress Classification for Roads and Parking Lots

Table 2- From PAVERTM Summary of Pavement Section Condition Report

Table 3-M & R Cost by Condition for Doral Roads

Table 4-Variable Minimum Conditional Table

Table 5-Budget Summary for Critical PCI











1.0 EXECUTIVE SUMMARY

This report provides an overall assessment and evaluation of the pavement condition of streets maintained by the City of Doral. M&R plan. Results from this evaluation was then used developed a Five Year Maintenance and Rehabilitation Plan.

C3TS recommends major Maintenance and Rehabilitation (M&R) for the City of Doral's Asphalt Concrete (AC) pavement roadway network based on knowledge and professional judgment associated with Pavement Management Systems (PMS). Recommended work activities for M&R shall consist of complete pavement reconstruction, milling and resurfacing (1-inch), and 1-inch overlay.

Work plan and Budget analysis was performed for in Paver[™] based on the Minimum Pavement Condition Index (PCI) and Critical PCI. The minimum PCI condition began by maintaining an annual PCI of 86 but was later varied to reduce the high budget cost in the first year. The critical PCI method used maintained the current area weighted PCI using a critical PCI of 70. One major disadvantage of this critical PCI method is that major critical projects where PCI are below critical are given low priority. For example, in a five year plan PAVER[™] a pavement section with a PCI rating of 68 could be scheduled for M&R in year one while a pavement section with a PCI rating of 30 could be scheduled in year four or even the final year of the M&R plan. The minimum critical PCI method also included planned work for fiscal year 2011/2012 which the City of Doral wanted to include.

The cost of the variable minimum PCI method is approximately \$12 million over the 5 years with about \$2.4 million required in each year. The average weighted PCI after work is completed under this plan is 86, 93 92, 94 and 93 for 2012, 2013, 2014, 2015 and 2016 respectively.





Constanting

The total cost of the Critical PCI method is approximately \$5.2 million with approximately \$1.9 million required in the first year. The average weighted PCI after work is completed under this plan is 86, 87, 86, 85 and 83 for 2012, 2013, 2014, 2015 and 2016 respectively.

C3TS recommends the **Minimum Condition PCI method** to develop the M&R plan for the City of Doral. City of Doral will achieve a **PCI above 91** for each roadway segment by the end of the work plan period and an area weighted PCI of 93 implementing this method.

2.0 INTRODUCTION

The City of Doral, located in Miami-Dade County Florida, was incorporated on June 24, 2003, and is home to approximately 46,000 residents. One of 35 municipalities throughout the County, the city was ranked 51st in "The "Top 100 Places to live and Launch a Business in the United States" by CNN Money and Fortune Small Business in 2008. This unique and attractive quality, mixed land use, and close proximity to Miami International Airport makes the City of Doral one of the most vibrant and fastest growing Cities in the Country, regularly hosting in excess of 100,000 people who work within the City. Doral occupies a land area of approximately 15 square miles and maintains more than 57 miles of existing roadway network. The City's aptitude for attracting residents and business alike necessitates the need for a reliable Pavement Management System (PMS) to ensure a smooth riding surface at all times. This will allow the City to predict future pavement conditions and strategically identify cost effective maintenance and rehabilitation (M&R) projects.

2.1 Consultant Role

C3TS was retained by the City of Doral to perform automated field data collection along all City owned road (57 miles) with image capture photos every 50-ft for asset





- Martines

management. This data will be used to determine the Pavement Condition Index (PCI) based on current conditions and develop a PMS utilizing a software called Paver[™] 6.5 developed by the US Army Corps of Engineers. ERoadInfo, a sub consultant for C3TS, conducted the data collection and populated the results into Paver[™] to determine the PCI for the existing roadway sections.

2.2 Pavement Management Systems Concept

A PMS provides a powerful tool to assist Municipalities in making decisions regarding M&R planning and implementation. Successful pavement management requires scheduling of M&R during the appropriate stages of deterioration before to optimize budgets and overall performance. Figure 1, taken from "Pavement Management for Airports, Roads and Parking Lots 2005", Second Edition by M.Y. Shahin, provides a conceptual illustration of how a pavement normally deteriorates and the associated cost of rehabilitation at various times throughout its life.




Figure 1-Pavement Life Cycle

The length of "satisfactory" years of a pavement is a direct correlation on how well the pavement has been maintained. Implementation of M&R before significant drop





off in pavement condition can result in major cost savings over the life of the pavement. Another advantage of preventive M&R besides cost, is reduced traffic detours and lane closures associated with pavement repair beyond critical deterioration (complete reconstruction) which has a negative impact on business and residents. By predicting the deterioration rate of pavement along with using standardized unit cost and minimum pavement performance requirement, a successful M&R Plan can be developed and implemented.

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

2.3 Purpose

The ultimate objective of this project is to survey all City owned roads, determine roadway conditions using PCI rating, and identify future five-year pavement M&R plan for the City of Doral. These objectives were accomplished through a series of systematic procedures which include:

- Pavement Inventory
- Data Collection
- Pavement Condition Rating
- Pavement Future Performance
- Prioritization of Repair & Rehabilitation
- M&R Projects

This report summarizes our findings and results of the 2011 Pavement Management System using Paver[™] for the City of Doral.





(E Kinner

3.0 METHODOLOGY

3.1 Roadway Network Inventory

As a starting point, a Geographic Information System (GIS) base shape file of Doral's road network was provided. The road network contained all City (Doral), Private (Gated Developments), County (Miami-Dade County), and State (Florida) owned roads including street names, ownership, and section length. Majority of the roads owned by the City have both curb and gutter and sidewalk consisting of one or two travel lanes in both directions. Also contained in the database was the classification for each roadway section used in the Section Ranking. The database was modified as required to match current field conditions. Also the 2007 PCI was also updated into the GIS base file. This PCI information was contained in the 2007 PMS report conducted by Sanchez-Zeinali & Associates Inc. and their sub consultant Applied Research, Inc. (ARA). A map of all the current roads and ownership within the limits of the City of Doral can be found in Appendix A.

3.2 Data Collection

Data collection involved automated surveying of the existing roadway surface of approximately 57 centerline miles of roads owned by the City of Doral, Florida. Image capture of all City owned roads was taken every 50-ft. An additional 33 centerline miles of County owned roads was driven to capture roadway images that can be used for hyper-link method to view these images. The total mileage for the City and County roads is estimated to be approximately 100 miles.

3.3 Pavement Condition and Rating

The City of Doral has decided to use Paver[™] software version 6.5 for their PMS which uses the PCI method to determine distress in pavement. Therefore, the PCI will be used to rate the present condition of the surface road network. The PCI is a





subjective method of evaluating distresses in pavement by providing a numerical rating between 0 and 100 where 0 is worst and 100 is best condition. This rating is based primarily on the type, quantity and severity of distresses for each pavement section. This concept was developed by the US Army Corps of Engineers in the late 1970's and was adopted by the American Society for Testing and Materials (ASTM) as the standard for airfields in 1993 and roads and parking lots in 1999 as well as other agencies. Paver[™] 6.5 uses the ASTM 2010 standard for new distress in pavement, ASTM D 6433-09 Standard Practice for Roads and parking Lots Pavement Condition Index Surveys. The overall rating scale used in Paver[™] for the PCI can be found below in figure 2. For this project, the standard PCI rating scale is used. Paver[™] allows for customization of the standard color rating scale should the user wish to adjust the ranges.




Figure 2-Pavement Condition Index Rating Scale

All pavements will deteriorate over time. This deterioration is typically a result of distresses that may be attributed to traffic applications/load, construction, materials, environment, and climate. In asphalt surface roads, the current ASTM standard for





(and

PCI currently recognizes pavement deterioration as a function of twenty distress type, three levels of severity (L-low, M-medium & H-high) and distress amount or density. A summary of these distresses, code, severity levels and causes are provided below in table 1 below.

Code	Distress	Severity Levels	Probable Cause
01	Alligator Cracking	L,M,H	Traffic
02	Bleeding	L,M,H	Materials, Construction
03	Block Cracking	L,M,H	Climate
04	Bumps and Sags	L,M,H	Climate, Traffic
05	Corrugation	L,M,H	Traffic
06	Depression	L,M,H	Construction
07	Edge Cracking	L,M,H	Traffic
08	Joint Reflection	L,M,H	Climate
09	Lane/Shoulder Drop-off	L,M,H	Other
10	Longitudinal and Transverse Cracking	L,M,H	Climate
11	Patching and Utility Cut Patching	L,M,H	Other
12	Polished Aggregate	N/A	Traffic
13	Potholes	L,M,H	Traffic
14	Railroad Crossings	L,M,H	Other
15	Rutting	L,M,H	Traffic
16	Shoving	L,M,H	Traffic
17	Slippage Cracking	L,M,H	Traffic
18	Swell	L,M,H	Climate, Environment
19	Raveling	м,н	Materials
20	Weathering	L,M,H	Climate



CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

L=Low, M=Medium, & H=High

The condition survey was completed by eRoadInfo using a surface mobile data collection surveying vehicle that is equipped with cameras and various Global





Position System (GPS) equipments. Prior to performing the inspection the roadway network was divided into manageable sections. Using the GIS base file, the sections were typically identified from intersection to intersections.

The ERoadInfo Capture module offers digital roadway imaging at a 1280 x 960 resolution taken from up to 6 cameras (including a high resolution 11 mega-pixels camera) from the moving survey vehicle. The cameras are mounted in adjustable housings above the vehicle for easy access, best viewing angle, and protection from outside elements. The cameras are pointed forward, left side, and right side with right-of-way views. The field of view includes the lane of travel, street signs, guide signs, mile markers, pavement markings, billboards, vegetation, terrain, and overhead signs. The images from the cameras are mounted on the rear of the vehicle to capture the reverse view. The camera positions are fully adjustable and can be locked once the desired position is acquired. Pavement inspection can be completed in real-time with 100% distance coverage at a speed from 3 to 70mph.

Typically, the images are captured at 55 ft intervals. The images are stored as JPEG files. Each image is approximately 200kB. At 3 frames per 25 ft, the images will require about 120 MB per mile. For this project images were captured every 50-ft.

The images position and orientation data are captured into a GIS database along with the data. The data can be easily transported from the on-vehicle computer to a central network using wireless network or removable hard drives.

Main Features

- 360 Degree panoramic camera collecting data at 15 MP
- High definition (HD) camera with 11 MP 4000x2600 resolution images





Synchronized data collection with up to 6 cameras

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

- Flexible camera locations and orientation
- Full-frame, non-interlaced JPG format
- Images are associated with Inertial Navigation System (INS) to acquire accurate location as well as camera heading, roll, and pitch information.
- Images are stored on hard drives in real-time. No post processing required.
- System automatically finds the street based on the GPS when capturing.
- System includes a progress tracking feature to verify all roads are covered.
- Capture is paused when vehicle stops moving.
- Distance information is automatically attached to all images.
- Bookmark and voice notes can be captured to provide additional information not easily visible from images.

ERoadInfo fully integrated data collection vehicle (figure 2) provides complete pavement data collection capability with a fully integrated pavement data collection vehicle that includes GPS/INS sensors, Right-of-way cameras, Longitudinal profiler (IRI), rutting measurement system, downward scanning and automatic crack detection system and optional Ground Penetrating Radar (GPR) system.








Figure 3-ERoadInfo Data Collection Vehicle

The ERoadInfo Playback and Asset Inventory module allows users to review images of the roadway and collect assets that appear in the field-of-view from the comfort of their desk.



Images from field Survey

The images collected using the ERoadInfo roadway imaging module can be played back like a VCR. When reviewing the images, assets visible on the image can be





captured from the office desk by simply clicking on the location of the asset in the image.

The data is collected using the photogrametry measurement based on the images' location and orientation information recorded during the survey. During this project this data was stored directly into a central GIS database and imported into $Paver^{TM}$ where the PCI was calculated.

4.0 DATA COLLECTION RESULTS

4.1 Pavement Inventory

In all, there were approximately 490 roadway segments based on the original GIS data from the City of Doral. Field survey indicated that some of these roadway segments were either grass surface or now private property and were removed from the PAVER database for the determination of the PCI. The total pavement area is approximately 8, 152 million square feet. Within the GIS data base, the City of Doral roads were classified as either class 4, 5 and 6. The City of Doral defines class 4 roads as Minor Arterial, class 5 as Collector and class 6 as Local Roads. In Paver[™], a section ranking was assigned to all pavement sections based on these classifications to facilitate the data processing. Roads identified as class 4 were assigned a section ranking of "P" for primary, class 5 were assigned section ranking of "S" for secondary and class 6 assigned section ranking of "T" for tertiary. Approximately 70 percent of existing roadway within the City of Doral can be described as secondary, 17 percent as primary and 13 percent as tertiary. The breakdown of pavement area by section ranking is provided in figure 4. Additional information for each section including PCI, rank, surface type, and dimensions can be found in Appendix B.








Figure 4-Pavement Area Distribution by Section Rank

OF DORA

EVALUATION 2011 AND FIVE-YEAR NCE & REHABILITION REPORT

4.1.1 History

Pavement condition work history is the most crucial information used by PAVER[™] in computing PCI, determining deterioration curves and future maintenance plan. By knowing when pavement sections have been reconstructed or the last construction date, integrated with PAVER[™], will allow the City of Doral to continue to successfully manage their roadway network now and in the future.

Most of the information obtained on the construction history was obtained from the 2007 PMS report conducted by Sanchez-Zeinali & Associates Inc. and their sub consultant Applied Research, Inc. (ARA). The report ultimately concluded that the construction dates used may be inaccurate. In PAVER[™], these inaccuracy produce data points that are classified as "Outliers" or "Out bounds" and is further discussed in section 5.1. The inaccuracy was a result of the limited construction history





Carlos and the second second

documentation from the City of Doral. The City of Doral also provided additional information on a few pavement sections that were rehabilitated and have been included in the work history inventory in PAVER[™]. Other pavement sections last construction date was estimated by reviewing the Miami Dade County parcel records of developments adjacent to these pavement sections. Google Earth has a tool called imagery date which allows you to go back in a few years and view the current images taken. This tool was also used to assist in determining the last construction date for roadway segments. Therefore, based on the limited information, the majority of roadway segments were treated as if they underwent major rehabilitation and reconstruction (R&R) characterized as "Complete Reconstruction AC" or "2-inch Cold Mill & Overlay" (milling and resurfacing). Figure 5 provides the pavement age at last inspection as a percentage of the total pavement area that underwent major R&R. Nearly 66 percent of the pavement sections underwent major work between 6-15 years ago, while about 25 percent in the past 2 years.




Figure 5-City of Doral Pavement Section Age Since Last Major R&R





and the second second

PAVERTM provides a statistical summary report of the section report is provided in table 2. The overall average age at inspection for the pavement network is 8 years.

Age Category	Average Age at Inspection	Total Area (SqFt)	Number of Sections	Arithmetic Average PCI	PCI Standard Deviation	Weighted Average PCI	
0-02	0.97	2,093,731.83	134	98.75	4.14	98.58	
03-05	4.50	77,045.63	4	95.00	7.55	93.66	
06-10	8.22	2,650,424.79	186	87.07	13.74	87.00	
11-15	12.94	2,723,261.20	135	84.33	11.97	85.00	
16-20	16.48	606,956.01	31	81.16	12.52	80.45	
All	8.03	8,151,419.45	490	87.90	12.80	88.88	

Table 2- From PAVER [™] Summary of Pavement Section Condition Report

MENT EVALUATION 2011 AND FIVE-YEAR

4.2 Pavement Condition Index

ITY OF DORAL

Pavement survey was conducted in accordance with ASTM D 6433-09 which characterizes distress type, severity (Table 1) and quantity for sample areas within each pavement section. Visual data collected on pavement sections for distress, severity and quantities were imported into PAVER[™] and the PCI value for each pavement section was calculated. The PCI returns a numerical rating value between 0 and 100 (Figure 2) to describe the condition of the pavement. A summary of pavement ratings for the City of Doral roadway network for 2011 as well as 2007 can be found in Appendix B.

4.2.1 PCI Results 2007 versus 2011

The PCI results between 2007 and 2011 shows for the majority of the roadway networks show an overall increase which is not consistent with the behavior of





pavement. All pavements will undergo some level of deterioration over time even if there is no traffic. In some segments the overall increase in PCI is expected since these roads underwent major (M&R) between 2009 and 2010. For example, NW 84th Avenue between NW 23rd Street and NW 25th Street had a PCI rating of 44.9 in 2007 and 93 in 2011. Information provided from the City of Doral indicates that this segment was milled and resurfaced during the fiscal year 2010-2011. By contrast, NW 52nd Street between NW 77th Ct and NW 78th Avenue has a PCI of 34.3 in 2007 and 73 in 2011. There is no record of the segment undergoing any M&R, but the increase in PCI suggests that some work must have been done on this pavement section. Some localized preventative or stop gap (filling potholes, patching etc.) maintenance must have been performed on this segment and others that show an increase in the 2007 PCI values for which no record of any M&R exist.

Figure 6 below provides the overall condition of the roadway network based on the percentage of pavement area. Overall, approximately 63 percent of the pavement is considered in "Good" condition, 24 percent "Satisfactory" condition, 11 percent "Fair" condition, and 2 percent in "Poor" condition.








Figure 6-City of Doral Pavement Rating 2011

CITY OF DORAL

5.0 DATA CONDITION AND PREDICTION MODELS

5.1 Prediction/Deterioration Models

Paver[™] uses what is called the Family Method to produce predication/deterioration models. Since PCI is used as an indicator of the overall pavement condition, the predication/deterioration models essentiality looks at the PCI versus time in the future. The family method represents a group of pavement sections surveyed that have similar characteristic. In Paver[™], the software allows users to select families based on last construction date, PCI, Rank, Surface, section category, type, Use, and Zones. Selections of these families are often driven based on available data and the overall accuracy of condition prediction. Before a successful family model can be built we must first identify the pavement family, filter the data, conduct an outlier analysis, develop the model and finally predict the pavement section condition.





For this project, the pavement family used consisted of three primary categories used in PaverTM which included the branch use, surface type and section rank. In PaverTM the branch use is described as "Roadway", surface type as "asphalt-concrete (AC)" and the section rank as either "P", "S" or "T" as described in section 4.1 of this report. Three separates prediction models were developed based on branch, surface type and section rank. The branch and surface type were identical for each model but the section rank (P, S, or T) varied based on the individual rankings. Figure 7 shows the family prediction model for all secondary pavements ("S"). A review of the model equation and statistics show a 4th degree polynomial and a coefficient correlation 0.663 (1 is perfect correlation) and a standard deviation of 8.939. The further out the degree of polynomial, the less accurate the model becomes. A standard deviation under 12 is also an indication of a fairly reliable model.









Figure 7-Family Prediction Model "S"

The best fit curve will only extend out as far as the available data. An additional data point at year 25 and a PCI of 0 is added to force the curve to zero. This was done with all the other family models ("P &T") to enhance the pavement prediction curve using an estimated life of 25 years. The revised prediction model "S" and equation statistics is calculated and shown in figure 8.








- Conservation

review of the outlier's pavement sections in this model indicate a PCI below 55 which is where the Critical PCI is set. A review of the out of bounds pavement sections indicate that these pavement sections recently underwent major M&R based on the information received from the City of Doral. All secondary pavement sections will be assigned to this prediction model which will help developed M&R plans. Similar data section abnormalities were observed in family predication models "P" & "T". The upper and lower boundaries (blue lines) of the model are established by the PAVERTM software to represent data points that are considered "Out of Range". PaverTM disregards any "Out of Range" data points when producing the best fit curve of the prediction model. Data points that are out of range typically suggest that the pavement section is in very bad condition or there is inaccurate construction history data. The red lines represent the outlier boundaries that PAVERTM uses to constrain the best fit curve to produce an accurate prediction.











water weeks have a second of S19 HBAVI 🖪

dett wohnth and-dat expensionalitient coldat el

🛙 Inversion 🍐 Work 🖉 FCI 🔭 Report 💪 Field Wookling 🎦 Cond Analysis 🖗 WER Ren 🍈 Sils/Tiree Sel 🔃 Liel Sel 🖉 Wickerds 🔄 Weral Weru P Help 🕌 Abour FRYFE

	-		-			-		Prediction	Sele
The s	K. A.		1						
•)
									*
S	JA	1200	1SH1/E/MN	QADRYTD	58 0 Onger	0.82	0.08	818	
S	JA	0000	3VAHTB7WN	0A0RYTD	58 0 Onlier	0.67	D'19	67.8	12
S	JA	0900	1SISIZ/MN	QAORYTO	SEO Orther	0.77	0.12	11 3	
S	3A	0100	15151#MN	QAORYID	64.0 Outlet	0.82	0 11	1.6	
S S	JA	0900	151517/MN	CITYROAD	330 0118	0.82	0.57	226	
S	JA	8100	1SH18EMN	QAORYTO	45.0 0.464	0.82	38.0	826	
S	JA	0100	ISHI/E/MN	QAORYTO	26.0 Dufier	0.82	075	67.8	
S	3A	0100	3VAH1411WN	0.0UUSID	10/00/00/00/07	0.82	0.68	22.6	10
S S S	JA	0520	AW114THAVE	QAORYTO	sbruoß io tu0 021-	0.82	330	21.5	
S	JA	0150	3VAH1111WM	QADRYTO	sbruoß to tu 0 0 22-	0.82	0.001	21.6	1
S)A	0/10	AWAT14THAVE	QAORYTD	sbruog to tu0 0.21-	0.82	330	21.6	-
S)A	0500	3VAH1411WN	QAORYTO	sbruog to tu 0.0.01-	0.82	016	22.6	
5 5 5	3A	0810	3VAH1411WN	CADRYTO	sbruod to tu 0 0.55.	0.87	0 001	226	
S	JA	0700	3VAHTBTWN	CADRYTO	sbruoß to tu 0.0.0.0.	0.62	0.86	813	
S	3A	0900	3VAHTEE'WN	CADRYID	sbruog to 10 0.65-	0.77	0.001	011	
S	JA	0610	3VAH14TTWN	OADRYTD	sbrueß to tul (0.05-	0.82	0.96	21.6	
S	JA	0700	3VAH186'WM	0A0RYTD	sbrueß to 10 0.21-	0.18	0 001	0.8	
5	JA	0030	3VAH1411WN	QAORYTO	sbruod to tu 0 0.05-	0722	0.726	2111	
S S S	JA	0050	NW-381HAVE	QAORYTO	sbruog to tu0 0.01-	018	0 001	08	-
5	JA	0030	1SH10S/MN	CADRYROAD	sbrud to tu 0 0.55-	0.82	0 001	22.6	
5	3A	0200	1SH10S/MN	CADRYROAD	sbrueß to tu 0 0.61-	0.82	0.76	22.6	
5 5 5	<u>JA</u>	0030	3VAHT8EWN	0408710	sbruog to 10 0.61-	0'18	0.001	08	-
2	34	0900	3VAHT8E'WN	01780AD	sbrue B tu 0 0.21-	0.18	0 001	08	-
2	34	0010	1SH10SMN	0408710	sprug to tu 0 022.	082	0 001	22.6	
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	2A DA	0900	1SH10S/MN	QAORYTO	spunds para gounds	0.82	0.86	226	-
5	34	0040	1SON25/MN	017R0AD	spring to tuo 0.61-	0'22	0.96	1513	
5	2A	0900	AVAHTEEWN	CITYROAD	spunds of a going	0.77	0.001	011	-
5	34	0,200	AW114114VE 1SH198/MN	CITYROAD	spunds of the genut	0.82	1000	22.9 22.9	-
5 C	AC AC	0050	15H138/MM	0408YTD 0408YTD	sbruod to tu 0 0.31- sbruod to tu 0 0.31-	078	0.001	229	
0	24	0040	15H138/W	QAORYTO	sbruoß to 10 0.11-	078	0.86	229	
2 C	34	0010	ISH150/W	0408710	sbruog to to 0 0.15	0722	0.00	2/11	
6	34	0130	AWHININW	QADRYTD CADRYTD	spunds on of Sounds	0.82	0.001	EL 6	
s	34	0200	3VAH14THAVE	QAORYTO CAORYTO	sbrud to the Bounds	0.82	0.001	226	-
s	34	0900	3VAH14TTWN	CADRYTO AD	sbrue to the grands	0.82	0 001	226	
s	34	0110	NW/84THAVE	CITYROAD	sbruog to tu0 0.81-	0.62	076	813	
S	3A	0900	3/VH118/MN	QADRYID	sbruoß to tu 0 0.15-	0.62	0 001	EL B	
5 5 5 5 5 5 5 5	JA	0200	3VAHT87WN	QAORYTD	abruo a b u O O ES-	011	0 001	2201	
S	34	0350	3/WHIFILMN	QAORYTO	sbruds to 0.005-	0.82	0.96	226	
S	JA	0900	1SON/2S/MN	QADRYTD	sbruog to tu 0 0.31-	0.17	0.65	1573	
S	JA	0130	3VAH148WN	QADRYTD	sbruce to tub 0.21-	0'52	0.06	22.91	
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	3A	0040	3VAHT48WM	QAORYTO	sbruog to tu 0 0.51-	0.52	076	22.91	
S	JA	0300	AVAHINI WW	CADRYTO	spunog jo yr o 0720	0.11	0.65	2271	
S	JA	0100	3VAH14TTWN	QADRYTD	sbruce to tub 0.55-	0.82	0.001	216	
S	37	0110	3/WH111LMN	QAORYTO	sbruoß to tud (0.81-	0.82	0'26	21.6	
S	JA	0800	3/WHINLIMN	CADRYTD	sbruod to tu0 0.05-	0.82	0.96	21.6	
5	JA	0220	3VMH14THWN	GAORYTO	sbruce to tub (0.81-	0.87	0.96	22.6	
S	JA	0200	AW84THAVE	QAORYTO	-130 Out of Bounds	052	0.88	22.91	
£Я	soehu2	CectionID	BranchiD	Obhowten	Difference Status	IsboM	60	q2n1 te egA	
				-		-			мау
	0							gailsbolk noitel	bien

"2" stad leboM vlims7 to weives9-9 erugi7








Figure 10-Review of Family Model Data "P"

Figure 10 shows the family prediction model for all the primary "P" pavement sections and the associated statistics. The model was manipulated in similar fashion as the family model "S" to enhance the best fit prediction curve.








Figure 11-Review of Family Model Data "T"

Figure 11 shows the family prediction model for all the tertiary "T" pavement sections and the associated statistics. The model was manipulated in similar fashion as the family model "S" to enhance the best fit prediction curve.





Constant.

Before the final M&R plan is implemented and accepted the outliers and out bounds pavement sections will have to be field verified to ensure there were no errors in the data collection.

5.2 Condition Analysis

CITY OF DORAL

PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

The pavement condition analysis or condition forecast determines past and future performance of pavement networks or individual sections. Paver[™] uses the last construction date and last inspection date which is then interpolated to determine past pavement condition. The "last construction date" was taken from the 2007 PMS report conducted by Sanchez-Zeinali & Associates Inc. which concluded that the dates were not very accurate due to limited information. Other information on "last construction date" was provided by the City of Doral and updated the corresponding pavement section. The future pavement condition is determined using the prediction/deterioration family models developed in 5.1. For each pavement rankings "P", "S", and "T", three condition forecast models were developed as shown in Figures 12, 13 and 14 respectively. These models forecast the pavement predicted condition or PCI (Area weighted average) 10 years from the last inspection Figures 12, 13 & 14 represent the rate of deterioration date (September 2011). without an M&R plan implemented. These prediction condition models will be used to develop the M&R work plan which is discussed in section 6.0.








Figure 12-Predicted PCI for Primary "P" Pavement Sections

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

Figure 12 shows the forecast for the predicted PCI by area weighted average for primary pavement sections if there is no M&R intervention. At year 2011 the overall weighted PCI for primary pavement sections gradually decreases from 93 to around 68.








Figure 13-Predicted PCI for Secondary "S" Pavement Sections

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

Figure 13 shows the forecast for the predicted PCI by area weighted average for secondary pavement sections if there is no M&R intervention. At year 2011 the overall weighted PCI for secondary pavement sections gradually decreases from 86 to around 58.





Contraction in the




Figure 14-Predicted PCI for Tertiary "T" Pavement Sections

Y OF DORA

ENT EVALUATION 2011 AND FIVE-YEAR ENANCE & REHABILITION REPORT

Figure 14 shows the forecast for the predicted PCI by area weighted average for tertiary pavement sections if there is no M&R intervention. At year 2011 the overall weighted PCI for tertiary pavement sections gradually decreases from 88 to around 58.

6.0 MAINTAINANCE AND REHABILITATION POLICES AND UNIT COSTS

M&R Planning is a systematic approach where a set of activities are applied to pavement sections based on distresses within pavement, budgeting and condition indicators. Paver[™] provides municipalities a variety of methods for M&R prioritization to roadway network or pavement sections. M&R activities for AC pavements are categorized in Paver[™] as Localized Safety and Preventive, Global Preventive, and Major M&R.





Localized Stopgap (Safety) M&R policies are applied to various areas throughout the a pavement section whose PCI is below critical. This work is implemented to the keep pavement section operational and safe until major M&R work (milling and resurfacing, reconstruction etc.) can be applied. This plan usually involves filling of pot holes.

Localized Preventive M&R activities are applied to entire pavement sections whose PCI is above the critical PCI for the purpose of slowing pavement deterioration. This plan involves some surface treatment such as crack sealing and patching.

Global Preventive M&R activities are applied to entire pavement sections whose PCI is above the critical PCI for the purpose of slowing pavement deterioration. This plan involves some surface treatment placing a thin overlay. This option is typically not used in Florida.

Major M&R activities applied to the entire pavement section to improve existing structural requirements. It is used to upgrade pavements below the critical PCI or on pavements above critical PCI to maintain current condition.

C3TS recommends Major M&R for the City of Doral's AC pavement roadway network based on knowledge and professional judgment associated with PMS. Recommended work activities for M&R shall consist of complete pavement reconstruction, milling and resurfacing (1-inch), and 1-inch overlay. Given the amount of daily traffic Doral experiences from residence, business, and visitors, Local and Global treatment will not be adequate to maintain the current roadway network and meet the ever growing demand. Work plan and Budget analysis was performed in Paver[™] based on the Minimum PCI and Critical PCI.





6.1 M&R Planning Based on Minimum PCI

This approach establishes a work plan based on a selected or specified minimum PCI for a pavement network. When this option is selected, Paver[™] provides an annual budget that is required to maintain all pavement levels above the minimum PCI (area weighted average) for the length of the plan. The family prediction models developed and discussed in section 5.1 are used to determine the year in which the PCI for each pavement section falls below this minimum PCI. When this occurs, Paver[™] identifies these sections and multiplies the pavement section area by a set unit cost for M&R activity. Before this can be done, a PCI versus unit cost for major M&R must be established and entered into the system tables of the major M&R families in Paver[™]. "Pavement Management for Airports, Roads and Parking Lots 2005", Second Edition by M.Y. Shahin provides guidelines for establishing the relationship. Table 3 provides M&R activities and unit cost versus PCI used for this project.





C - Consta

M&R Work	Condition	Cost	Unit
	0	\$6.50	SqFt
Reconstruction -	10	\$6.50	SqFt
(8" Base, 2" AC)	20	\$6.50	SqFt
	30	\$6.50	SqFt
_	40	\$2.00	SqFt
Milling and	50	\$2.00	SqFt
Resurfacing (1" AC)	60	\$2.00	SqFt
	70	\$2.00	SqFt
	80	\$1.50	SqFt
Overlay (1" AC)	90	\$1.50	SqFt
	100	\$1.50	SqFt

Table 3-M & R Cost by Condition for Doral Roads

ITY OF DORAL AVEMENT EVALUATION 2011 AND FIVE-YEAR AINTENANCE & REHABILITION REPORT

An inflation of 3 percent rate per year was applied to the M&R unit costs. These unit costs are based on historical estimates from the Florida Department of Transportation as well as similar projects managed by C3TS for various municipalities. The minimum PCI condition was then set at 86 for all City of Doral Roads over the length of work plan. This minimum value was established by recognizing the overall area weighted PCI for the predicted PCI curves for pavement rank "P", "S" and "T" in section 5.2 at the time of inspection was in good condition.

6.2 M&R Planning Based on Critical PCI Method

The Critical PCI is that point where a pavement begins to rapidly deteriorate with time. PaverTM uses this method to apply major M&R polices as well as Localized and Global which are not being considered. In typical asphalt pavement this critical PCI





Come

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

ranges from 55 to 70. The Critical PCI allows municipalities to determine different budgeting scenarios when developing the M&R plan.

When a pavement section is above or equal to this critical PCI, PaverTM verifies if the section is structurally deficient. If the pavement section is structurally deficient then major M&R is applied. If it is not then Localized M&R polices are assigned to the pavement section. Since these distresses are only known within the first year, $PAVER^{TM}$ uses a unit cost versus PCI in subsequent years (Table 3).

If a pavement section is below the Critical PCI the major M&R will be applied to the pavement section. If no funding is available then localized safety M&R is applied. Paver[™] will apply Major M&R plan to all pavement sections that meet this criteria as long as funding is available.

One major disadvantage of this M&R plan is that roadway segments below the critical PCI (sections characterized as failed, serious, very poor, poor in Figure 2) are given low priority in planned projects. Pavement sections that are in fair to satisfactory condition are given a higher priority in the planned projects. For example, in a five year plan PAVER[™] a pavement section with a PCI rating of 68 could be scheduled for M&R in year one while a pavement section with a PCI rating of 30 could be scheduled in year four or even the final year of the M&R plan.

6.3 M&R System Tables

A Cost by condition table (table 3) has been added in PaverTM for the purposes of this analysis. PaverTM M&R priority system tables by default sets the work priority for section rank as high for primary "P" pavement section, medium for secondary "S" pavement sections, and low for tertiary "T" pavement sections. For the purpose of this M&R plan a new M&R priority system table was created and all pavement





sections have been assigned a high priority ranking. In the PaverTM two new work types were added to the system work type tables. The first for a 1-inch Asphalt Concrete overlay (OL_1) and the second for 1-inch cold milling and overlay or milling and resurfacing existing AC for a depth of one inch.

7.0 REHABILATION NEEDS AND BUDGET ANALYSIS

Paver[™] was used to perform M&R analysis after customizing systems tables and establishing unit cost as discussed in section 6.0. An M&R plan was developed based on the minimum PCI being set to 86 for all pavement sections for a five year period. Figure 15 shows the annual amounts needed to maintain this minimum PCI with approximately \$5.5 million of the total \$8.6 million required in the first year. Figure 16 shows the average weighted PCI per year after work has been done.




Figure 15-M&R Budget for Doral Based on Minimum PCI of 86








Figure 16-Average Weighted PCI after Improvement Based on Minimum PCI of 86

OF DORAL

EMENT EVALUATION 2011 AND FIVE-YEAR NTENANCE & REHABILITION REPORT

Each pavement section will have a PCI of above 86 in 2016 based on a minimum PCI of 86 per year.

The disadvantage of using the minimum PCI method is having such a high PCI in the first year calls for a high budget in the first year also. One alternative to reduce the initial cost is to vary the minimum PCI having a lower value in the initial years and maintaining higher value in the later years. After several meetings with the City of Doral, and discussing various budget options the minimum PCI method was revised to obtain optimum results for City's entire roadway network. The PCI was then set to 71 in the first year and gradually increased to 91 in the last year. Table 4 was then used to run the M&R analysis.





Year	Minimum Condition
2012	71
2013	82
2014	87
2015	90
2016	91

Table 4-Variable Minimum Conditional Table

Using the variable minimum PCIs in table 4, the City of Doral can achieve a PCI above 91 for each roadway segment in 2016. Figure 17 shows the revised annual amounts needed to maintain the minimum PCI for each year in table 4. Approximately \$2.4 million will be required per year for grand total of approximately \$12 million over the next 5 years. Figure 18 shows the average weighted PCI per year after work has been done.





Carl Contact in



Figure 17-Revised M&R Budget for Doral Based on Minimum PCI of 71 to 91




Figure 18- Revised Average Weighted PCI after Improvement Based on Minimum PCI of 71 to 91



Carles and the

The revised M&R analysis (Minimum PCI based on Table 4) provides an overall weighted PCI above the minimum and reduces the annual cost compared to maintaining a constant PCI for the length of the term. Another disadvantage of this analysis is that it does not allow you to include any planned work which the City of Doral has expressed interest in performing. A work plan based on this M&R is provided in Appendix C.

Another M&R analysis was performed using the Critical PCI method. This method allows you to enter planned work as well as perform the required analysis and combined the budgets. In this method, the analysis was ran to maintain current area weighted PCI for the network with the critical PCI set to 70. No Localized or Global M&R work was assigned to any pavement sections in this analysis.

Figure 19 shows the revised annual amounts needed to maintain the current area weighted PCI for each year. Approximately \$1.9 million of the total \$5.2 million will be required in the first year. Of that \$1.9 million, about \$1 million represents projects City of Doral requested added for the 2011/2012 fiscal year is found in Appendix E. See table 5 for budget summary. Figure 20 shows the average weighted PCI per year after work has been done.








Figure 19-M&R Budget for Doral Based on Critical PCI Method

Table 5-Budget	Summary f	or Cr	itical I	PCI

Category	Total	2012	2013	2014	2015	2016	2017
Required Project(s)	\$1,062,294	\$1,062,294					
Work Planner	\$4,142,078	\$839,000	\$840,079	\$829,841	\$831,737	\$801,421	
Total Expenditure	\$5,204,371	\$1,901,293	\$840,079	\$829,841	\$831,737	\$801,421	









Figure 20-Average Weighted PCI After improvement Based on Critical PCI Method

CITY OF DORAL PAVEMENT EVALUATION 2011 AND FIVE-YEAR MAINTENANCE & REHABILITION REPORT

6.5







.



APPENDIX B

PAVEMENT CONDITION RESULTS





Бq	tssJ notzeqtan	tast Construction	3DATRU2	สกธส กอช่ว92	Gl nobos2	(32) A3RA	٥T	From	JMAN TJARTZ
86	1102/22/6 Date	1/1/2005	AC	\$ 	OT -	00'296'5	NW 361H 51	AW 251H TEA	3VAHTODIW
62 56	1102/22/6	2002/1/1 2002/1/1	עכ יעכ		09	00'125'*	15 H1/2 MN	NW S6TH SC WN	TAXHIODIM
89	1102/22/6	1/1/2005	AC		30	00 172'7	AW 27TH TEA	15 H1/2 MA	JAVHIOOTHAVE
02	1102/22/6	2002/1/1	AC		05	00'621'5	AW 24TH TEA	NW 27TH TER	W100THAVE
16	1102/22/6	0002/1/1	vc		os	00'189'61	NM JELH LEV	ISHIPT MN	3VAHT001W
66	1102/62/6	2002/1/1	vc	. d	580	00.058,11	NW 481H STREET CIR	455 ft 5 of NW 48TH STREET CIR	MIDSNDVAE
u	1102/52/6	2002/1/1	VC	. d	02	15'161'00	R31 CAED WN	12 1214 WH	MIDSNDVAE
88	1102/52/6	1/1/2005	AC	đ	012	22,270.00	T2 HT34 WM	AW 43RD TER	MIDSNDVAL
66	1102/52/6	1/1/5005	VC		012	00.477,01	12 HT34 WN 10 N 11 222	12 H134 WN 30 N 13 141	3VAGN SOLW
26	1102/22/6	2002/1/1	PC PC		0/1	00'655'5	N1 H160 MM	AD 133972 HT84 WW	3VAGN501W
66	1102/22/6	2002/1/1	AC .		062	00 125'22	15 ONZS MM	NJ HTęp WN	MIDSKDYAE
¥2 26	1102/12/6	2002/1/1	τ. •C		500	00 126'91	NW 561H 168	15 GNZS MN	BAVENCOLAN
26 82	1102/12/6 1102/12/6	7/1/2005 2/1/1/2005	עכ : עכ		001 061	36,913.00	T2 HT82 WM. bead End	831 HT82 WN 12 HT82 WN	3VADNSOLW 3VADNO2VE
	1102/22/6	0002/1/1	vc	5	05	36,224.00	15 H16T MN	A 11 HT 21 WW	AV102KDAVE
	1102/22/6	0002/1/1	VC	5	081	00 191'52	15 151 E MN	T2 HT01 WM	MIDSKDYAE
89	1102/22/6	1/1/2003	Y C		σττ	00'111'9	NW 201H TER	A3THTCK WM	3VADASNDAVE
001	1102/22/6	0102/1/1	AC .		021	00.567,85	15 H152 MN	15 1512 MN	3VADANS01W
25	1102/22/6	0002/1/1	¥C.	\$	OEL	00 818'S	MW 27TH TER	15 H122 MN	3VADASNDAVE
58	1102/12/6	1/1/2005	AC	d	500	00'959'E	15 H199 MM 30 N 13 T91	12 HT35 WN	MIDSWDYAE
٤٢	1102/22/6	1/1/5000	, DA		0†I	00'S¥E'Z	15 H152 MM JO N 4 211	T2 HT25 WN	MIDSHDVAE
٤٢	1102/22/6	0007/1/1	עכ		051	00'651'5	15 H192 MN	12 H192 MN 10 S ¥ 852	MIDSHOWAE
70 92	1102/22/6	0007/1/1	¥C		091	00.558,2	12 HTTS: WA 27TH 159	15 H192 MM	MIDSHDVAE
28 96	1102/22/Б 1102/22/6	6661/1/1 2002/1/1	VC VC		01 052	00.110,1	191 M oʻ MW 381H 1EB 191 M oʻ MM 381H 1EB	NW 2011 151 NW 2011 168	MIDSMD61
E8 Z8	1102/12/6 1102/22/6	1002/1/1 6661/1/1	עכ איכ		30	00'815'52 00'269'92	15 1515 MN	T2 T215 WN T2 T215 WN	WIDHINAE WIDSHDDF
92	1102/12/6	1007/1/1	¥C ¥C		0T	00'200'11	AW 37TH TER	IS HISE WN	3VAHTROIN
12	1102/92/6	1/1/5007	VC		OE	00 122'9	bead End	T2 H185 WN	JVAHT MOLW
96	1102/62/6	1/1/5007	vc	\$	07	51'446'00	15 H19E MN	IS ONE WN	3VAHTPOIW
69	2102/01/2	16 61/1/1	,	\$	os	23'334 00	GN3 GA3G OT HTUDE	TE ONSE WH	JVAHTPOIW
76	1102/22/6	7/1/3 003	YC .	L	ot	00'928'61	T2 HT85 WN	15 H192 MN	TOHTHOTW
2 6	1102/52/6	1/1/5005	v c	s	10	15,582.00	IS OBEE MN	MW 3151 TER	BVAHT 201W
26	1102/22/6	7/1/1	vc		Œ	10 302 00	12 H182 MN	15 H122 MN	JAVHI SOTA
9 6	1102/22/6	2002/1/1	עכ		ož	00.888.8	15 HL/C MN	1\$H192 MN	3AVHLSOLA
001	1102/22/6	2661/1/1	70 70		<u>.</u>	00'262'61	15 H162 MN	15 H1/2 MN	JVAHTEOLW
001 89	1102/22/6	2661/1/1 2661/1/1	VC VC		1	00 185'02 00 282'61	T2 HT0E WN T2 DAEE WN	15 H162 MN 15 H162 MN	TAHTEOLW THEOLW
66 001	1102/22/6	\$002/1/1	¥C			00'EST'82	N1 H187 MN	NT CHEF AN	3VAHT001W
86	1102/82/6	\$002/1/1	74			00.628,8	IS HIDS MN	NT H187 MN	JVAHT COTW
96	1102/22/6	\$007/1/1	AC AC		001	00.£76,8	IS HILS MN IO N ¥ OZE	T2 HTT8 WN	JVAHTEOIW
£8	1102/52/6	5007/1/1	VC	5	01	00'282'28	15 H106 MN	12 H106 MN 10 2 U 189	3VAHTEOTW
86	1102/52/6	\$007/1/L	¢¢	\$	0E	19'050'00	NT 15E5 MM	15 HIOS MN.	JVAHT601W
86	1102/22/6	5002/1/1	۸C	s	07	00'952'8	NT OUES MN	NT 1515 MN	JVAHTeotw
94	1102/22/6	5002/1/L	γc			00'875'16	15 H185 MN	NI QUES MN	JVAHTeotw
001	1102/22/6	0102/1/1	AC			00.778,81	15 H162 MN	15 HLZZ MN	JVAHTEOJW
001	1102/22/6	0102/1/1	AC SC		1	00'982'1	15 H162 MM 30 S 13 S26	12 H165 WN	3VAHTE01W 3VAHTE01W
26 001	1102/E2/6 1102/22/6	1002/1/1 0102/1/1	AC AC		02T 06	13'901 00 11'590 00	NT DUED MN IS HIDE MN 30 S 13 SEE	15 1517 MN 	JVAHTEOLW
66 	1102/62/6	5002/1/1	,			00 816'6	15 H128 MN	15 H198 AVN	344476014
100	\$007/1/1	\$007/1/1				3'141 00	12 HT28 WN	NJ HTA8 WW	3VAHTEO/W
58	2102/01/2	\$002/1/1	• • • •		1	4'350 00	T2 CREB WN	T2 GNS8 WN	3VAHTEOIN
96	3/10/2013	\$002/1/1	, DA	5	0/1	00 87/'9	IS ONER MN	NJ HTOS WW	3VAHTEOIN
58	2102/01/2	\$002/1/1	vc	s	530	2'358 00	12 H198 MN	ABT HT26 WW	3VAHT COTW
58	2/10/2017	\$002/1/1	٧C			2,232.00	ABT HT28 WN	T2 HT25 WN	3VAHTEOJN
96	2102/01/2	\$002/1/1	AC		091	00 071'2	MJ HTOR WN	ISHLGC MN	3VAHTEOIN
58	2102/01/2	\$002/1/1	∀C		007	00'951'5	NJ HTAB WN T2 HTET WN	NW 28TH TER	BVAHTEOLV BVAHTEOLV
19 15	Z10Z/01/Z Z10Z/01/Z	5002/1/1 5002/1/1	AC		1	2°100'00 4°320 00	IS HIDE MN	WM 836D 21	3VAH1001
75	2102/01/21	5002/1/1	, VC			3'860.00	ABT HTAT WW	IS HIBL MN	3VAHTCOIN

96 69 04 59 59 64 89 86 26 89 86 26 89 59 2001 001 66 88 59	1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 1102/12/6 2102/01/2 2102/01/2	2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1	AC AC AC AC AC AC AC AC AC AC AC AC AC A	2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	022 01E 051 07 07 07 082 005 025 025 025 025 025	00 559'9 00 565'9 00 996'11 00 996'11 00 996'9 00 000'91 00 996'9 00 000'91 00 996'9 00 766'11 00 996'9 00 766'11 00 999'2 00 769'9	MW 4121 51 MW 4121 168 MW 2121 168 436 M 01 MW 63MD 168 436 M 01 M 01 M 01 M 010 M 0	WW 301H ST WW 201H ST WW 2751 TEV WW 321H ST WW 3	ATTOLIVINE DAVIALDILA ATTOLIVINE ATTOLIVINE ATTOLIVINE ATTOLIVINE ATTOLIVINE ATTOLIVINE ATTOLIVINE ATTOLIVINE ATTOLIVINE
69 02 59 62 89 62 89 86 26 26 26 28 59 001 001 001 66 59	1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6 1102/+2/6	2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1	AC AC AC AC AC AC AC AC AC AC AC AC AC A		01E 051 07 07 082 005 092 025 05 05 05 021	00 896'11 00 596'8 00 006'11 00 865'91 00 865'9 00 266'11 00 895'9 00 266'11 00 928'9	WW 3121 TER RW 301H 47 MW 75TH LW 4966 R N 01 KW 75TH LW 520 FT N 01 WW 62ND TER 720 FT N 01 WW 62ND TER 72 DFT N 01 KW 75ND TER 72 DFT N 02 WW 75ND TER 72 DFT N 02 WW 75ND 75ND 75ND 75ND 75ND 75ND 75ND 75ND	WW 50TH ST 50 FT 50 50 FT 5 OF WW 66TH 5T WW 62ND TER WW 62ND TER WW 60TH 5T WW 60TH 5T WW 60TH 5T WW 60TH 5T WW 60TH 5T WW 60TH 5T WW 5TH 5T WW 5T WW 5TH 5T WW 5TH 5T WW 5T ST WW 5T ST WW 5T ST WW 5T ST WW 5T ST WW 5T ST WW 5T ST WW 5T ST WW 5T ST ST WW 5T ST ST ST ST ST ST ST ST ST ST ST ST ST	IVAHTPELV VILTERV IVAHTPELV IVAHTPELV IVAHTPELV VILTERV VELTER
02 59 52 59 62 89 56 26 29 59 001 001 66 86 87 59	LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/DZ/7 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6 LIDZ/PZ/6	2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1	שב אב אב אב אב אב אב אב אב אב אב אב אב אב	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	051 07 071 082 005 092 026 05 05 021	00 592 8 00 264 11 00 895 9 00 895 9 00 895 9 00 895 9 00 895 9 00 995 9 00 9 00	430 1312 1515 436 M NOI MM 63MD 158 431 M NOI MM 63MD 158 432 M NOI MM 93MD 158 433 M NOI MM 93 434 M NOI M 93 434 M N	WW 50TH ST MW 517H AVE MW 52ND 12H AVE MW 52ND 1ER SOL FT 5 OF NW 66TH 5T	YAAHTAKE VIJATHAVE VIJAHTAVE VIJAHTAVE VIJAHTAVE VIJATHAVE VIJATHAVE
 \$9 \$9 62 89 86 26 89 26 89 26 89 2001 001 66 86 	1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6	2002/1/1 2661/1/1 2661/1/1 2661/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1	AC AC AC AC AC AC AC AC AC AC AC AC AC A	1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	07 07 520 520 520 520 520 50 50 50 50	00 0(9'1) 00 862'51 00 865'51 00 885'9 00 264'11 00 9291	430 111 01 MM 6310 168 436 M 40 M 41 M 6310 168 436 M 41 M 10 M 41 430 M 41 M 41 M 41 430 M 41 M 41 M 41 M 41 44 M 41 M 41 M 41 M	T2 HT02 WN 12 HT4 T2 HT4 12 HT45T WN 12 HT85T WN 12 HT	VAIATHAVE VIIATHAVE VIIATHAVE VIIATHAVE VIIATHAVE
\$9 62 99 86 86 86 86 89 59 001 001 66 86 86	1102/92/6 1102/92/6 1102/92/6 1102/92/6 1102/92/6 1102/92/6 1102/92/6 1102/92/6 1102/92/6 2102/01/1 2102/01/2 1102/92/6 2102/01/2	LEEL/1/1 LEEL/1/1 LEEL/1/1 ZOOZ/1/1 ZOOZ/1/1 ZOOZ/1/1 ZOOZ/1/1 LEEL/1/1 DIOZ/1/1 SOOZ/1/1 DIOZ/1/1 DIOZ/1/1	AC AC AC AC AC AC AC AC AC AC AC AC AC A	s s s 	001 092 005 092 026 05 021	00 629'91 00 885'9 00 895'9 00 995'91 00 995'91	A31 7212 WM 12 H102 WM MJ H127 WM MJ H177 WM MJ H177 WM 12 H187 WM IO M 369	T2 HTO2 WN 3VA HTA12 WN 72 HTA2 WN ML HT25 WN 12 HT86 WN	UTAHTARUE SVAHTARUE VAHTARUE VAHTARUE SVAHTARUE SVAHTARUE
62 99 86 86 26 89 59 001 001 66 86	1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 1102/72/6 2102/01/1 2102/01/2 1102/72/6 2102/01/2	L661/1/1 L661/1/1 Z002/1/1 Z002/1/1 Z002/1/1 Z002/1/1 L661/1/1 Olu2/1/1 S002/1/1 Olu2/1/1	AC AC AC AC AC AC AC AC AC AC AC AC AC A	s s s 	092 005 092 025 05 021	00 862'51 00 885'9 00 264'11 00 929'9	MN 3131 TER MN 7314 LM M1 7514 LM	T2 HTO2 WN 3VA HTA12 WN 72 HTA5 WN 12 HTA5 WM	JVAHTALLV JVAHTALLV JVAHTALLV JVAHTALLV JVAHTALLV
89 86 86 26 89 59 001 001 66 86 86	1102/b2/6 1102/b2/6 1102/b2/6 1102/b2/6 1102/b2/6 1102/b2/6 1102/b2/6 2102/01/1 5002/11/1 2102/01/2 1102/b2/6 2102/01/2	L661/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 5002/1/1 5002/1/1 0102/1/1	AC AC AC AC AC AC AC AC AC AC AC AC	s s 	005 092 026 05 021	00'895'91 00'895'9 00'895'9	NJ HIST WN IS HIOS WN HIST WN	12 H105 WN 3VA H14L1 WN 12 H14C WN	JVAHTALLA JVAHTALLA JVAHTALLA
£6 86 26 £9 001 001 66 \$6 \$6	1102/62/6 1102/62/6 1102/92/6 1102/92/6 1102/92/6 2102/01/1 5002/11/1 2102/01/2 1102/82/6 2102/01/2	2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 5002/1/1 0102/1/1	AC AC AC AC AC AC AC	s s 	092 026 05 021	00'928'9 00'262'11 00'885'9	ABT TZEZ WN F2 HTO2 WN	T2 HT02 WN 3VA HT411 WN	ATT4LHVALE
86 26 89 9001 001 66 86 86	1102/62/6 1102/92/6 1102/92/6 1102/92/6 2102/01/1 5002/11/1 2102/01/2 1102/82/6 2102/01/2	2002/1/1 2002/1/1 2002/1/1 2002/1/1 2002/1/1 5002/1/1 0102/1/1	₩C ₩C ₩C ₩C	s 	02E 05 021	00 928'81 00 262'11	WA 232 156 MM	T2 HT02 WN	34414114
26 89 9001 001 001 66 86	1102/+2/6 1102/+2/6 1102/+2/6 2102/01/1 5002/11/1 2102/01/2 1102/22/6 2102/01/2	2002/1/1 2002/1/1 2661/1/1 0102/1/1 5002/1/1 0102/1/1	∀C ∀C VC ¥C	s 	02E 05 021	00'928'81	WA 232 156 MM	T2 HT02 WN	34414114
89 59 001 001 001 66 86	1102/¥2/6 1102/¥2/6 2102/01/1 5002/1/1 2102/01/2 1102/22/6 2102/01/2	2002/1/1 2661/1/1 0102/1/1 5002/1/1 0102/1/1	AC AC AC	\$	05 0/1	<u> </u>	15 15() MN		
89 59 001 001 001 66 86	1102/¥2/6 1102/¥2/6 2102/01/1 5002/1/1 2102/01/2 1102/22/6 2102/01/2	2002/1/1 2661/1/1 0102/1/1 5002/1/1 0102/1/1	AC AC AC	9	0/1	<u> </u>		ISHI6E AN	144411114
\$9 001 001 001 66 \$6	1102/92/6 2102/01/1 5002/1/1 2102/01/2 1102/22/6 2102/01/2	2661/1/1 0102/1/1 5002/1/1 0102/1/1	עכ עכ עכ				15 H177 MN	WALCHER MN	JAVHINILA
001 001 001 66 \$6	2102/01/1 5002/1/1 2102/01/2 1102/22/6 2102/01/2	0102/1/1 5002/1/1 0102/1/1	VC VC			15'078'00	15 H182 MN	NT HILL MN	ALIATHAVE
001 001 66 \$6	5002/1/1 2102/01/2 1102/22/6 2102/01/2	5002/1/1 0102/1/1	- 7 C	2		00'162'1	811 0X58 WW	IS GN ZE MN	DSUHLETTA
001 66 86	2102/01/2 1102/22/6 2102/01/2	0102/1/1			÷ .	í l			
66 86	1102/22/6 2102/01/2					8'150 00	T2 HT87 WM	N1 H161 WN	WHIELLA
\$6	2102/01/2	0007/1/1	¢C			3'891 00	831 GN28 AW	T2 GN 58 WN	LOHIETTA
			∀C		01	52'382'00	831 H19E WW	15 H17£ WN	LOHIETTA
96		1002/1/1	AC			00.882,2	3YA HT87 WN	N31 H127 WH	JAVHLETTA
	2102/01/2	500Z/T/T	YC	S	i	00.088.2	15 H18¢ MN	NJ HT87 WN	10412114
	2102/01/2	5002/1/1	٧C	1	.c	00 879'5	N1 H18/ MN	NT H162 MM	MHISIT
001	2102/01/2	\$002/1/1	679	1	τ	00'205'5	AJT HTSS WM	T2 HT85 WW	16HLZLIA
\$6	1102/82/6	1661/1/1	AC	1	01	00'/95'88	LS ON 28 MM	AW 112TH AVE	TOHISLING
00I	1102/22/6	1/1/2010	AC	i	os	00'266'61	15 H162 MN	T2HT75 WM	ATTELHANE
16	1102/52/6	1/1/2005	SA	1	340	00'661'61	IS HIDS MN	A3T HT84 WN	IVANTSTUAVE
56	1102/62/6	2002/1/1	YC	1	530	00'\$68'61	15 GNZS MN	T2 HT02 WM	JAVHIZITA
96	1102/62/6	2002/1/1	VC	•	09t	00'566'61	NJ H134 WN	NI CHEP MN	ATTSTHAVE
86	1102/62/6	2002/1/1	YC	1	ost	00 076'9	N1 GHEP MM	NN 93KD FM	JVAHTSTUA
00T	1102/22/6	0102/1/1	YC 2	5	560	00'519'12	15 GREE WH	15 HLOE MN	3VAHTS11V
и	1102/22/6	0102/1/1	VC		012	00'TSL'6	15 H19E MN	T2 CAREE WW	IVANTSTRAVE
001	1102/22/6	1/1/2010	DA.		OE	00.138,01	15 H1/2 MH	15 H152 MN	ATTSTHAVE
	1102/22/6	2002/1/1	- 74		011	52'020'00	NT CHIZE MAN	15 15tp MN	ATTSTHAT
96	1102/62/6	2002/1/1	VC VC		50	00'685'19	15 H185 MN	NT CHES MN	3VAHTSIIV
	1102/22/6								
		0102/1/1	AC 2A		OST	00'\$1\$'\$1	12 HTOE WM	12H195 WN	374415114
66	1102/62/6	2002/1/1	AC AC		05	11,184 00	AW 481H 16A	MN 461H FM	3VAHTSIN
	1102/62/6	1/1/5002	AC			00 091'S	AW 11511 AV	15 QN 28 MN	JVANTELL
	1102/12/6	1/1/2005	AC		130	00'986'21	N1 OVES MN	T2 ON \$2 WN	3VAHTSTUAVE
	1102/12/6	\$002/1/1	AC		100	00'005'5	NTHISZ MN		3VAHTSIIV
100	1102/12/21	1102/11/21	AC	1	09	00'501/E1	15 ON 85 MN	NT HLOS ANN	3VAHTSIIV
\$6	1102/12/6	5002/1/1	AC		OET	00'612'8	NJ HTOS WN	NI HTET WH	3VAHTSITV
24	1102/12/6	\$002/1/1	AC	1	510	00.108,8	N1H164 MM	NT HLSZ MN	JAVHIEL
100	1102/62/6	\$002/1/1	24.		041	00 559 11	15 H199 AAN	T2 H148 AV	JAYHIZTU
001	1102/62/6	\$00Z/T/T	AC		500	00'\$12'6	15 H128 MN	15 H198 MM	3VAHTSTIN
28	1102/62/6	500Z/T/T	, AC		09	00'186'2	A31 HTTT WM	NT H152 MW	JVAHTSIII
t 6	1102/62/6	5007/1/1	VC		07	00'171'5	HISE MN	KW 74TH TER	JAYHLEIL
t 6	1102/62/6	5002/1/1	, AC	•	οι	00'720'6	831 H142 MN	IS HIPE MN	IVANTSIN
	1102/62/6	\$007/1/1	AC		sosz	2'145'00	3VA HTSEE WW IO WN A 885		JVAHTSII/
	1102/12/6	\$00Z/T/T	YC		081	00'018'2	15 HIVS MN		INVHICTL
	1102/12/6	5002/1/1	- VC		140	00'111'0	NT H182 MN	· · · · · · · · · · · · · · · · · · ·	JAVHIZIL
82	1102/12/6	5002/1/1	AC		. OZ	00'ESO'S	15 H182 MN		JVAHTSEE
	1102/82/6	5002/1/1	AC .		380	00'696'52	15 H106 MN		JVAHTSIT
	2102/01/2		l .		1		N1 H184 AN		THITHCT
	1	5002/1/1	. VC		5	2,320.00			
96 86	2107/01/2	\$00Z/1/1	AC		E	00.014'S	MJ HTeT WN		1241111
	2102/01/2	\$002/1/1	AC		•	4,820.00	NJ HTO& WW		1341111
001	5007/1/1	\$00Z/T/T	AC		is	00 098 6	12 H138 WN		LOHITT
	5/10/2015	\$002/1/1	VC		i	00'000'S	831 H182 WN		12H1111
100	2102/01/2	\$007/1/1	אכ י		T	10,000	12 H198 MN		JAHTOIT
00T	2102/01/2	T/T/5002	, AC		30	00'098'11	12 H198 MN	T2 HT48 WN	3VAHTOIL
58	1102/22/6	1/1/2005	שכ		ot	00'6ES'P	Dead End	T2 HT22 WM	3VAHTOLL
	ગઠવ	əfeQ	• • • • • • • •	••	!	•	····		
ы	uoppodsuj	Construction	SURFACE	Section Rank	Section ID	(72) A39A	٥T	רוסש	3MAN T338T

56 96 06 16	1102/22/6 1102/22/5	1661/1/1 1661/1/1	AC AC		30 10	00 968'65	JVA GNSOI WN JVA HTTOI WN	JVA ONSOL WN	T2HTEIWN
06 16	1	1001/1/1	J¥.						
16					1	1	1	T2HTT2 WH	TZHTELWN
	3\55\5011	2661/1/1	YC		50	00 926'91	NW 881H CT	3VA HTT8 WN	AJTHT&IWN
	1102/22/6	2661/1/I	AC	1	ot	00'619'19	1d H168 MN	NW 88TH CT	AJTHTSIWN
68	1102/22/6	\$661/1/1	24	s	30	00 751 77	3VA HTTB WU	3VA HTA8 WN	1SH171WN
05	1102/#2/6	\$661/1/1	AC	s	07	53'456.00	3VA (INS8 WN 10 W A E87	AW B2ND AVE	15H12TMN
00 T	2661/1/1	1661/1/1	, DA	5	30	00'272'61	IN ABLH CL	3VA HTTE WW	ISHLLIMN
26	1102/22/6	1001/1/1		s	01	58'581'00	IS HIGT AVA	10 H186 MM	ISHLETAN
100	1102/22/6	2661/1/1	AC	5	10	00 920'61	WM 103HD VAL	TWW TOOL WW	AJIHTZEWN
P6	1102/22/6	6661/1/1	AC	1	00	16,093.00	NW 89TH CT	3VA HT88 WN	TZHTZZWN
92	1102/22/6	6661/1/1	VC	1	0£	00 #25'91	3VA HTES WM	3VA HTT8 WM	15H1SEMN
89	1102/72/6	2661/1/1	AC		ot	15'0160	3VA HTET WN	3VA HTAT WH	TZHTZZWN
58	1102/92/6	2661/1/1	νc		07	00'252'22	pu3 baed		
66	1102/22/6	2661/1/1				1		JVA GNSB WM	12H19TWN
			¥C.		01	00 999'26	WA 1001H AVE	WM 381HC1	12H14EWN
58	1102/92/6	2661/1/1	AC		30	00'END'97	3VA GHSS WH	3VA HTET WH	T2HTATWN
92	1102/22/6	1/1/2005	AC	1	50	22,513,00	3VA HTES WH	3VA HTTS WW	RETHTERWN
92	1102/22/6	1/1/2003	2AC	1	OE	00 116'51	12 H168 WN	3VA HTBS WN	ATHTERW
68	1102/22/6	7/1/2003	AC .	1	01	00'251'9	Desd End	ID HIES MN	ATHTERWN
001	1102/22/6	1/1/2010	AC	1	01	00'511'5	3VA HTTE WN 10 3 T1 EE1	3VA HTTE WN	ISHIELMN
00 t	1102/22/6	1/1/2010	24	1	50	00'9E¥'01	3VA HTTE WH TO 3 TO 14 LA2	3VA HTTE WM 3O 3 73 561	ISHIELMN
100	1102/22/6	1/1/2010	, AC	· 1	·07	15,731.00	ID OBEG MN	134 EL M OL 3360 CL	1SHIETAN
300	1102/22/6	0102/1/1	VC		05	10 019 61	13411 M OI 6380 CL	3VA HTTE WM 3D 3 T3 142	1SHLETAN
69	2102/01/2	\$661/1/1	VC		05	00'010'12	15 HLDE MN	T2HT25 WM	3AVHLLLTAN
-112	1102/12/6	0002/1/1	VC			00'560'51	3VA HTYLE WA	IS HIDS MN	BATHLETIAN
					30				
£9	1102/12/6	1/1/5000)A		50	00.481,85	12 HT82 WN 90 2 T9 608 ,L	15 H185 MN	JAVHILLIMN
100	1102/22/6	1/1/5000	AC		10	00.625,74	15 H105 MN	9MAA 3Y9T AQISO11	3VAHTTITWN
E 9	1102/22/6	0002/1/1	AC	s	07	24,521,00	bead End	T2 HT4E WW	JVAHTTIWN
00 T	5/10/3015	0102/1/1	AC	s	1	12'945 00	AM GHES MN	15 GNZ9 MN	3VAHTATIWN
001	2102/01/2	0102/1/1	AC	\$	ι.	00"PE2'E	ABT HTAS WN	T2 HT48 WW	THISTIMN
00 T	2/10/301/2	0102/1/1	24	5	2	15'69'00	10 N OL NM 861H 21	ANY 84TH TER	THISTIMN
001	5/10/3015	1/1/5070	2A	s	t	00'E9E'E	A 31 ONSS WH	15 ON29 MN	LOHLSTIMN
001	5/10/3015	1/1/2010		Ś	2	10'023'00	YAW GRES WN	NW 83ND TER	LOHISTIMN
001	2102/01/2	0102/1/1	VC		£	00.016,1	15 H198 MN	YAW GREB WM	10H1STIMN
00 t	2102/01/2	0102/1/1	VC			5'413'00	A11 H148 WW	12 H198 MN	LOHISTIAN
oot	2102/01/2	1/1/2010				00 111'S		NW SATH TER	LOHISTIAN
	1		24		1		15 H198 MN		
001	1102/11/21	1102/15/71	¥C.		08	00'205'61	15 1510 MN	ISH16E MN	3VANT 2LIWN
001	1102/11/21	1102/12/21	AC		01	25,655.00	15 H16E MN	T2 HTPE WN	3AVH1STIMN
100	2102/01/2	0102/1/1	AC	s	Z	00'TLL'E	YAW GAES WN 10 HTUO2 '001	AJT ONS& WN	TAAHTELIWN
100	5/10/3015	1/1/5010	AC	5	t T	00'597'E	A31 DNS8 WN	TZ QNSS WN	TAGHTALIWN
001	2102/01/2	0102/1/1	VC	5	OPE	00'262'91	T2 HT68 WW	T2 HT09 WM	344HIPTIMN
001	1102/12/6	1/1/2010	74	······ s	330	00 000 09	15 GN 29 MM	15 ON 28 MN 10 MS U EPS	JAVHLETIMN
001	2102/01/2	0102/1/1	AC	s	OSE	00'898'9	N1 HLLS MN 10 HLDOS 200	15 H188 MN	JAVHLETIMN
01	1102/12/6	2002/1/1	AC.		150	00 855'51	A 31 CAET WA	15 ONZL MN	JAYHLIPTIMN
001	1102/92/6	2002/1/1	 vc		09	00 895'61	HAN 431 DIE	12 1215 WN	JAVHLIPTIAN
65	1102/02/6	2002/1/1	∀C		00	00'891'0	15 H192 MN	MW 7380 TER	JVAHTAIIWN
					1	1			
86	1102/22/6	2002/1/1	AC		08	00'\$96'2	366 FT N OF NW 48TH TER	NW 48TH TER	3VAHTALLWN
001	1102/92/6	1/1/2005	AC AC		OET	00'\$/8'11	15 H185 MM 10 N 13 095	T2 HT82 WM	BVAHTALLWN
86	1102/12/6	2002/1/1	AC		05	00'65E'52	831 H19E MN	15 HIVE MN	BANHITIAN
16	1102/12/6	7/1/5005	24	5	500	00'216'51	A31 H184 WM	T2 HTTA WN	3VAHTATEWN
59	1102/72/6	2002/1/1	AC AC	5	90	8'939'00	T2 HT03 WM 4D 2 T3 804	12 H103 WN	3VAHTAITWN
28	1102/02/6	1/1/5005	۶C	5	091	11,210.00	15 H199 MW 40 5 14 T05	15 H199 MN	JVAHTAILWN
\$9	1102/92/6	1/1/3005	AC	s	540	00'269'9	8 3L H129 MN	12 H199 MN	IVAHTATEWN
19	1102/92/6	7/1/5005	24		530	11'205'00	831 H169 MN	A 3T HT83 WN	JVAHTAILWU
£9	1102/92/6	7/1/5005	۷C		012	00 228 21	15 GNZZ MN	A3T HT63 WH	IVANTALLWU
86	1102/62/6	7/1/1	¥C V		051	19,282,00	15 HL(7 MN	12 H144 WN	3VAHTATEWN
					1	1	15 HL25 MM	15H155 AV	JAVHLDILMN
100	1102/22/6	1/1/2005	AC		052	00 918 81			
96	1102/92/6	2002/1/1	AC		091	15,435.00	15 H185 MN	IS HILLS MA	JVAHTALLWN
001	1/1/5002	1/1/5005	24	5	550	5,851,00	811 H189 MN	831 H178 WM	3VAHTELLWN
88	1107/17/6	7/1/2005	. אכ	S	001	00.606,8	15 HLSS MN	T2 HT22 WN 10 2 A 765	3VAHTATIWN
PCI	Last Inspection Date	Last Construction Date	3 ว Aากบร	Section Rank	Ol noittea	(72) AJRA	01	moił	JMAN TJJRTZ

10	1107/27/2	****				0077077			
	1102/22/6	\$661/1/1	 			59'059'00	JAM B2KD KAE	3VA HTET WW	15151
	ZTOZ/T/L ZTOZ/T/L	2102/1/L 2102/1/L	AC 2A		1	15'022'00	JVA HT28 WM	3VA HTHE WH	A31H10
			•		÷	11,664.00	3VA HTTA WN	3VA HT28 WM	A3THTC:
	2102/1/2	2102/1/2)A			00'502'01	3VA HTA8 WN	3VA GNG AV	A11H10
	1102/22/6	2661/1/1	VC		1	00'925'9E	3VA HTSLI WM	3VA HTEOT WW	12010
	1102/22/6	1661/1/1	VC V		1	36,603.00	3VA HTEOT WW	3VA HTBOT WW	12H10
	1102/22/6	6661/1/1	YC.	1	i	11,267.00	3VA HTET WN	JVA HTBY WN	12H16
	1102/22/6	6661/1/1)A	1	05	00 986'81	3VA HT85 WN	T2HT47 WM	120116
Z6	1102/72/6	6661/1/1	YC	٩	08	00'211'6E	3VA HTT8 WN	3VA HTA8 WN	T2HT2
<u> 8</u> 3	1102/22/6	6661/1/1	VC	1	09	51'053'00	JVA HISEL WN	3VA HTOLE WH	12H16
S 6	1102/22/6	6661/1/1	YC S	1	L 09	00.516,51	3VA HTOLL WN	3VA HTEOL WN	12H16
16	1102/22/6	6661/1/1	γc γ	i	los	58'035'00	3VA HTEOL WW	JVA HTEOF WN	15H16
и	1102/22/6	6661/1/1	AC	1	507	39,410.00	3VA GNS8 WN	JVA HTET WN	T2HIE
700	1102/22/6	0102/1/1	. ⊃¥	1	07	00'909'ET	AW 102ND AV	3VA HTOOL WA	A3THT8
100	1102/22/6	1/1/2010			502	00'522'E1	3VA HT001 WN	JVA HTEE WN	831HTER
100	1102/22/6	1/1/2010			ot	00'606'21	AWA HT86 WM	3VA HTTE WM	AJTHT8
	1102/22/6	0102/1/1	VC		OE	13,132.00	3VA HTEE WN	JVA HTAR WN	AJHTA
	1102/22/6	2002/1/1	• · · ·						
			¥C		01	00'875'ET	3VA HT2OL WN	INN TOTLE CL	15H18
	1102/22/6	0107/1/1	AC		6 012	15'865'00	3VA HT89 WN	JVA HTTE WW	AJTHTT
	1102/22/6	0102/1/1	AC .		5 OE	00'521'E1	3VA HTee WN	3VA HT89 WM	AJTHTT
	1102/22/6	1/1/5010	¥C V		6 01	00'885'51	3VA DOZNO AVE	3VA HTOOI WM	A31HTT
	1107/22/6	1/1/5010	VC	1	502	13'522'00	3VA HTOOI WN	3VA HTCC WW	RJTHTT
	1102/22/6	71/1/2005	VC	1	5 05	13,027.00	3VA HTOOL WN	3VA HTEE WN	12417
οt	1102/22/6	0102/1/1	אכ "	1	502	15'155'00	JVA HTSE WN	3VA HTTE WN	12H11
01	1102/22/6	0102/1/1	אכ	i i	06	29,244.00	3VA HTEOL WN	JVA HTEOT WH	12H11
01	1102/22/6	2661/1/1	VC	L	L 00T	00'169'51	3VA HTEOL WW	3VA HTTOE WN	12417
ot	1102/22/6	2661/1/1	AC	•	5 01 1	00'215'82	3VA HTTOT WN	BVA HT201 WM	12417
8	1102/22/6	1/1/2010	vc	•	803	00'#24'ET	3VA HT69 WN	JVA HT89 WW	12411
6	1102/22/6	1661/1/1	AC AC			00'211'96	3VA H1211 WW	JVA HTEOT WH	ISHL
	Z10Z/L/1	2102/2/1	VC		:	00 011 05	3VA HTAR WN	IN BIND AVE	12H11
	2102/1/2	2102/1/2			4	31'354'00	T2 HT68 WN	13 H1(8 MN	19414
	2102/1/2	2102/1/2			1		L) HIZE MN	JAN HILS MA	İşill
			. vc		5 02	00 ESS'LL			
	2102/1/2	2102/1/2	24		5 09	00 012'EE	3VA HTT8 WM	3VA HTAS WW	15417
	1102/22/6	1/1/2005	AC		130 2	15,988.00	AW 103KD AVE	3VA HTOOL WM	19414
16	1102/22/6	1/1/3005	AC	L	iot	00'912'EL	3VA HTROE WH	NW 1011H CI	19419
98	1102/22/6	1/1/2005	AC	9	soz	00'SE6'0E	T) HT(8 WN	T2 HT4 WH	12H1
x i	1102/22/6	2002/1/1	עכ יאכ		sios	00115'51	3VA HTEE WN	3VA HTBE WW	12411
8	1102/22/6	1/1/5005	V C	,	5,01	00'9E0'EI	3VA HTOOT WN	3VA HTEE WM	12415
18	1107/22/6	1/1/5005	. אכ	9	302	00'896'21	IN JOSHD AVE	3VA HTOOL WH	12011
ж	1107/27/6	1/1/2005	VC	9	soz	00'015'11	3VA HTEE WN	3VA HTBE WH	BIHIER
19	1102/22/6	2002/1/1	. AC		sot	00'219'9	1001 MAN 1001 MAN	JVA HTRE WH	831111
	1102/22/6	2661/1/1	VC		LOT	00'625'12	14 H169 MN	15 H152 MN	RETHTER
	1102/22/6	2661/1/1	VC		5 02	35'709.00	3VA H188 WN	JVA HTAS WN	15081
	1102/22/6	2661/1/1	vc vc			39'255'00	14 H168 MN	NW 881H CI	1508
			1						1109
	,2102/1/L	2102/1/1)A		501	30'036'00	NW 881H CL	JVA HITS WN	
	1102/22/6	2661/1/1	AC		sot	00.185,0	JVA HTTB WN	3VA HTƏB WM	A3112
	1102/92/6	2661/1/1	AC		SOE	50'321'00	15 1512 MN	JVA HTET WH	1212
	1102/\$2/6	2661/1/1	AC		SOII	53'054'00	besû	INN OSKD VAE	1515
8	1102/22/6	2661/1/1	vc		502	00'852'11	12 7215 WW	12 1215 WH 10 3 4 566	1212
10	1102/22/6	2661/1/1	VC	•	S 09	00 ⁻ 260 ⁻ ET	12 1225 WM to W A 364	15 ISTZ MN	1515
8	1102/22/6	2661/1/1	vc	•	S 01	16,212,00	IM DISIO MI	3VA OVSOI WI	1515
6	1102/22/6	2661/1/1	vc	•	5 09	00'926'20	12 1215 WH	14 GNZOL MA	1512
8	1102/22/6	2661/1/1	AC		5 02	00 711'S	15 1512 MN	15 1575 MB	1515
8	1102/22/6	2661/1/1	۷C		1021	00'850'6	3VA HTTOI WH	12 1215 WH	1515
	1102/22/6	2661/1/1	۶C		1 001	2'555'00	15 15TZ MN	12 1215 WH	1515
	1102/22/6	2661/1/1			\$ 06	00 891'52	JAN JOZNO VAN	15 15TZ MN	1212
	1102/22/6				s 09		15 151 MM	JVA HTEE WH	1212
		2661/1/1	¥C .		1	13'69'10		15 151Z AW	1515
	1102/92/6	2661/1/1			5 05	56,259.00	NW 63ND AVE		
02	1107/77/6	1661/1/1	VC		1,01 	00 122'92	19 HT 68 WM	WM 881H CI	12410
	noitoeqtion Date	Construction Date	SURFACE	Section Rank		1	01	moni	BMAN TBB
Ъđ									

3VA HT201 WM 3VA HT401 WM		3VA HTCOT WN 31		1 	3VA HTTOI WW				s'ot	• • • • • • •			ə 160	0001	ated	
1		The second second second			1						77					EG i
	TUATH AVE			4	TVA HIZOT WN		19'924'00 20'925'02		d 001		vc vc	-	2/1/1		1102/12/6 1102/12/6	1
HT HT BE WH		1352 V M QI NM 381H CL		i i		1941	00.765,65	ł	4 091		AC		2/1/1		1102/22/6	
	3VA 2011KOS AVE		_	1			18,218.00		4 021		AC		2/1/1		1102/22/6	
3VA HTEOL WN				1			00'910'ZE		SOET)AC		2/1/1		1102/22/6	1
3VA HTCOI WH				1			00'650'st		s ozi		¥C	İ	e/1/1		1102/22/6	6
JVA HTEOL WH		1		1	1		56,265.00		\$ 071)A	1	2/1/1		1102/22/6	56
BVA GHEB WR	3VA QNS8 WR	3VA QN 58 WA 10 W A 229			3VA GN 58 WH 10 W A 228	DAVE	00'8t 5' 9t	c	\$ 02	/ S)A		2/1/1	1002	1102/92/6	99
MN 10 3 4 669	3VA HTTR WW 10 3 A EE	3VA HTT8 WN 3VA HTT8 V		ł.	3VA HTT8 WN		00'216'EL	c	S 09	/ s	SA C		z/1/1	1001	0\5 4 \5077	8
10 1243 11 503	IVA 20HLICMIRIOT 10 T2A3 T1 702	TORREMOLINOS AVE	'S	υ	NIJOM3RROT 10 T2A3 T1 M4	BAN SONITOWER	00'611'01		ajosi		۶¢	:	<i>e/1/1</i>		1102/22/6	
	TAN SOULOW BUILD		-	1			20'281'12		101		יעכ	•	enn		1102/22/6	
3VA HTET WA		i		i	i		40 [°] 039 [°] 00		5 011		vc	•	enn		1102/92/6	
JVA TZZE WW				1		1	0 F98'8		5.07		AC		2/1/1		1102/92/6	-
TO HTER WW IVA BATH AVE		3VA TZZE WN 3VA HTA8 WN Io W A 248		1		374 H	0.978 1 ,91 0.958,81		5 OE		AC		enn enn	1002/ 0102/	1102/72/6 1102/72/6	5
JVA HITE WW		· · · · · · · · · · · · · · · · · · ·	_	ļ <u>_</u>			58'462'00		6.08		¥C تيد	-		2002	1102/22/6	
	3VA HTP8 WM to 3 A 252		_	1			15'941'00		\$ 06		AC			1007	1102/92/6	
3VA HTT8 WW		· · · · · · · · · · · · · · · · · · ·		1			0'211'16		\$ 05		YC			0102/	1102/92/6	
3VA HT201 WW			_				0'852'61	1	a 091		AC		₹/1/ 1		1102/22/6	
JVA HTTE WN	IVA HTTE WW	3VA 1212 WN 10 123W 'EOD	•	1	3VA 1216 WN 3D 123W '609	3VA 121	144'999 00	t a	5 061	i s	∀C	1	Z/0E/E	1102	2102/01/2	01
	JVA HTZIT WH		-	1		ł	12'351'00		sot	•	24		2/91/1		1/16/5015	01
	IVA HTATI WW			1			00.688,65		502		2A 2A	4	2/91/1		2102/91/1	
IDHIELL WW	WW 113TH AVE		_	L			0'510'12 0'529'51		5 07 5 0E		AC	ł	2/91/1 2/91/1		2102/91/1	
JAM BILL MA						j	41,860.00		sot		אכ	+	Z/T/T Z/91/T	(3003 1007	1102/\$2/6 2102/91/1	
1	AW 104TH AVE			1			X) 85E'6E		S OL		AC			1007/	1107/52/6	
T2HTEIT WM	T2 H1811 WW			1	1	1	0.010,01	C	sjot	/ S	AC	1	2/1/1	15000	1102/22/6	
ID HILL MN	T2HITT WW	3VA H185 WW		• !	3VA H185 WW	1	x7265'S		\$ 02	i ŝ	, AC	-+	2/1/1	2002	1102/92/6	s i
3VA HTBY WN							13'500 00		S OL		vc			z002/	1102/92/6	
	CH 133912 H109 MM			i		ŧ	20 829'02		5 02		vc	1		2002/	1102/92/6	
JVA HTET WM				1		ļ	0 P20 82		SOL		AC			z002/	1102/92/6	1
	WW \$151H AVE WW \$01H 518EET RD						00.140,85 00.140,85		5.02 5.1		AC AC		2/1/1 2/16/21	2002/ 2002/	1102/92/6 2102/01/2	-
15 H18E MN		201 133812 HOA WH				C C	0°22E'St		5 01		AC			(5005 1005	1102/72/6	1
JVA HTET WN				1			51'825'00		5 02)AC			2002/	1102/22/6	
AVA TZIB WW	3VA TZIB WW	3VA QNS8 WN	Ì		3VA QNS8 WN		0'872'2	0	s ot	i s	AC		2/1/1	2002	1102/62/6	r I
3VA ON 28 WM	3VA ONSE WW	15 1510 MN 3			15 15TÞ MN	Ì	0.020,55,55	o	s 08	/ s	AC		2/1/1	2002/	1102/52/6	17
12 1214 WN	12 1214 MN	JVA HTT8 WN			3VA HTT8 WN		53'840'0	o	\$ 07	i s	VC		2/1/1	2002	1102/62/6	9
1	3VA H1211 WW			L .			56,440.00		söt), AC	•		2002/	1102/62/6	8
IDHINT MN							17,480.00	1	5 02		עכ	•		2002/	1102/62/6	
	3VA HTALL WN 3VA HTALL WN	· · · · · · · · · · · · · · · · · · ·		.		-	0'922'S		5 02		, AC	÷		2002	1102/22/6	
	3VA HTEOL WW 3VA HTEOL WW To 3 A 8151		-	•			00026'12 00162'62		5.09 5.017		vc vc			/661/ 2002/	1102/E2/6 1102/E2/6	
•	JAM HILL ANN AN TO THE ANN		_	i			56,988 00		SOE		שר	-• -		15005	1102/52/6	
IDHISTI MN			_				0 109'51		\$ 05		VC			2002/	1102/22/6	
3VA HTAOT WW	3VA HTAOT WN	15 NW 104TH CT			TO HTHOT WH		X)'S72'12	o	30 b	/d	AC	•	1/1/1	6661/	1102/22/6	
JVA HTTE WN	3VA HTTE WN	3va HTee ww		• · ·-	JVA HTEE WN	t	24,122.00	z	d 012	i di	7	•	1/1/1	6661/	1102/22/6	8
NW TOSKO LT						•	18'636'0	1	a 022		., AC	1	i/1/1	6661/	1102/82/6	16
1	IVA DISKO AVE						0'2E0'21		1 091			÷		6661/	1102/62/6	- 1
TZ ONSZ WW 3VA HTEE WM							0.01.11		d 06		AC AC	÷		6651/	1102/62/6	1
1	3VA 106TH AVE						0.844.01	1	4 021 4 002		¥C HC	Į.		6661/ 6661/	1102/EZ/6 1102/EZ/6	
TO HTAOL WW							0.588,6	1	4 091		AC			666t <i>/</i>	1102/52/6	
NW 104TH CT	TO HIAOT WW	ID HISOI MN			TO HI SOI WN		0'668'51		1011		AC	1		6661/	1102/22/6	
3VA HTBY WN	3VA HTBY WN	JVA HTES WN			3VA HTET WN	ţ	13'437'0	к ¦о	s'ost	i s')AC	İ	1/1/1	666T/	1102/52/6	2
3VA HT48 WM		3VA HT48 Wit to W A 251			374 HT48 WH 10 W A 251	3VA H	0.681,6		5.07		vc	ł		6661/	1102/52/6	6
TO HITTE WM		NW 1184 WM		1	1	1	0'E52'01		5 02		24			\$66T/	1102/22/6	
3VA HTA8 WM	3VA HTTE OF NW STH AVE			i i			5,740.00	1	5 05 5 0E		AC			6661/ 6661/	1 102/12/6 1 102/12/6	

374416799	IS HISE WH	15 H16E MN	55'281 00	1022		AC	1/1/2010	1102/12/6	96
3VAHTERWY	15 H149 MN	T2 HT84 WH	00'201'11	061)AC	0102/1/1	1102/12/6	66
3774166747	T2 HT84 WA	12 H184 WN	5'330'00	1,00Z		vc	0102/1/1	1102/12/6	00 T
3444166444	ISHIPE MU	IS HIVE MN ION IJ ZZE	18'015'00	5701			0102/1/1	1102/12/6	00 T
374416644	15 HIGE WW	12 121 MM	00'949'81	1092		AC	0102/1/1	1102/12/6	00 t
12418(44)	BVA HITOT WH	JVA HTEOL WW	00'006'92	T		٧C	5002/1/1	2102/01/2	56
1504186.000	THETT MU	THE MAN	00 920'9			vc	5002/1/1	2102/01/2	56
15418//	JAN HIELT MA	M HIETT WN	00'759'8	59		, AC	\$00Z/T/T	2102/01/2	\$6
12H187WY	14H1511 MM	JVA HTELE WW	00 611'2	s		, vc	5002/1/1	2102/01/2	\$6
12H185WW	3VA HTST1 WH	WA 11211 AW	00.038/5	5 7		. DA	\$007/1/L	2102/01/2	\$6
12418744	INM 1111HCL	IVA HTSIL WM	00 128'9	1		YC	\$002/1/1	2102/01/2	\$6
15H18LMA	JVA HTEOL WA	WW TITH CL	55,000.00	1			5007/1/L	2102/01/2	\$6
NJHTSTWN	10 H1211 MN	AW HISIT WW	00'985'5	1		24	5002/1/1	2102/01/2	96
NUHTBYWN	IN TITLE AN	ID HITTE WW	00'281'9			٣C	\$00Z/T/T	2102/01/2	96
3AVH18LAVA	15 ONES MH	LS OVES ANN	00 209'9			DA.	1002/1/1	1102/12/6	86
3VAH18CWH	15 H195 MH	T2 HT22 WW	001111			VC VC	1002/1/1	1102/12/6	68
3VAHTBY W	15 HISS MN	15 H195 MN	00.001,7	ot		VC	1002/1/1	1102/62/6	18
3VAHTERWAN	15 H195 MH	15 H125 MH	00.509,7	1		¥C	1002/1/1	1102/12/6	001
3AVH18LMN	15 H127 MH	15 HISE MN	00 565'65	1		24	E002/1/1	1102/02/6	89
BIHLLOW	IN TITH AVE	MW 1121H PLACE	00 099'9				5002/1/1	2102/01/2	96
831H177W	100 11211 MA	LO HITTE MA	00 098'S			PC PC	5002/1/1	2102/01/2	96
831H177WM	EW 113TH PLACE	WW 1131H AVE	00 020'9			vc 1	5002/1/1	2102/01/2	96
LOHILLAN	15 H155 MM	15 H195 MN	00'856'9	1		AC 24	1/1/2001	1102/12/6	52
10H111AM	15 H1 PS MA	15HLSS MN	00'116'9	5 OE		90 VC	1002/1/1	1102/12/6	99
10HILLAW	15 H162 M2	LS ON ZE MIN	00'261'61	5,05			1/1/2003	1102/22/6	u
LOHLLOW	15 ON 25 M21	15 OVES MN	00.959,00				\$661/1/1	1102/12/6	19
10H111AM	15 GHES MA	15 H195 MN	00'917'9			VC VC	5661/1/1	1102/12/6	79
15H199MN	3VA HITOL WH IO 3 A 487	JVA HITOE WN	00'9EE'81	1		vc ∀C	2002/1/1	7002/1/1	001
1SH199/WN	3VA HTTE W1	3VA HTSOL WH IO W II SEES	00'968'65			90 VC	2002/1/1	1102/22/6	£6
15H125MN	puj prog	JVA HTØT WH	00'851'5	50C		VC VC	9002/1/1	1102/12/6	001
15H125MN	3VA HT87 WN	JVA HTET WH	00'E08'#1	oz		AC 24	2002/1/1	1102/12/6	001
15H195MN	TO HITE WH	IVA HTRY WN	00'210'11	5.05		AC	2661/1/1	1102/12/6	\$6
1SH19SMN	JVA HTBY WH	JVA HTET WH	00'8E9'81			AC AC	2661/1/1	1102/12/6	58
15419500	3VA HTET WN	JVA ONSE WH	58'875'00	soz		90 VC	2661/1/1	1102/12/6	¥L
15H195MM	JVA ONSE WM	3VA H148 WH	59,212,00	ot		AC AC	2661/1/1	1102/12/6	18
15H195MM	3VA HTAR WW	IVA HITE WH	59,143.00	5 OE		AC AC	2661/1/1	1102/12/6	19
15H155AW	JVA HTØT WM	IVA HTEC WW	13'344'00	5 OE		AC AC	2661/1/1	1102/12/6	68
ISHISSAN	10 H1// MN	3VA HT05 WM	00 992 21	ot		. AC	2661/1/1	1102/12/6	06
1SH115SWN	BVA HTBY WW	JVA HTET WH	00'555'51	502		AC AC	2661/1/1	1102/12/6	06
ISHIPSAN	3VA HTPC WM	IVA GNES WW	56,276,00	5 OS		AC A	2661/1/1	1102/12/6	ζL
1SH1PS/W	INN 83KD VAL	JVA HTAS WH	00'567'92	5 OT		AC	2661/1/1	1102/12/6	85
1SH1PSMA	INN BATH AVE	IVA HITE WW	00'626'92	5.09		AC	2661/1/1	1102/12/6	•1 19
1SH1PSMA	TO HITT WH	JVA HTOT WW	00'112'50				2661/1/1	1102/12/6	88
8310AE2WW	JVA HTAB WM	IVA HTT8 WM	00'609'92	5 OE 5 OT	_ .	VC VC	1661/1/1	1102/12/6	
19095544						AC		:	1.W 98
	3VA HITS WH IN 3 A CCS	3VA HTAS 10 W 13 564	00'295'9	5 OET			2661/1/1	1102/82/6	
ISCHESMA	KW 77TH CT	TAN TOTAL OF THE TANK TO THE TANK	10'152'00	1		70	6661/1/1	1102/12/6	001
ISCRESAW	TAM HIGH MA	3VA HTAR WH IN W A TTS	00'6ES'S	5.03		¥C	1661/1/1	1102/12/6	E6
	WW 38TH AVE	TAA HTEE WW	00015'61	507			1661/1/1 1661/1/1		52
ISCHESMA	JVA HTTS WW to 3 A CTS	IVA HITE WN	00'555'8	5 091		24	2661/1/1	1102/82/6	99 76
1SONESAW	JVA HTET WA	AND TER	35'191'00			¥C	2661/1/1	1102/12/6	26
ISONESAN	WA SSRD LEW	WW BATH AVE	00 109/11	5.001		• • • • •	2661/1/1	1102/12/6	11
1SONESAN	321 FT E OF NW 871H AVE	377 61 W DI WW 841H AVE	00'562'9				2661/1/1 	1102/12/6	83
LSOUESAN	WA STRD LEW	WAS SHO	16'355'00			. DA	1661/1/1	1102/12/6	89
831CN75AM	WM 25KD LEB	IS CHES MN	56,968.00	502		AC AC	6661/1/1	1102/12/6	
N31CN/SAM	IS ONES MA	831 GNZ5 MN	3'578'00	s ot		VC VC	6661/1/1	6661/1/1	
1SUNESAU	KW 102TH CT	3VA HT801 WM	10'0250'01	108		¥C	6661/1/1	1102/12/6	66
15GNZSAM	3VA HTT# WM to 3 A 265	JVA HTTO WN	00.000,8			AC	6661/1/1	1102/12/6	08
1SON ESAM	3VA HITS WM 30 3 11 935	3VA HITE WM 3D 3 11 152	00'610'9	5.022		. DA	6661/1/1	1102/12/6	
150N25AA	3VA HTT8 WM 3O 3 T3 2E3	369 FT M OF MM 841H AVE	5,335.00	S'OET		AC	6661/1/1	6661/1/1	001
	Liom	oT	(12) ABRA	Section ID	Section Rank	SURFACE	Construction Date	Inspection	ы
STREET NAME									

		0101/1:2				100 00 -f-			
	2102/31/2	0102/1/1	AC AC		٤	00'005'2	D29 HTELL WH	HTA9 HTA11 WM	MASSKDIER
86	1102/12/6	2661/1/1	2A ZA		OE	00'256'72	3VA HTSLI WM	3VA HITOT WW	1SON/EANN
	1102/52/6	2661/1/1	24	1	30	00.789,55	HIVA HIFTI MN	3VA HTSII WN	1SON/RANN
86	1102/12/6	2661/1/1	YC	Ĩ	01	00 509 89	JVA HTTI I WN	HTA9 HTA11 WM	1SON 28MN
88	1102/\$7/6	6002/1/1	70	b	001	30,885,00	T2 HTAS WN	503 ET 5 OF NW 14TH 5T	3VAGN 58WW
06	1107/17/6	1002/1/1	70	5	OE	00'2EB'SI	15 H185 MN	12 H195 WN	3VAGH SBWN
и	1102/12/6	1002/1/1	עכ	s	01	00'6E6'SL	15 H195 MN	12 H 1 P 2	3VAGN S8WW
16	1102/92/6	\$661/1/1	VC	d	06 L	00 125'61	15 H19E MN	IS HILLE MN	3VAGM SBWM
66	1102/92/6	566T/T/T	vc	đ	021	00'SPE'6	15 1STE MN	AST HTOE WA	AVAGN28WN
SL.	1102/12/6	S661/1/1	AC AC	d	ost	10'100 00	AW SOTH TER	15 H16Z MN	3AVGN28AAN
E 9	1102/17/6	5661/1/1	yc (d	001	16,424.00	IS HIZE MN	15 HLZE MN 10 5 4 ZPS	AVAGN SBWN
100	1102/92/6	\$661/1/1	¥C		500Z	00'225'7	15 1512 MN 30 N 19 640	15 15TZ MN 40 N 14 T82	AVAGNSBWW
001	1102/#2/6	6002/1/1			DET	00 816'2	15 1512 MN 10 N 11 182	15 1512 MN	AWARNERWN
68	1102/22/6	\$661/1/1	vc		091	00 908'S	254 EL 2 OL MM 321H 21	15 1512 MN 40 N 14 619	3VAQNSEWN
28	1102/02/6	5661/1/1	VC						
			L		09	10'111'91	12 H175 WW	T2 H125 MN	3VADAYS
18	1102/02/6	6002/1/1	٧C		091	55,529.00	15 T215 WW	15 1215 WW 30 2 11 738	3VADAYSWW
	1102/92/6	\$661/1/1	AC		011	00'299'61	IS ONEE MN	12 T216 WM	3VAQNS2WW
SS	1102/92/6	\$661/1/t	¥C	d	00	33'366.00	TE OREE WN IO N A 955	T2 GALE WN	AW82KDVAE
58	1102/\$2/6	600Z/1/L	۶¢	b	oz	16,236.00	15 H152 MN	12 H1 S OL HM 32 H 21	3VAGMS8WM
66	1102/92/6	6002/1/1	, SAC	d	02	00'669'ET	IS HIST MOI MA IS HIST	15 HIZT MN	3VAGN58WW
96	1102/92/6	\$661/1/I	∀C	b d	os	54'286'00	15 H162 MN	12 HIZZ MN	3VAGN'SWW
08	1107/17/6	600Z/T/T	۷ ۲	đ	06	00'EZÞ'ÞE	15 H121 MN	IS HIPT AN	JAYONZSMN
02	1102/þ2/6	5661/1/l	V C		0 ZL	31'038'00	15 151¢ MN	T2 HT35 WM	JVAGNSSWN
Z6	1102/12/6	\$661/1/t	VC		09	00'995'01	15 HILT MN JON 13 900	ISHLLT MN	3VAGNS8WW
	2102/01/2	5002/1/1		-	2	35'040'00	WW 113TH AVE	IDHITT MN	NUHLOSAN
	2102/01/2	5002/1/1			t	19,200.00	IN TITLE IN	3VA HTEOL WH	NJHTOSWN
96	2102/01/2	5002/1/1	1		1	00 099 11			
	1		¥C		T		NW 1121H FL	TH HIELL WN	N1H162MN
96	2/10/501/2	5002/1/1	YC YC		£	00'005'5	WW 111TH CT	JVM 1121H AVE	NJHTetwn
96	2102/01/2	5007/T/T	YC V		Z	00'098'5	3VA HTSEE WM	WW TIZTH PL	NJHTETWN
100	1102/12/6	0102/1/1	AC AC	đ	140	00'11('91	15 H125 MN	15 H195 MN	3VAHTETWN
300	1102/12/6	0102/1/1	VC	đ	015	00.634,8	12 HTO2 WN 10 N A 691	15 HLOS MW	AWPETHAVE
100	1102/12/6	0102/1/1	VC	d	ot	33'353 00	15 1STE MN	12 HTes WM	3VAH10TWN
00 T	0102/1/1	0102/1/1	VC	ď	OL	3'869'00	12 1214 WN	12 T2/4 WN	3VAHTETWN
66	1102/12/6	0102/1/1	VC	đ	07	13'024'00	305 F N 91 NM 4721 21	15 LSTP MN	3VAHTETWN
100	1102/12/6	1/1/2010	vc	a	001	00'959'61	TE GRED WN	362 EL N OL NM 4721 21	3VAHTETWN
66	1102/12/6	0102/1/1	70		ÖSZ	00.756.8	15 QUEP MN 10 N 11 661	LS QUED MN	3VAHTETWN
	0102/1/1	0102/1/1	DAC .		350	00'616'2	15 GHEP 10 N 11 BEE	15 CHEP 30 N 13 641	3VAHTerwn
	1102/12/6	0102/1/1	vc		530	00	IS HIDS AN	IS HIB MM	3VAHTETWN
	1102/12/6	0102/1/1			051	00'528'98	TE ORES WW	15 ONZS ANN	3VAHTETWH
			• • • •						
	1102/12/6	0102/1/1	νc 		340	00.089,8	15 GNZS AN	15 1515 MW	3VAHTETWN
	1102/12/6	1/1/5010	AC		520	00 999 'SE	15 15t5 MM	T2 T212 WN 10 2 A 601	JVAHTETWN
	1102/12/6	1/1/2010	VC		150	00 99E ST	15 GHZE MN	IS ISTE MN	JVAHTETWN
00 t	1102/12/6	1/1/5010	7	đ	06	00 681 91	15 H195 MM	IS HISS AN	3VAHTetwn
100	1102/12/6	1/1/2010	AC	ď	330	00 9/2'61	LS HLLP MN	15 H12 P MN (P 5 U 986	3VAHTETWN
00 T	1107/17/6	0102/1/1	VC VC	· · · ·	011	00 STE 91	T2 HT82 WM	15 HILS MN	3VAHTerww
700	1102/12/6	0102/1/1	24	a	05	00'856'91	LS HLSS MN	T2 HT42 WM	3VAHTETVVN
001	1102/12/6	0102/1/1	vc		500	51'814'00	15 HLLE MN 10 5 11 867	15 HILE MN	3VAHTETVYN
001	1102/12/6	0102/1/1	VC VC		091	16,273 00	IS CHEE MAN	15 ONZE MN	3VAHTETWA
	1102/12/6	0102/1/1	עכ		09	00'256'2	15 H197 MM JO N 1365	15 H19# MN	3VAHTETWAN
66	1107/17/6	1/1/2010	AC .		05	00 +59'11	15H197 MN 40 5 14722	12 H199 MN	JVAHTETWW
	1102/12/6	0102/1/1	vc		0£	00 69249 00	12H195 WW	15 H1SZ WN	JAVHL6LMN
	1102/12/6		i		1			T2 UT22 WM	3VAHTETWN 3VAHTETWN
		0102/1/1	VC		50	16,747.00	15 H195 MN		
001	1102/16/21	1102/16/21	YC		340	55'332'00	12 HILL MN 30 N 13 992		3VAHTETWN
	1102/16/21	1102/16/21	עכ		OSE	16,329.00	244 ET 5 OF KW 2321 5T	15 1515 MM	3VAHTETWN
16	1102/12/6	1/1/2010	YC		580	00'096'2	15 H19E MN		3AVH16LMN
59	1102/92/6	2661/1/1	עכ	· · ·	021	00 025 61	15 HLLT MN	IS HIST WW	3VAHTETWN
00T	1102/12/6	0102/1/1	VC YC	·ā	OEL	00'600'52	IS HIPE MN	TZ CITEE WIN	3VAHTETWN
66	1102/12/6	0102/1/1	vc	ď	001	00'160'11	IS HIDE WN	IS HILLE AN	JVAHTETWN
00 T	1102/15/21	1102/15/21	VC	. 5	091	00'EEB'61	IS HIST AN	T2HT4T WM	3VAHTETWN
·	ateQ	9J&Q	+			· · · · ·			······
ысі	robceden tast	tesl Construction	SURFACE	Section Rank	Ol notros2	(72) A <u>3</u> RA	01	moni	3MAN T338T2
-									

SNDAVE	350 EL 2 OE NM 53LH 21 ET8 EL 2 OE NM 53LH 21	T2 HT25 WN 30 FT 813 T2 HT65 WN 30 FT 813	00 602'21 00 259'91	05 07		AC AC	0002/1/1 0002/1/1	1102/22/6 1102/22/6	06
JAADNS	Dezd End	15 HLBS MN	00.838,81	01		AC	1/1/5000	1102/E2/6	02
JAVIST	12 DAFE WN	ba3 ba9Q	00'282'21	10	s		6661/1/1	1102/02/6	ZB
14н16	T2 HT05 WW	IS QUEZ MN	00'526'22	08	L	DV.	6661/1/1	1102/22/6	Z 6
мніє	T2 CAES WW	15 HISE MN	18,244.00	30	L	AC	6661/1/1	1102/22/6	76
J GH16	15 HLSZ MN	T2 HT25 WN	5,043.00	07	1	VC	6661/1/1	1102/22/6	£L
7 93416	WM TELH LEB	T2 HT05 WN	21,483.00	01	1	YC YC	6661/1/1	1102/22/6	16
10916	IS HIZT MH	APT HTER WW	00 526'51	09	1	VC	2661/1/1	1107/77/6	£8
12816	ABT HTEL WW	T2 HT21 WN	00 066'ET	05	1	VC	2661/1/1	1102/22/6	68
12H16	LS HLSZ MN	12 H196 MM	00 116'EL	07	s	VC	6661/1/1	1102/22/6	16
12HTE	IS HISZ MN	IS HILL MA	J6,602.00	30	s	YC	6661/1/1	1102/22/6	28
12H16	T2 CHEE WH	NT HISE MA	50'333'00	50	s)AC	6661/1/1	1102/92/6	118
13H16	IS HIST AN	bn3 basQ,	00'615'9	01	1)AC	2661/1/1	1102/22/6	59
12H18	JVA HTSII WH	3VA HTPET WN	50,055 00	2	ś	AC.	1/1/2010	2102/01/2	96
T2HTB	3VA HTTOL WM	3VA HTEOT WN	56,520.00	i	s	AC AC	1002/1/1	2102/01/2	78
12418	RATHTER WA	IS HIDE MN	50'582'02	01	··· ··· ··	, , , , , , , , , , , , , , , , , , ,	2661/1/1	1102/22/6	12
TOHIS	T2 HT05 WH	NW 2121 164	00.039,91	30	1	¥C	2661/1/1	1102/22/6	\$8
TOHIS	NW STST LEG	T2 ORES WW	00'997'EL	OE	1	DA.	2661/1/1	1102/22/6	£9
3VAHTE	NATEL WH	IS HIST MW	00'596'98	30	1	AC	\$661/1/1	1102/22/6	82
3VAHT8	IS HIST MN	Dead End	00'181'5	01	i		2661/1/1	1102/22/6	£6
12411	IS H192 MN	15 H122 AN	00 9/0'/1	ot	s	AC	1/1/3003	1102/22/6	98
15H19	3VA HTEOL WN	WW 103TH CT	00'215'9	09	s	AC	\$002/1/1	1102/12/6	86
15419	BVA HTOLL WA	THIOTT MN	00 951'9	os	s	γC	\$00Z/1/1	1102/62/6	£8
12415	TO HITTI WR	3VA HTSIL WW	00'296'9	50	s		\$002/1/1	1102/62/6	001
15419	3VA HTTOT WA	3VA HTEOS WM	00 / 10 81	01	s	AC	\$002/1/1	1102/62/6	00 T
15419	JVA HTEOL WA	3VA HTOT & WM	00'56\$'21	06	5	AC	5002/1/1	1102/62/6	76
12413	THE HLOTT MA	LD HLTTT MN	8'105'00	01		ΥC	5007/1/1	1102/12/6	0 8
12112	TO HIEOT WA	NM 1001H VAE	00'67/'8	09		DA	5002/1/1	1102/12/5	100
12H13	JVA HTSII WA	HTAT HTAT WW	00 081,9E			ЭA	6002/1/1	2102/01/2	100
12012	324 HISTI WI	IDNHIST MN	00'001'5	06		2A	0102/1/1	2102/01/2	100
3VAHT0	111 ST21 LEK	15 Q352 MN	13,162.00	01)A.	E002/1/E	1102/22/6	
831414	32API HIELI WA	1) HIST MN	00 090'S	τ		AC	0102/1/1	2102/01/2	00T
83THT6	LT HISTI NU	HTA9 HTA11 WM	00'009'9	z		AC	0102/1/1	2102/01/2	001
15414	TI HISTI MU	LD HISTT AW	00.070,6	s		24	0102/1/1	2102/01/2	100
12411	ITTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	3VA HTELE WA	00 001'E	•		, AC	\$002/1/1	2102/01/2	96
12411	10 H10TT MA		00 076'5	L		, AC	5002/1/1	5002/1/1	001
12HTA	3VA HTOLE WW	10 HLOTT AN	00 032'5			vc	5002/1/1	2102/01/2	96
12H14	JVA HTEOI WN	JYA HTOTT WW	00 029'EL			·	S002/1/L	2102/01/2	96
ATHAVE	ISHLLT AN	15 H165 MW	00'211'28	i			5661/1/1	1102/22/6	98
374114	IS ON ES MU	TE ONSE WIN TO HIRON TH LEL	00.678,5			AC	6661/1/1	6661/1/1	001
3VAHTA 2VAHTA	15 ONES MAN JO HEROS LA TAL	IS (385 M)	00'690'0	05			6661/1/1	1102/12/6	28
3VAHTA	IS CHES AN	NN 838D 11	00 1/6'61			AC	6661/1/1	1102/82/6	59
374474	15 GRES WN TO HTUOS TT BAC	IS GHE MA	55,450.00	06			5661/1/1	1102/22/6	
3VAHTA 3VAHTA	IS USEC MA SO HEROS IS SUC	15 Udec MN	00 196'ST	09		AC	1/1/1	1102/12/6	28 001
3VAHTA 3VAHTA	13 11 12 13 11 12 13 13 13 13 13 13 13 13 13 13 13 13 13	12 H171 WW		09		AC	\$661/1/1 \$661/1/1	1102/22/6	88
3VAHTA 3VAHTA	12 HILL WN 30 HILOS 13 FLET 15 HILL WN 30 HILOS 13 FLET	3VA HTAB WW T2 HT71 WW	00'125'6E 00'922'2E	OF			\$661/1/1 \$661/1/1	1102/22/6	¥8 76
374114	15 H195 MM	IS HIDS WW	00'922 21 00'0E2'ST	011		AC AC	1002/1/1	1102/82/6	26
374476	12 H161 WM	12 HIGI JO HINON 11 981	00 985'5	110		vc vc	\$661/1/1	1102/12/6	26
3VAHTA 3VAHTA	NA 30TH TOF WW	T2 MIPL 30 MIRON I 3 ML	00 995 5	501		VC	2661/1/1	1102/22/6	59
41HAVE	12 MIG 201H 116	NN 301H 1EU		i				1102/12/6	59 189
	12 HILLS WN		10'115 00	140		¥C	2661/1/1		
3VAN14		IS H162 MM	00 / 11'81			עכ אר	2661/1/1	1102/12/6	
374414	15 11 15 11 15 11 15 11 15 11 15 15 15 1	NW 131H TER	54'552'00	091		ענ 'יייר	\$661/1/1	1102/22/6	16 00
THAVE	IS ONES MIN TO HERON TH LEL	15 DIES ANN 30 HENOS LI TET	00'510'8	09		AC	6661/1/1	1102/12/6	88
THAN	15 H122 MN	pu3 prad	00 919'91	051		AC	1661/1/1	1102/12/6	22
JVAHT	T2 0382 WN	15 H15Z MN	00'\$67'91	1		AC	0102/1/1	1102/22/6	86
36DMA	3VA HTALL WN	WA 115TH CI	2,292.00	1			0102/1/1	2102/01/2	001
WILCH	D24 H1ELT MN	NW 3331H CI	00022'9	E		AC .	0108/1/1	2102/01/2	001
SINDIER	NW TISTHCE	HTA9 HTA1 HTA1 WN	8,140.00	1	s 	AC	0102/1/1	2102/01/2	001
JMAN T338	mori	01	(72) A3AA	Gl nottos2	สุทธส กอเว วอ2	3DATRU2	tael Construction SteC	Last Date Date	PCI

bCI	Last Inspection Date	Last Construction Date	Section Rank SURFACE	GI nottos2	(32) A3RA	oī	From	3MAN TƏƏRTZ
18	1102/22/6	1/1/5000	AC	SOE	15'264'00	15 H1SZ MN JO N ¥ GTE	12 H122 WW	JVAQNSew
300	1102/22/6	0102/1/1	AC AC	1 02	00 [.] 916'S	12 HIST MN 30 N 13 261	12H1SE WM	TODAREW
100	1102/22/6	0102/1/1	DA	1 01	00'96E'8	260 FT 5 OF NW 331H 5T	T2 HTEL WN	W93RDCT
700	1102/22/6	0102/1/1	νc	5 02	00'690'9	IS HILZ MN	T2 HT35 WM	3VAHT82W
00 T	1102/22/6	0102/1/1	vc	SOE	2'9\$6'5	NW 28TH TER	NW STTH TER	3VAHT82W
001	1102/22/6	0102/1/1	vc	sos	00'262'\$	A 27TH TER	12 H175 WM	3VAHT86W
700	1102/22/6	0102/1/1	עכ	5 OP	00'852'5	12 HT25 WW	HISS WW	3VAHT82W
001	1102/22/6	6661/1/1	VC	soz	00'9 *5' 9E	15 HIPT MN	T2 HTSE WH	TOHTREW
£6	1102/22/6	6661/1/1	VC	sot	00'6EZ'9E	15 HILT MN	12 H141 MN	1091864
00 t	1102/22/6	1/1/5010	VC	sot	00'26Z'S	15 H122 MN	15 H192 MN	3VAHTeew
100	1107/22/6	1/1/3010	AC AC	\$ 08	00'101'2	A3T HT25 WW	T2 HT25 WM	3VAHTeew
00τ	1102/22/6	1/1/5010	ΥC	5 02	00 *** '5	NW 27TH TER	15 HLZZ AN	3VAHT66W
89	1102/22/6	6661/1/1	YC.	1 05	00'¥91'/E	IS HISZ MN	15 1512 MW	3VAHT00W
00 L	1102/22/6	1/1/5010	YC YC	5 07	00'612'1	bead End	MW 28TH TER	3VAHT66W
00 t	1102/22/6	0102/1/1	YC YC	SÖE	2'353'00	NW 281H TER	WA 27TH TER	3VAHT62W
88	1102/92/6	1/1/5000	YC YC	s 06	00'\$E6'8	3VA HTEE WH	12 H182 WW	3VAHT00W
29	1102/92/6	1/1/2000	VC VC	5 02	00'896'61	12 HT03 WN	3VA HTEE WN	3VAH166W
001	1102/22/6	0102/1/1) AC	5 09	00.818.5	15 H192 MN	A31 HT25 WM	3VAHTeew

Branch ID	Section ID	From	То	PCI_2007	PCI_2011
NW100THAVE	10	NW 25TH TER	NW 26TH ST	87	93
NW100THAVE	20	NW 27TH ST	NW 27TH TER	70.4	68
NW100THAVE	30	NW 27TH TER	NW 28TH TER	93	70
NW100THAVE	40	NW 28TH TER	Dead End	93	100
NW100THAVE	50	NW 14TH ST	NW 15TH TER	75.2	91
NW100THAVE	60	NW 26TH ST	NW 27TH ST	88.8	79
NW102NDAVE	70	NW 41ST ST	NW 43RD TER	69.7	71
NW102NDAVE	90	NW 15TH TER	NW 19TH ST	72.1	95
NW102NDAVE	100	NW 58TH ST	Dead End	46.2	97
NW102NDAVE	110	NW 27TH TER	NW 28TH TER	93	68
NW102NDAVE	120	NW 21ST ST	NW 25TH ST	38.8	100
NW102NDAVE	130	NW 27TH ST	NW 27TH TER	41.9	57
NW102NDAVE	140	NW 25TH ST	117 ft N of NW 25TH ST	92.9	73
NW102NDAVE	150	258 ft S of NW 26TH ST	NW 26TH ST	92.9	73
NW102NDAVE	160	NW 26TH ST	NW 27TH ST	90.6	74
NW102NDAVE	100	NW 48TH STREET CIR	NW 49TH LN	74	97
NW102NDAVE	180	NW 19TH ST	NW 21ST ST	88.8	<u>57</u> 99
NW102NDAVE	190	NW 56TH TER	NW 58TH ST	93	78
NW102NDAVE	200	NW 46TH ST	NW 102ND AVE	74	85
NW102NDAVE	210	NW 43RD TER	NW 46TH ST	69.7	88
NW102NDAVE	240	NW 66TH ST	Dead End	N/A	100
NW102NDAVE	250	NW 28TH TER	191 ft N of NW 28TH TER	93	96
	250	NW 52ND ST		67.3	92
NW102NDAVE			NW 56TH TER		
NW102NDAVE	270		414 ft N of NW 102ND AVE	74	99
NW102NDAVE	280	455 ft S of NW 48TH STREET CIR	NW 48TH STREET CIR	74	99
NW102NDAVE	290	NW 49TH LN	NW 52ND ST	74	99
NW102NDPL	10	NW 21ST ST	NW 25TH ST	56.6	82
NW104THAVE	10	NW 36TH ST	NW 37TH TER	81.9	76
NW104THAVE	20	NW 37TH TER	NW 41ST ST	78.5	
NW104THAVE	30	NW 58TH ST	Dead End	84.1	71
NW104THAVE	40	NW 33RD ST	NW 36TH ST	90.3	96
NW104THCT	10	NW 26TH ST	NW 28TH ST	70.5	92
NW105THAVE	10	NW 31ST TER	NW 33RD ST	88.8	92
NW105THAVE	20	NW 26TH ST	NW 27TH ST	90.5	96
NW10STHAVE	30	NW 27TH ST	NW 28TH ST	77.8	97
NW108THAVE	10	NW 27TH ST	NW 29TH ST	90.3	100
NW108THAVE	20	NW 29TH ST	NW 30TH ST	100	88
NW108THAVE	30	NW 30TH ST	NW 33RD ST	100	100
NW109THAVE	10	681 ft S of NW 90TH ST	NW 90TH ST	78	83
NW109THAVE	20	NW 43RD LN	NW 48TH LN	86	93
NW109THAVE	30	NW SOTH ST	NW 51ST LN	78.5	98
NW109THAVE	40	NW 51ST LN	NW 53RD LN	78.5	98
NW109THAVE	50	NW 30TH ST	NW 33RD ST	100	100
NW109THAVE	60	NW 29TH ST	NW 109TH AVE	44.9	100
NW109THAVE	70	NW 53RD LN	NW 5BTH ST	72.1	76
NW109THAVE	80	NW 27TH ST	NW 29TH ST	70.7	100
NW109THAVE	90	NW 109TH AVE	NW 30TH ST	44.9	100
NW109THAVE	100	NW 87TH ST	320 ft N of NW 87TH ST	78	96
NW109THAVE	110	NW 48TH LN	NW 50TH ST	86	98
NW109THAVE	120	NW 415T ST	NW 43RD LN	<u>N/A</u>	97
NW109THAVE	130	NW 86TH ST	NW 87TH ST	70.2	99

PCI_2011	PCI_2007	То	From	Section ID	Branch ID
85	100	Dead End	NW 29TH ST	10	NW110THAVE
91	100	NW 74TH TER	NW 74TH ST	10	NW112THAVE
96	86	NW 58TH ST	NW 53RD LN	20	NW112THAVE
100	73.2	NW 27TH ST	NW 25TH ST	30	NW112THAVE
91	100	NW 75TH TER	NW 74TH TER	40	NW112THAVE
100	46.9	NW 29TH ST	NW 27TH ST	50	NW112THAVE
82	100	NW 77TH TER	NW 75TH LN	_60	NW112THAVE
78	100	NW 78TH ST	NW 77TH TER	70	NW112THAVE
83	100	NW 82ND ST	NW 80TH LN	80	NW112THAVE
99	90.3	NW 48TH TER	NW 46TH LN	90	NW112THAVE
81	100	NW 75TH LN	NW 75TH TER	100	NW112THAVE
100	69.3	NW 42ND LN	NW 41ST ST	110	NW112THAVE
93	87.1	NW 53RD LN	NW 52ND ST	120	NW112THAVE
95	100	NW 80TH LN	NW 79TH LN	130	NW112THAVE
83	100	NW 78TH LN	NW 78TH ST	140	NW112THAVE
98	69.3	NW 43RD LN	NW 42ND LN	150	NW112THAVE
96	69.3	NW 46TH LN	NW 43RD LN	160	NW112THAVE
100	N/A	NW 86TH ST	NW 84TH ST	170	NW112THAVE
99	N/A	NW 84TH ST	301 ft S of NW 84TH ST	180	NW112THAVE
100	100	NW 30TH ST	NW 29TH ST	190	NW112THAVE
100	N/A	NW 87TH ST	NW 85TH ST	200	NW112THAVE
72	100	NW 79TH LN	NW 78TH LN	210	NW112THAVE
93	100	NW 112TH AVE	NW 82ND ST	220	NW112THAVE
95	87.1	NW 52ND ST	NW 50TH ST	230	NW112THAVE
91	90.3	NW 50TH ST	NW 48TH TER	240	NW112THAVE
100	N/A	286 ft NW of NW 112TH AVE	NW 112TH AVE	250	NW112THAVE
100	90.3	NW 33RD ST	NW 30TH ST	260	NW112THAVE
77	90.3	NW 34TH ST	NW 33RD ST	270	NW112THAVE
99	100	NW 90TH ST	NW 87TH ST	280	NW112THAVE
99	N/A	NW 36TH TER	NW 34TH ST	10	NW113THCT
59	90.3	NW 74TH ST	NW 73RD TER	10	NW114THAVE
65	87.1	NW 60TH ST	NW 114TH AVE	20	NW114THAVE
65	75.2	NW 78TH ST	NW 77TH LN	30	NW114THAVE
65	100	NW 114TH AVE	NW 62ND TER	40	NW114THAVE
98	87.1	NW 36TH TER	NW 34TH ST	50	NW114THAVE
100	72	NW 42ND TER	NW 41ST ST	60	NW114THAVE
100	72	NW 43RD TER	NW 42ND TER	70	NW114THAVE
98	83.1	NW 114TH AVE	NW 48TH TER	80	NW114THAVE
92	90.3	NW 41ST ST	NW 39TH ST	90	NW114THAVE
88	100	NW 55TH ST	297 ft S of NW 55TH ST	100	NW114THAVE
97	83.1	NW 39TH ST	NW 36TH TER	110	NW114THAVE
70	90.3	NW 73RD TER	NW 72ND ST	120	NW114THAVE
100	87.1	NW 114TH AVE	NW 58TH ST	130	NW114THAVE
65	100	496 ft N of NW 78TH ST	NW 78TH ST	140	NW114THAVE
70	100	NW 114TH AVE	NW 114TH AVE	150	NW114THAVE
76	87.3	NW 58TH ST	NW 57TH ST	160	NW114THAVE
83	72	NW 44TH ST	NW 43RD TER	170	NW114THAVE
82	100	NW 66TH ST	NW 114TH AVE	180	NW114THAVE
98	83.1	NW 47TH ST	NW 44TH ST	190	NW114THAVE
94	83.1	NW 48TH TER	NW 47TH ST	200	NW114THAVE
63	90.3	NW 72ND ST	NW 69TH TER	210	NW114THAVE

PCI_2011	PCI_2007	To	From	Section ID	Branch ID
100	89.2	NW 68TH TER	NW 67TH TER	220	NW114THAVE
64	90.3	NW 69TH TER	NW 68TH TER	230	NW114THAVE
65	89.2	NW 67TH TER	NW 66TH ST	240	NW114THAVE
100	87.3	NW 57TH ST	NW 55TH ST	250	NW114THAVE
93	83.1	NW 50TH ST	NW 114TH AVE	260	NW114THAVE
96	100	928 ft N of NW 51ST TER	NW 51ST TER	270	NW114THAVE
79	75.2	NW 77TH LN	NW 75TH LN	280	NW114THAVE
68	75.2	NW 75TH LN	NW 74TH ST	300	NW114THAVE
69	87.1	NW 62ND TER	NW 60TH ST	310	NW114THAVE
98	100	NW 51ST TER	NW 50TH ST	320	NW114THAVE
96	62.1	NW 39TH ST	NW 34TH ST	10	NW115THAVE
97	62.1	NW 41ST ST	NW 39TH ST	20	NW11STHAVE
100	84.4	NW 50TH ST	FLORIDA TPKE RAMP	10	NW117THAVE
63	17	NW 58TH ST	NW 117TH AVE	20	NW117THAVE
84	17	NW 117TH AVE	NW 50TH ST	30	NW117THAVE
63	46.9	Dead End	NW 34TH ST	40	NW117THAVE
100	67.3	NW 97TH AVE	NW 13TH ST	10	NW13THST
100	67.3	NW 13TH ST	NW 13TH ST	20	NW13THST
100	67.3	NW 13TH ST	NW 13TH ST	30	NW13THST
100	67.3	NW 13TH ST	NW 93RD CT	40	NW13THST
89	88.8	Dead End	NW 89TH CT	10	NW13THTER
76	73	NW 88TH AVE	NW 87TH AVE	20	NW13THTER
76	62.5	NW 89TH CT	NW 88TH AVE	30	NW13THTER
99	90.3	NW 100TH AVE	NW 98TH CT	10	NW14THST
85	50.9	Dead End	NW 82ND AVE	20	NW14THST
84	77.7	NW 82ND AVE	NW 79TH AVE	30	NW14THST
63	77.9	NW 79TH AVE	NW 78TH AVE	10	NW15THST
82	100	Dead End	NW 89TH CT	20	NW15THST
76	71.4	NW 88TH AVE	NW 87TH AVE	30	NW15THST
94	81.1	NW 89TH CT	NW 88TH AVE	40	NW15THST
100	93	NW 102ND AVE	NW 100TH AVE	10	NW15THTER
92	86	NW 19TH ST	NW 98TH CT	10	NW17THST
100	88	NW 98TH CT	NW 97TH AVE	20	NW17THST
83	69.3	NW 87TH AVE	NW 84TH AVE	30	NW17THST
90	76	783 ft W of NW 82ND AVE	NW 82ND AVE	40	NW17THST
91	64.9	NW 89TH PL	NW 88TH CT	10	NW18THTER
90	63.9	NW 88TH CT	NW 87TH AVE	20	NW18THTER
98	86	NW 102ND AVE	NW 17TH ST	10	NW19THST
95	86	NW 107TH AVE	NW 102ND AVE	20	NW19THST
70	77.7	NW 89TH PL	NW 88TH CT	10	NW20THST
87	93	NW 102ND PL	NW 102ND AVE	10	NW21STST
84		NW 21ST ST	392 ft E of NW 21ST ST	20	NW21STST
60	66.5	NW 21ST ST	NW 79TH AVE	30	NW21STST
95	73.3	NW 21ST ST	NW 102ND PL	40	NW21STST
51	66.5	NW 82ND AVE	NW 21ST ST	50	NW21STST
100		436 ft W of NW 21ST ST	NW 21ST ST	60	NW21STST
86		NW 21ST ST	NW 21ST ST	70	NW21STST
82	73	NW 215T ST	NW 99TH AVE	80	NW21STST
82	73	NW 102ND AVE	NW 21ST ST	90	NW21STST
86		NW 21ST ST	NW 21ST ST	100	NW21STST
95	81.6	Dead End	NW 82ND AVE	110	NW21STST

Branch ID	Section ID	From	То	PCI_2007	PCI_2011
NW21STST	120	NW 21ST ST	NW 107TH AVE		86
NW21STTER	10	NW 86TH AVE	NW 87TH AVE	77.1	80
NW21STTER	20	NW 87TH AVE	NW 88TH CT	47	78
NW23RDST	10	NW 88TH CT	NW 89TH PL	86	76
NW23RDST	20	NW 84TH AVE	NW 86TH AVE	76	86
NW24THTER	10	NW 25TH ST	NW 89TH PL	40.3	83
NW25THTER	10	NW 99TH AVE	NW 100TH AVE	80.2	68
NW25THTER	20	NW 98TH AVE	NW 99TH AVE	87	96
NW26THST	10	NW 104TH CT	NW 105TH AVE	88.8	91
NW26THST	20	NW 87TH CT	NW 89TH CT	88.8	86
NW26THST	30	NW 100TH AVE	NW 102ND AVE	87	84
NW26THST	40	NW 99TH AVE	NW 100TH AVE	89.2	85
NW26THST	50	NW 98TH AVE	NW 99TH AVE	84.3	90
NW26THST	60	NW 97TH AVE	NW 98TH AVE		87
NW27THST	10	NW 109TH AVE	NW 112TH AVE	86	97
NW27THST	20	NW 97TH AVE	NW 98TH AVE	89.1	100
NW27THST	30	NW 82ND AVE	NW 84TH AVE	42.2	78
NW27THST	40	NW 87TH CT	NW 89TH CT	84.4	81
NW27THST	50	NW 99TH AVE	NW 100TH AVE	93	91
NW27THST	60	NW 84TH AVE	NW 87TH AVE	54.6	78
NW27THST	70	NW 87TH AVE	NW 87TH CT	61.1	84
NW27THST	80	NW 98TH AVE	NW 99TH AVE	93	86
NW27THST	90	NW 108TH AVE	NW 109TH AVE	41.4	100
NW27THST	100	NW 107TH AVE	NW 108TH AVE	77.5	100
NW27THST	110	NW 105TH AVE	NW 107TH AVE	89.2	100
NW27THST	120	NW 100TH AVE	NW 102ND AVE	93	83
NW27THTER	10	NW 100TH AVE	NW 102ND AVE	73.2	100
NW27THTER	20	NW 99TH AVE	NW 100TH AVE	71.8	100
NW27THTER	30	NW 98TH AVE	NW 99TH AVE	80.2	100
NW27THTER	40	NW 97TH AVE	NW 98TH AVE	48.2	100
NW28THST	10	NW 104TH CT	NW 105TH AVE	84.4	97
NW28THTER	10	NW 97TH AVE	NW 98TH AVE	88.8	100
NW28THTER	20	NW 99TH AVE	NW 200TH AVE	87.4	100
NW28THTER	30	NW 98TH AVE	NW 99TH AVE	84.4	80
NW28THTER	40	NW 100TH AVE	NW 102ND AVE	87.4	100
NW29THST	10	Dead End	NW 107TH AVE		100
NW29THST	20	NW 79TH AVE	NW 82ND AVE	63.9	77
NW29THST	30	NW 78TH AVE	NW 79TH AVE	69.5	86
NW29THST	40	NW 109TH AVE	NW 110TH AVE	87.1	95
NW29THST	50	NW 108TH AVE	NW 109TH AVE	75.8	91
NW29THST	60	NW 110TH AVE	NW 112TH AVE	83.1	87
NW29THST	70	Dead End	NW 92ND AVE	100	100
NW29THST	80	NW 84TH AVE	NW 87TH AVE	72	92
NW29THST	90	NW 77TH CT	NW 78TH AVE	69.5	80
NW29THTER	10	Dead End	NW 107TH AVE	51.9	82
NW30THST	10	NW 108TH AVE	NW 109TH AVE	88.8	99
NW30THST	20	NW 109TH AVE	NW 112TH AVE	90.3	99
NW30THTER	10	NW 82ND AVE	NW 84TH AVE	25.7	71
NW30THTER	20	NW 84TH AVE	NW 85TH AVE	46.7	84
NW30THTER		NW 85TH AVE	NW 87TH AVE		78
NW31STST	10	NW 79TH AVE	NW 82ND AVE	34.7	91

Branch ID	Section ID	From	То	PCI_2007	PCI_2011
NW31STST	20		NW 31ST TER		95
NW31STTER	10	NW 105TH AVE	NW 107TH AVE		93
NW31STTER	20	NW 31ST ST	NW 105TH AVE		100
NW33RDST	10	TORREMOLINOS AVE	NW 104TH AVE	78	81
NW33RDST	20	NW 84TH AVE	849 ft W of NW 84TH AVE	89.2	75
NW33RDST	30	NW 89TH CT	NW 91ST AVE	91.2	91
NW33RDST	40	NW 91ST AVE	Dead End	84.4	93
NW33RDST	50	NW 87TH AVE	NW 89TH CT	91.2	99
NW33RDST	60	633 ft E of NW 87TH AVE	NW 87TH AVE		83
NW33RDST	70	NW 82ND AVE	655 ft W of NW 82ND AVE	89.2	66
NW33RDST	80	NW 97TH AVE	NW 98TH CT		98
NW33RDST	90	575 ft E of NW 84TH AVE	NW 84TH AVE	89.2	67
NW33RDST	100	NW 104TH AVE	NW 105TH AVE	51	100
NW33RDST	110	NW 79TH AVE	NW 82ND AVE	34.7	73
NW33RDST	120	NW 107TH AVE	NW 108TH AVE	88.4	92
NW33RDST	130	NW 109TH AVE	NW 10311 AVE	89.1	93
NW33RDST	140	NW 109TH AVE	NW 11210 AVE	89.1	95
	140	337 ft E of NW 33RD ST	NW 33RD ST	07.1	1
NW33RDST NW33RDST	160	NW 105TH AVE		90.3	87
	170	NW 33RD ST	NW 107TH AVE	90.5	93
NW33RDST	170		TORREMOLINOS AVE		86
NW33RDST	10	NW 98TH CT	1327 ft W of NW 98TH CT		84
NW34THST	1	NW 115TH AVE	NW 117TH AVE	93	93
NW34THST	20	NW 114TH AVE	NW 115TH AVE	68.3	100
NW34THST	30	NW 113TH CT	NW 114TH AVE	90.3	100
NW34THST	40	NW 112TH AVE	NW 113TH CT	81.6	100
NW35THLN	10	NW 87TH AVE	NW 89TH CT	91.2	79
NW36THST	10	NW 104TH AVE	NW 107TH AVE	89.2	100
NW36THTER	10	NW 113TH CT	NW 114TH AVE	88.8	90
NW37THST	10	NW 78TH AVE	NW 79TH AVE	63.9	52
NW37THST	20	NW 77TH CT	NW 78TH AVE	32.5	50
NW37THTER	10	NW 104TH AVE	<u>NW 107TH AVE</u>	86	99
NW38THST	10	NW 78TH AVE	NW 79TH AVE	57.3	36
NW38THST	20	NW 40TH STREET RD	NW 97TH AVE	68.1	66
NW40THST	10	NW 38TH ST	NW 40TH STREET RD	88.3	64
NW40THST	20	NW 40TH STREET RD	NW 97TH AVE		73
NW41STST	10	NW BIST AVE	NW 82ND AVE	25.7	14
NW41STST	20	NW 79TH AVE	NW 815T AVE	25.7	55
NW41STST	40	NW 41ST ST	NW 87TH AVE		63
NW41STST	80	NW 82ND AVE	NW 41ST ST	27.7	45
NW50THST	10	NW 112TH AVE	NW 114TH AVE	64.1	81
NW50THST	20	NW 114TH CT	NW 115TH CT		100
NW50THST	30	NW 107TH AVE	NW 109TH AVE	72.1	90
NW50THST	40	NW 109TH AVE	NW 112TH AVE	79	100
NW50THST	50	NW 115TH CT	NW 117TH AVE	80.3	98
NW50THST	60	1218 ft E of NW 79TH AVE	NW 79TH AVE	9.1	64
NW50THST	70	NW 114TH AVE	<u>NW 114TH CT</u>	80.3	97
NWS2NDST	20	NW 104TH AVE	NW 104TH CT		91
NW52NDST	30	NW 84TH AVE	NW 84TH AVE		97
NW52NDST	40	NW 84TH AVE	175 ft W of NW 84TH AVE	39.2	96
NW52NDST	· 50	521 FT E OF NW 87TH AVE	367 FT W OF NW 84TH AVE	_	93
NW52NDST	70	NW 77TH CT	NW 78TH AVE	34.3	73

.

	·				
100		T2 HT42 WN	TZ CARE WN	05	3VAHT87WN
86	L'69	TS ORES WN	T2 ONS2 WN	40	3VAHT87WN
89	5.62	LS HIST MN	15 HIZT MN	30	3VAHT87WN
100	8.69	15 H125 MN	T2 HT32 WW	50	3VAHT8TWN
84	1.16	15 H195 MN	TS HT22 WN	ÖT	3VAHT8YWN
12	8:98	IS ONZE MN	12 H162 WN	05	MW77THCT
SL	72.6	T2 HT32 WW	T2 HT22 WN	40	ICHITCT
99	9'05	12 H122 WN	T2 HT42 WN	30	TOHITTWN
P 3	6.11	T2 QRE2 WN	TS ONS SWN	50	TOHITTY
79	61	T2 HT42 WN	TZ OREZ WW	OT	TJHITT
86	e/u	3VA HTSOL WN to W it Se2S	AVA HTYE WN	50	12H199WN
100	e/u	3VA HTTOL WN	3VA HTTOL WN 10 3 /1 8651	OT	T2HT33WW
100	1.18	3VA HTEY WN	3VA HTBY WN	50	1SH12SMN
001	5'88	3VA HT8Y WN	Dead End	10 10	1\$H1ZSWN
56	STE	3VA HT87 WN	TO HITT WN	05	1\$H19\$MN
58	· 1'19	JVA HTET WN	3VA HT87 WN	40	1SH19SWN
19	33'6	3VA HTT8 WN	3VA HTA8 WN	0E	TSHTƏZWN
VL	9.04	AVA 0NS8 WN	BVA HTET WN	50	1SH19SMN
\$8	2.05	3VA HTA8 WN	AW 82ND AVE	10	1SH19SWN
68	£.22	3VA HTET WN	3VA HT8T WN	50	TSHT22WW
06	84	AVA HT87 WW	ID H1// MN	στ	TSHT22WN
22	2'9	AVA 0NS8 WN	3VA HTET WN	05	T2HTA2WN
2 9	8.85	AVA HTT8 WW	3VA HTA8 WN	40	T2HTP2WN
88	2.69	AW HT87 WW	ID H1// MN	30	TSHTP2WN
06	\$'\$S	JVA HTET WN	AVA HT87 WN	50	T2HTA2WW
85	0	AVA HT48 WW	3VA GNS8 WN	10	T2HTA2WW
E8	1.163	AW 87TH AVE	3VA HTA8 WN	οτ	NWS3RDTER
001	80'4	3VA H187 WW	12 H1// MN	160	TZGREZWN
99		AVA HTY8 WW	3VA HTT8 WN to 3 Ji ets	140	TZOAEZWN
98		402 FT W OF 84TH AVE	3VA HT78 WN 10 3 11 652	730	TZOAEZWN
28		277 FT W OF NW 84TH AVE	3VA HTT8 WN 3O 3 T3 TS2	150	TZOREZWN
Z6	95	NW SZND TER	3VA HTET WN	011	TZOAEZWN
11	2'58	AVA HTA8 WN	MA SZAD TER	001	TZCIAEZWN
88	93.4	NW SZND TER	MA SZAD LEK	06	TZOREZWN
£6	TS	277 ft W of NW 84TH AVE	3VA HTA8 WN	08	TZOREZWN
٤٢	48.8	AVA HT67 WW	3VA HT87 WN		TZOAEZWN
18		IS OBES MN	NM 25/00 LEB	07	NW52NDTER
001	╉┣	NW S2ND TER	TZ GREZ WN	01	NWSZNDTER
ÞL	┥──┤	221 FT E OF NW 87TH AVE	3VA HTT8 WN 9O 3 T3 685	530	LISONSSUDST
86	┼──┼	3VA HTPOL WN	Id QNZQE MN	550	
E8	╂	3VA HTEE WN	3VA HTTE WN	510	LSONZSMN
£6	┨───┤	15 QNZS MN	3VA HTEE WN	007	LSGNZSMN
ν. γ.	+ - +	MM 1001H CL	3VA HT001 WN	0/1	
68	+	<u> </u>	NM TOPLH VIE	021 09T	LSONZSMN
ε.	97	3VA HTET WN	3VA HT87 WN	OST	
66	8.88	Id ONZOT MN	3VA UNSOL WW	140	
001		369 FT W OF NW 84TH AVE	635 FT E OF NW 87TH AVE	001	
	┨────┤				
08 66	┥────┤	3VA HT78 WN	3VA HTT8 WW 10 3 11 265	150	TSONSZNDST
	0.7	10 HISOT MN	NW 104TH CT	011	
76 66	9'72		IS ONZS MN	06	
66		AVA HTAOL WN	NM TOZH CL	08	LSONZSMN
1102 134	PCI_2007	оГ	From	GI noitcel	Branch ID

•

	1				
00T	38.2	3VA 0N28 WN	1S ISTS WN	130	NW82NDAVE
02	22	TS T215 WN	15 H19E MN	750	3VAQN28WN
63	8'#\$	T2 OAEE WN	1S TRE WN	011	AVAQNS8WD
88	<i>L</i> 'ZS	T2 H141 WN	3VA ONS8 WN	100	NW82NDAVE
08	8.95	15 H12T MN	T2 HT4L WN	06	NW82NDAVE
78	5'88	15 H122 WN	15 H15Z MN	08	3VAGN28WN
66		3VA GN28 WN	15 H1ZT MN	02	NW82NDAVE
Z6	6.27	NW 82ND AVE	IS HIZT MN	09	3VAQNS8WN
92	Ľ'69	T2 HT22 WW	T2 HT72 WN	05	
ss	1.17	T2 DAEE WN 10 N 11 ETT	T2 OAEE WN	40	AW82NDAVE
06	9'25	12 H185 WN	15 H195 MN	30	AW82NDAVE
58		15 H157 MN	3VA DVS8 WN	50	3VAONS8WN
<i>LL</i>	6'28	15 H195 MN	T2 HT42 WN	10	3VADAVE NW82NDAVE
62	46.4	15 1515 MM	3VA HTET WN	320	3VAHTetwin
12	4.84	3VA HTET WN	15 H12T MN	340	3VAHTETWN
700		TS HITA WN	T2 HT74 WN to 2 # 885	330	3VAHTETWN
100		3VA HTET WN to N fi est	3VA HTET WN	320	3VAHTETWN
00T	ĽĽ	15 H105 MN JO N 1J 691	15 H105 MN	910	3VAHTETWN
66	72	T2 HT8E WN	T2 HTTE WN	300	эуантегуии
700 7	6.24	15 HIZE MN	3VA HTET WN	067	3VAHTETWN
† 6	22	15 H19E MN	T2 HT8E WW	580	BVAHTETWN
96		12 H16E WN	T2 HT3E WN	022	3VAHTETWN
00T	£'69	T2 T214 WN	T2 HT2E WN	560	эуантегwи
66		3VA HTET WN	JVA HTET WN to 2 ft ETE	520	зуантетwи
100	ĽĽ	1S ONZS MN	T2 T212 WN	540	эуантеүүү
00T	5'79	T2 HT02 WN	T2 HT84 WN	530	зуантегwи
100 T		T2 T212 WN	T2 T212 WN 10 2 A 605	520	эуантетwи
00T		3VA HTET WN	T2 HT45 WW	012	3VAHTETWN
100	5'79	12 H184 WN	T2 HT84 WN	500	зуантегии
66	5'79	T2 HT84 WN	LS HLZ# MN	061	зуантегши
100	£'9L	T2 DAEE WN	15 ONSE WN	780	зуантегши
59	\$°9\$	T2 HT51 WN	LS HLST MN	0/1	эуантегши
29	6°11	T2 HT21 WN	T2 HT41 WN	09T	3VAHTETWN
66	Z'68	TZ QAEZ WN	15 QNZS MN	051	3VAHTETWN
100	611	15 H125 MN	T2 HT32 WN	140	эуантетши
T00	6'7\$	T2 HT4E WN	TZ QAEE WN	130	3VAHTETWN
100	E'92	15 ONZE MN	IS ISTE MN	150	3VAHTeTWN
100	7 'E9	TS HT82 WW	15 HLZS MN	110	3VAHTETWN
100	2.08	TS OREA WN	362 FT N OF NW 4151 ST	100	3VAHTETWN
100	7'58	12 H195 WN	TS HT22 WN	06	3VAHTETWN
00T	Þ '58	15 HISS MN	T2 HT42 WN	08	ЭУАНТЕТШИ
00τ		12 1215 WN	1\$ 1\$1\$ MN	02	3VAHTETWN
00T	5'79	15 H197 MN 30 N 19 09	T2 HT34 WN	09	ЭУАНТЕГШИ
66	£.08	T2 HT34 WW 40 2 T3175	T2 HT34 WN	05	ЭУАНТЕТШИ
66	L'08	15 1514 M 01 M 01 752	T2 T2154 WN	40	BVAHTETWN
00T	5'79	T2 HT25 WN	1S H1SZ MN	30	3VAHTECWN
00T	2.28	T2 HT42 WN	TZ OREZ WN	50	BVAHTETWN
100	611	IS ISTE WN	IS H16Z MN	- OT	BVAHTETWN
ts	737	12 H18E WN	IS HIZE MN	08	BVAHT8YWN
68	98	1S HISS MN	IS H1#S MN	04	AMH187WN
100		Dead End	1S H1/S MN	09	ΞΥΑΗΤ 8Υ₩Ν
	PCI_2007	0 <u>1</u>	From	Section ID	Branch ID
THUC ING	Irone ing	T		In anting	

Branch ID	Section ID	From	То	PCI_2007	PCI_2011
NW82NDAVE	140	547 ft S of NW 37TH ST	NW 37TH ST		63
NW82NDAVE	150	NW 29TH ST	NW 30TH TER	72	75
NW82NDAVE	160	NW 82ND AVE	NW 82ND AVE		89
NW82NDAVE	170	NW 30TH TER	NW 31ST ST	80.2	99
NW82NDAVE	180	NW 82ND AVE	NW 21ST ST	72.9	81
NW82NDAVE	190	NW 37TH ST	NW 36TH ST		91
NW82NDAVE	200	NW 82ND AVE	NW 82ND AVE		100
NW82NDST	10	NW 114TH PATH	NW 117TH AVE		93
NW82NDST	20	NW 112TH AVE	NW 114TH PATH		94
NW82NDST	30	NW 107TH AVE	NW 112TH AVE		98
NW84THAVE	10	NW 27TH ST	NW 29TH ST	68.1	68
NW84THAVE	20	NW 30TH TER	NW 33RD ST	54.5	65
NW84THAVE	30	NW 23RD ST	NW 25TH ST	44.9	93
NW84THAVE	40	NW 84TH AVE	NW 17TH ST	77.7	88
NW84THAVE	50	NW 84TH AVE	NW 53RD ST	79	87
NW84THAVE	60	NW 54TH ST	NW 56TH ST	88.7	100
NW84THAVE	70	NW 17TH ST	NW 19TH ST	84.4	86
NW84THAVE	80	NW 84TH AVE	NW 84TH AVE		88
NW84THAVE	90	NW 84TH AVE	NW 23RD ST	76.3	87
NW84THAVE	100	NW 52ND ST	NW 84TH AVE	79	100
NW84THAVE	110	NW 56TH ST	NW 58TH ST	72.3	97
NW84THAVE	120	NW 19TH ST	NW 84TH AVE		100
NW84THAVE	130	NW 13TH TER	NW 84TH AVE		92
NW84THAVE	140	NW 29TH ST	NW 30TH TER	67.4	68
NW84THAVE	150	NW 27TH ST	Dead End	68.1	72
NW84THAVE	160	NW 12TH ST	NW 13TH TER		91
NW84THAVE	170	NW 53RD ST	NW 53RD TER	77.1	65
NW86THAVE	10	NW 21ST TER	NW 23RD ST	76.3	86
NW86THST	10	NW 110TH PL	NW 111TH CT		80
NW86THST	20	NW 111TH CT	NW 112TH AVE		100
NW86THST	30	NW 109TH AVE	NW 110TH AVE		92
NW86THST	40	NW 108TH AVE	NW 108TH CT		98
NW86THST	50	NW 110TH AVE	NW 110TH PL		83
NW86THST	60	NW 108TH CT	NW 109TH AVE		100
NW86THST	70	NW 107TH AVE	NW 108TH AVE		100
NW87THCT	10	NW 26TH ST	NW 27TH ST	80.2	86
NW88THAVE	10	NW 15TH ST	Dead End	78	93
NW88THAVE	20	NW 13TH TER	NW 15TH ST	75.1	82
NW88THCT	10	NW 18TH TER	NW 20TH ST	76.2	71
NW88THCT	20	NW 20TH ST	NW 21ST TER	90	85
NW88THCT	30	NW 21ST TER	NW 23RD ST	68.7	63
NW89THCT	10	NW 15TH ST	Dead End	45.4	65
NW89THCT	20	NW 33RD ST	NW 35TH LN	100	84
NW89THCT	30	NW 26TH ST	NW 27TH ST	77.9	82
NW89THCT	40	NW 25TH ST	NW 26TH ST	89.2	94
NW89THCT	50	NW 13TH TER	NW 15TH ST	70.3	89
NW89THCT	60	NW 12TH ST	NW 13TH TER	66.8	87
NW89THPL	10	NW 18TH TER	NW 20TH ST	88.4	94
NW89THPL	20	NW 23RD ST	NW 25TH ST	79.8	92
NW89THPL	30	NW 20TH ST	NW 23RD ST	74.5	92
NW89THPL	40	NW 25TH ST	NW 25TH ST	57.7	73

•

Branch ID	Section ID	From	То	PCI_2007	PCI_2011
NW91STAVE	10	NW 33RD ST	Dead End	100	87
NW92NDAVE	10	Dead End	NW 58TH ST		70
NW92NDAVE	20	320 ft S of NW 29TH ST	NW 29TH ST	70.1	100
NW92NDAVE	30	NW 25TH ST	319 ft N of NW 25TH ST		87
NW92NDAVE	40	618 FT S OF NW 29TH ST	319 FT N OF NW 25TH ST		90
NW92NDAVE	50	320 FT S OF NW 29TH ST	618 FT S OF NW 29TH ST		86
NW93RDCT	10	NW 93RD CT	NW 13TH ST	38.3	100
NW93RDCT	20	NW 12TH ST	NW 93RD CT	38.3	100
NW98THAVE	10	NW 28TH TER	Dead End		100
NW98THAVE	20	NW 26TH ST	NW 27TH ST	80.2	100
NW98THAVE	30	NW 27TH TER	NW 28TH TER	93	100
NW98THAVE	40	NW 25TH TER	NW 26TH ST	69.4	100
NW98THAVE	50	NW 27TH ST	NW 27TH TER	83.5	100
NW98THCT	10	NW 14TH ST	NW 17TH ST	88.8	93
NW98THCT	20	NW 12TH ST	NW 14TH ST	88.8	100
NW99THAVE	10	NW 26TH ST	NW 27TH ST	83.1	100
NW99THAVE	20	NW 99TH AVE	NW 60TH ST		62
NW99THAVE	30	NW 27TH TER	NW 28TH TER	56	100
NW99THAVE	40	NW 28TH TER	Dead End		100
NW99THAVE	50	NW 21ST ST	NW 25TH ST	76.1	68
NW99THAVE	60	NW 25TH TER	NW 26TH ST	69.4	100
NW99THAVE	70	NW 27TH ST	NW 27TH TER	73.5	100
NW99THAVE	80	NW 25TH ST	NW 25TH TER	65.7	100
NW99THAVE	90	NW 58TH ST	NW 99TH AVE		88

APPENDIX C

RECOMMENDED PROJECTS





2012 RECOMMENDED PROJECTS FOR CRTICAL PCI METHOD

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2012	NW102NDAVE	200	1-Inch Overlay	84.71	3,656.00	\$5,484.00	3.009
2012	NW104THAVE		Milling & Resurfacing (1-inch)	75.76	11,007.00		6.979
2012	NW112THAVE		Milling & Resurfacing (1-inch)	77.71	5,053.00		5.239
2012	NW112THAVE		1-inch Overlay	80.44	5,500.00		6.989
2012	NW13THTER	_	1-inch Overlay	88.25	6,157.00		3.009
2012	NW13THTER		Milling & Resurfacing (1-inch)	75.32	22,573.00	\$45,146.00	12.249
2012	NW13THTER		Milling & Resurfacing (1-inch)	75.32	15,911.00		12.249
2012	NW14THST		1-inch Overlay	84.24	22,757.00		3.009
2012	NW17THST		1-inch Overlay	82.32	44,154.00		3.009
2012	NW18THTER		1-inch Overlay	90.22	41,619.00	\$83,238.00	3.007
2012	NW18THTER		1-inch Overlay	89.23	14,976.00	\$29,952.00	3.009
2012	NW21STST		Milling & Resurfacing (1-inch)	57.67	20,351.00	\$40,702.00	3.00
2012	NW21STST		Milling & Resurfacing (1-inch)	47.84	26,289.00	\$52,578.00	120.969
2012	NW24THTER		1-inch Overlay	82.52	21,529.00		3.009
2012	NW26THST	_	1-inch Overlay	86.17	12,994.00		3.009
2012				77.71			
	NW27THST	_	Milling & Resurfacing (1-inch)		33,710.00		5.239
2012	NW29THST		Milling & Resurfacing (1-inch)	76.87	39,410.00	\$78,819.00	3.789
2012	NW29THST		1-inch Overlay	85.2	17,267.00		3.005
2012	NW29THST		1-inch Overlay	86.31	21,023.00	\$31,535.00	3.00
2012	NW29THST		Milling & Resurfacing (1-inch)	79.51	18,984.00	\$37,969.00	7.53
2012	NW30THTER		Milling & Resurfacing (1-inch)	77.71	17,664.00	\$28,519.00	5.23
2012	NW31STST		1-inch Overlay	90.12	29,029.00		3.00
2012	NW33RDST		1-inch Overlay	80.49	21,187.00		8.49
2012	NW33RDST	180		83.69	39,797.00		3.00
2012	NW37THST		Milling & Resurfacing (1-inch)	48.93	13,206.00	\$26,413.00	87.82
2012	NW37THST		Milling & Resurfacing (1-inch)	46.76	5,597.00		153.64
2012	NW38THST	10	Milling & Resurfacing (1-inch)	31.62	13,274.00	\$26,548.00	16.01
2012	NW40THST		Milling & Resurfacing (1-inch)	72.19	10,592.00	\$20,024.00	8.97
2012	NW50THST	10	1-inch Overlay	80.44	26,440.00	\$39,660.00	6.98
2012	NW52NDST	70	Milling & Resurfacing (1-inch)	72.19	10,753.00	\$20,328.00	8.97
2012	NW52NDST	150	Milling & Resurfacing (1-inch)	72.19	13,431.00	\$25,390.00	8.97
2012	NW52NDST	160	1-inch Overlay	88.54	6,883.00	\$10,325.00	3.00
2012	NW52NDST	210	1-inch Overlay	82.65	24,122.00	\$36,183.00	3.00
2012	NW52NDST	230	Milling & Resurfacing (1-inch)	73.35	6,039.00	\$11,066.00	11.63
2012	NW52NDTER	20	1-inch Overlay	80.44	26,968.00	\$40,452.00	6.98
2012	NW53RD5T	20	Milling & Resurfacing (1-inch)	72.19	13,540.00	\$25,598.00	8.97
2012	NW53RDST	100	Milling & Resurfacing (1-inch)	76.87	11,401.00	\$18,885.00	3.78
2012	NW53RDST	130	1-inch Overlay	85.2	4,967.00	\$7,450.00	3.00
2012	NW53RDTER	10	1-inch Overlay	82.32	24,809.00	\$37,213.00	3.00
2012	NW54THST	50	Milling & Resurfacing (1-inch)	71.04	26,276.00	\$51,186.00	5.75
2012	NW56THST		1-inch Overlay	83.28	29,212.00		3.00
2012	NW56THST		Milling & Resurfacing (1-Inch)	73.35	28,912.00	\$52,981.00	11.63
2012	NW56THST		1-inch Overlay	84.24	14,634.00		3.00
2012	NW77THCT		Milling & Resurfacing (1-inch)	74.53	6,953.00		9.68
2012	NW77THCT		Milling & Resurfacing (1-inch)	69.89	19,197.00	\$38,395.00	3.00
2012	NW78THAVE		1-inch Overlay	83.28	7,199.00		3.00
2012	NW78THAVE		Milling & Resurfacing (1-inch)	66.32	59,595.00		3.00
2012	NW82NDAVE		Milling & Resurfacing (1-inch)	76.87	15,939.00		3.78
2012	NW84THAVE		Milling & Resurfacing (1-inch)	63.19			3.78
					32,681.00		
2012	NW88THAVE		1-inch Overlay	81.6	18,985.00		3.00
2012	NW88THCT		Milling & Resurfacing (1-inch)	60.76	13,466.00		3.00
2012	NW89THCT	_	1-inch Overlay	88.25	18,990.00	\$37,979.00	3.00
2012	NW89THCT	60		86.31	15,375.00	\$30,750.00	3.00
2012	NW89THPL	20		91.21	18,244.00	\$36,489.00	3.00
2012	NW89THPL	40	Milling & Resurfacing (1-inch)	71.89	2,043.00	\$4,086.00	8.11

2013 RECOMMENDED PROJECTS FOR CRTICAL PCI METHOD

Year	Street Name	SectionID	Recommended Work	PCI	Area(SF)	Cost	Delay Penalty
2013	NW100THAVE	30	Milling & Resurfacing (1-inch)	63.33	4,729.00	\$9,743.00	3.00%
2013	NW102NDAVE	70	Milling & Resurfacing (1-inch)	64.59	12,161.00	\$25,051.00	3.00%
2013	NW102NDAVE	110	Milling & Resurfacing (1-inch)	60.09	6,111.00	\$12,588.00	3.00%
2013	NW102NDAVE	140	Milling & Resurfacing (1-inch)	68.44	2,345.00	\$4,831.00	3.00%
2013	NW102NDAVE	150	Milling & Resurfacing (1-inch)	68.44	5,159.00	\$10,627.00	3.00%
2013	NW102NDAVE	210	1-inch Overlay	86.33	22,270.00	\$34,407.00	3.00%
2013	NW104THAVE	30	Milling & Resurfacing (1-inch)	65.02	6,721.00	\$13,845.00	3.00%
2013	NW108THAVE	20	1-inch Overlay	85.02	19,232.00	\$29,713.00	3.00%
2013	NW112THAVE	210	Milling & Resurfacing (1-inch)	66.7	4,807.00	\$9,902.00	3.00%
2013	NW114THAVE	120	Milling & Resurfacing (1-inch)	63.36	15,358.00	\$31,638.00	3.00%
2013	NW114THAVE	150	Milling & Resurfacing (1-inch)	63.36	8,365.00	\$17,231.00	3.00%
2013	NW114THAVE	310	Milling & Resurfacing (1-inch)	61.74	11,948.00	\$24,614.00	3.00%
2013	NW17THST	20	Milling & Resurfacing (1-inch)	51.93	19,727.00	\$40,637.00	3.00%
2013	NW20THST	10	Milling & Resurfacing (1-inch)	62.22	28,721.00	\$59,165.00	3.00%
2013	NW30THTER	10	Milling & Resurfacing (1-inch)	65.02	40,305.00	\$83,028.00	3.00%
2013	NW31STTER	20	Milling & Resurfacing (1-inch)	57.93	4,345.00	\$8,951.00	3.00%
2013	NW33RDST	110	Milling & Resurfacing (1-inch)	68.46	40,026.00	\$82,453.00	3.00%
2013	NW52NDST	20	1-inch Overlay	88.76	21,745.00	\$33,596.00	3.00%
2013	NW52NDST	130	Milling & Resurfacing (1-inch)	57.93	2,335.00	\$4,811.00	3.00%
2013	NW52NDST	170	Milling & Resurfacing (1-inch)	68.61	6,944.00	\$14,305.00	3.00%
2013	NW52NDTER	10	Milling & Resurfacing (1-inch)	57.93	3,248.00	\$6,690.00	3.00%
2013	NW54THST	20	1-inch Overlay	86.27	13,355.00	\$20,634.00	3.00%
2013	NW55THST	20	1-inch Overlay	85.35	13,244.00	\$20,462.00	3.00%
2013	NW79THAVE	340	Milling & Resurfacing (1-inch)	65.02	22,395.00	\$46,133.00	3.00%
2013	NW82NDAVE	120	Milling & Resurfacing (1-inch)	62.26	21,628.00	\$44,553.00	3.00%
2013	NW82NDAVE	150	Milling & Resurfacing (1-inch)	69.95	10,160.00	\$20,929.00	3.00%
2013	NW84THAVE	80	1-inch Overlay	84.45	8,045.00	\$12,430.00	3.00%
2013	NW84THAVE	100	Milling & Resurfacing (1-inch)	57.93	2,879.00	\$5,931.00	3.00%
2013	NW84THAVE	150	Milling & Resurfacing (1-inch)	66.72	14,818.00	\$30,525.00	3.00%
2013	NW88THCT	10	Milling & Resurfacing (1-inch)	63.8	20,285.00	\$41,787.00	3.00%
2013	NW92NDAVE	10	Milling & Resurfacing (1-inch)	63.34	18,868.00	\$38,868.00	3.00%

2014 RECOMMENDED PROJECTS FOR CRTICAL PCI METHOD

Year	Street Name	SectionID	Recommended Work	PCI	Area(SF)	Cost	Delay Penalty
2014	NW100THAVE	20	Milling & Resurfacing (1-inch)	51.24	4,741.00	\$10,059.00	16.91%
2014	NW102NDAVE	160	Milling & Resurfacing (1-inch)	65.57	5,822.00	\$12,353.00	3.00%
2014	NW114THAVE	20	Milling & Resurfacing (1-inch)	45	8,926.00	\$18,939.00	205.78%
2014	NW114THAVE	30	Milling & Resurfacing (1-inch)	45	12,018.00	\$25,501.00	205.78%
2014	NW114THAVE	40	Milling & Resurfacing (1-inch)	45	11,430.00	\$24,253.00	205.78%
2014	NW114THAVE	140	Milling & Resurfacing (1-inch)	45	14,879.00	\$31,569.00	205.78%
2014	NW114THAVE	240	Milling & Resurfacing (1-inch)	45	8,832.00	\$18,739.00	205.78%
2014	NW114THAVE	300	Milling & Resurfacing (1-inch)	51.3	18,548.00	\$39,355.00	15.05%
2014	NW15THST	30	Milling & Resurfacing (1-inch)	67.54	16,374.00	\$34,741.00	3.00%
2014	NW23RDST	10	Milling & Resurfacing (1-inch)	67.54	28,622.00	\$60,730.00	3.00%
2014	NW2STHTER	10	Milling & Resurfacing (1-inch)	51.24	6,612.00	\$14,030.00	16.91%
2014	NW33RDST	20	Milling & Resurfacing (1-inch)	68.54	18,676.00	\$39,626.00	3.00%
2014	NW33RDST	70	Milling & Resurfacing (1-inch)	47.06	14,418.00	\$30,593.00	143.67%
2014	NW33RDST	90	Milling & Resurfacing (1-inch)	49.15	12,641.00	\$26,822.00	80.17%
2014	NW38THST	20	Milling & Resurfacing (1-inch)	47.06	20,628.00	\$43,769.00	143.67%
2014	NW53RDST	140	Milling & Resurfacing (1-inch)	47.02	8,355.00	\$17,728.00	144.60%
2014	NWS4THST	40	Milling & Resurfacing (1-inch)	49.13	26,373.00	\$55,957.00	81.10%
2014	NW77THCT	20	Milling & Resurfacing (1-inch)	42.92	6,624.00	\$14,054.00	234.75%
2014	NW77THCT	30	Milling & Resurfacing (1-inch)	47.02	6,911.00	\$14,665.00	144.60%
2014	NW79THAVE	170	Milling & Resurfacing (1-inch)	45	19,520.00	\$41,417.00	205.78%
2014	NW82NDAVE	50	Milling & Resurfacing (1-inch)	66.64	24,586.00	\$52,166.00	3.00%
2014	NW82NDAVE	140	Milling & Resurfacing (1-inch)	46.39	16,424.00	\$34,848.00	65.34%
2014	NW84THAVE	10	Milling & Resurfacing (1-inch)	51.3	18,117.00	\$38,441.00	15.05%
2014	NW84THAVE	140	Milling & Resurfacing (1-inch)	51.3	10,472.00	\$22,219.00	15.05%
2014	NW84THAVE	170	Milling & Resurfacing (1-inch)	44.96	13,371.00	\$28,371.00	206.94%
2014	NW99THAVE	50	Milling & Resurfacing (1-inch)	49.37	37,184.00	\$78,896.00	83.42%

2015 2016 RECOMMENDED PROJECTS FOR CRTICAL PCI METHOD

Year	Street Name	SectionID	Recommended Work	PCI	Area(SF)	Cost	Delay Penalty
2015	NW102NDAVE	190	Milling & Resurfacing (1-inch)	65.15	14,723.00	\$32,176.00	3.00
2015	NW109THAVE	70	Milling & Resurfacing (1-inch)	68.3	31,548.00	\$68,946.00	3.00
2015	NW114THAVE	10	Reconstruction (8" Base, 2" AC)	16.04	4,168.00	\$29,607.00	3.00
2015	NW114THAVE	160	Milling & Resurfacing (1-inch)	68.31	12,432.00	\$27,169.00	3.0
2015	NW114THAVE	230	Reconstruction (8" Base, 2" AC)	28.62	11,702.00	\$83,114.00	3.00
2015	NW21STTER	20	Milling & Resurfacing (1-inch)	69.37	20,026.00	\$43,765.00	3.0
2015	NW40THST	10	Reconstruction (8" Base, 2" AC)	28.62	15,327.00	\$108,865.00	3.0
2015	NW50THST	60	Reconstruction (8" Base, 2" AC)	28.57	21,930.00	\$155,760.00	3.0
2015	NW56THST	30	Reconstruction (8" Base, 2" AC)	28.57	29,143.00	\$206,996.00	3.0
2015	NW82NDAVE	90	Milling & Resurfacing (1-inch)	69.73	34,473.00	\$75,338.00	3.0
2016	NW102NDAVE	240	Milling & Resurfacing (1-inch)	57.94	24,098.00	\$54,244.00	3.0
2016	NW114THAVE	220	Milling & Resurfacing (1-inch)	57.94	2,851.00	\$6,419.00	3.0
2016	NW117THAVE	40	Reconstruction (8" Base, 2" AC)	6.93	54,821.00	\$401,058.00	3.0
2016	NW66THST	10	Milling & Resurfacing (1-inch)	57.94	31,157.00	\$70,135.00	3.0
2016	NW82NDAVE	40	Reconstruction (8" Base, 2" AC)	13.86	23,366.00	\$170,943.00	3.0
2016	NW82NDAVE	180	Milling & Resurfacing (1-inch)	67.62	22,529.00	\$50,713.00	3.0
2016	NW89THCT	10	Reconstruction (8" Base, 2" AC)	10.17	6,549.00	\$47,908.00	3.0
			· · · · · · · · · · · · · · · · · · ·	·		<u></u>	

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2012	NW100THAVE	20	Milling & Resurfacing (1-inch)	65.94	4,741.00	\$9,481.00	3.00%
2/1 <u>6/2012</u>	NW100THAVE	30	Milling & Resurfacing (1-inch)	68.28	4,729.00	\$9,459.00	3.009
2/16/2012	NW102NDAVE	70	Milling & Resurfacing (1-inch)	69.21	12,161.00	\$24,322.00	3.009
2/16/2012	NW102NDAVE	110	Milling & Resurfacing (1-inch)	65.94	6,111.00	\$12,222.00	3.009
2/16/2012	NW102NDAVE	130	Milling & Resurfacing (1-inch)	53.34	5,818.00	\$11,636.00	3.00%
2/16/2012	NW104THAVE	30	Milling & Resurfacing (1-inch)	69.48	6,721.00	\$13,441.00	3.00%
2/16/2012	NW104THAVE	50	Milling & Resurfacing (1-inch)	68.93	23,394.00	\$46,788.00	3.00%
2/16/2012	NW112THAVE	210	Milling & Resurfacing (1-inch)	70.67	4,807.00	\$9,453.00	4.75%
2/16/2012	NW114THAVE	10	Milling & Resurfacing (1-inch)	55.66	4,168.00	\$8,337.00	3.00%
2/16/2012	NW114THAVE	20	Milling & Resurfacing (1-inch)	62.5	8,926.00	\$17,852.00	3.00%
2/16/2012	NW114THAVE	30	Milling & Resurfacing (1-inch)	62.5	12,018.00	\$24,037.00	3.00%
2/16/2012	NW114THAVE	40	Milling & Resurfacing (1-inch)	62.5	11,430.00	\$22,861.00	3.00%
2/16/2012	NW114THAVE	120	Milling & Resurfacing (1-inch)	68.3	15,358.00	\$30,716.00	3.00%
2/16/2012	NW114THAVE	140	Milling & Resurfacing (1-inch)	62.5	14,879.00	\$29,757.00	3.00%
2/16/2012	NW114THAVE	150	Milling & Resurfacing (1-inch)	68.3	8,365.00	\$16,729.00	3.00%
2/16/2012	NW114THAVE	210	Milling & Resurfacing (1-inch)	60.21	13,833.00	\$27,666.00	3.00%
2/16/2012	NW114THAVE	230	Milling & Resurfacing (1-inch)	61.35	11,702.00	\$23,403.00	3.00%
2/16/2012	NW114THAVE	240	Milling & Resurfacing (1-inch)	62.5	8,832.00	\$17,663.00	3.00%
2/16/2012	NW114THAVE	300	Milling & Resurfacing (1-inch)	65.97	18,548.00	\$37,096.00	3.009
2/16/2012	NW114THAVE	310	Milling & Resurfacing (1-inch)	67.13	11,948.00	\$23,897.00	3.009
2/16/2012	NW117THAVE	20	Milling & Resurfacing (1-inch)	60.19	38,184.00	\$76,368.00	3.009
2/16/2012	NW117THAVE	40	Milling & Resurfacing (1-inch)	60.17	54,821.00	\$109,641.00	3.009
2/16/2012	NW117THAVE	50	Milling & Resurfacing (1-inch)	68.92	71,040.00	\$142,080.00	3.009
2/16/2012	NW15THST	10	Milling & Resurfacing (1-inch)	60.21	12,619.00	\$25,237.00	3.009
2/16/2012	NW20THST	10	Milling & Resurfacing (1-inch)	67.96	28,721.00	\$57,442.00	3.009
2/16/2012	NW21STST	30	Milling & Resurfacing (1-inch)	56.79	20,351.00	\$40,702.00	3.009
2/16/2012	NW21STST	50	Milling & Resurfacing (1-inch)	46.66	26,289.00	\$52,578.00	156.65%
2/16/2012	NW2STHTER	10	Milling & Resurfacing (1-inch)	65.94	6,612.00	\$13,225.00	3.009
2/16/2012	NW33RDST	70	Milling & Resurfacing (1-inch)	63.65	14,418.00	\$28,837.00	3.009
2/16/2012	NW33RDST	90	Milling & Resurfacing (1-inch)	64.81	12,641.00	\$25,282.00	3.009
2/16/2012	NW37THST	10	Milling & Resurfacing (1-inch)	47.78	13,206.00	\$26,413.00	122.819
2/16/2012	NW37THST	20	Milling & Resurfacing (1-inch)	45.54	5,597.00	\$11,193.00	190.499
2/16/2012	NW38THST	10	Reconstruction (8" Base, 2" AC)	29.99	13,274.00	\$86,280.00	3.009
2/16/2012	NW38THST	20	Milling & Resurfacing (1-inch)	63.65	20,628.00	\$41,257.00	3.009
2/16/2012	NW40THST	10	Milling & Resurfacing (1-inch)	61.35	15,327.00	\$30,654.00	3.009
2/16/2012	NW41STST	10	Reconstruction (8" Base, 2" AC)	5.77	7,748.00	\$50,363.00	3.009
2/16/2012	NW41STST	20	Milling & Resurfacing (1-inch)	51.12	21,852.00	\$43,704.00	21.319
2/16/2012	NW41STST	40	Milling & Resurfacing (1-inch)	60.19	23,840.00	\$47,679.00	3.009
2/16/2012	NW41STST	80	Milling & Resurfacing (1-inch)	39.93	33,950.00	\$68,970.00	229.569

2012 RECOMMENDED PROJECTS FOR MINIMUM PCI METHOD

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2012	NWSOTHST	60	Milling & Resurfacing (1-inch)	61.33	21,930.00	\$43,859.00	3.00%
2/16/2012	NW53RDST	140	Milling & Resurfacing (1-inch)	63.63	8,355.00	\$16,710.00	3.00%
2/16/2012	NW54THST	10	Milling & Resurfacing (1-inch)	54.5	26,495.00	\$52,990.00	3.00%
2/16/2012	NW54THST	40	Milling & Resurfacing (1-inch)	64.79	26,373.00	\$52,745.00	3.00%
2/16/2012	NW54THST	50	Milling & Resurfacing (1-inch)	70.67	26,276.00	\$51,672.00	4.75%
2/16/2012	NW56THST	30	Milling & Resurfacing (1-inch)	61.33	29,143.00	\$58,286.00	3.00%
2/16/2012	NW77THCT	10	Milling & Resurfacing (1-inch)	59.04	6,416.00	\$12,833.00	3.00%
2/16/2012	NW77THCT	20	Milling & Resurfacing (1-inch)	61.33	6,624.00	\$13,247.00	3.00%
2/16/2012	NW77THCT	30	Milling & Resurfacing (1-inch)	63.63	6,911.00	\$13,823.00	3.00%
2/16/2012	NW77THCT	50	Milling & Resurfacing (1-inch)	69.46	19,197.00	\$38,395.00	3.00%
2/16/2012	NW78THAVE	30	Milling & Resurfacing (1-inch)	65.68	59,595.00	\$119,189.00	3.00%
2/16/2012	NW82NDAVE	40	Milling & Resurfacing (1-inch)	52.01	23,366.00	\$46,733.00	3.00%
2/16/2012	NW82NDAVE	120	Milling & Resurfacing (1-inch)	67.99	21,628.00	\$43,256.00	3.00%
2/16/2012	NW82NDAVE	140	Milling & Resurfacing (1-inch)	60.56	16,424.00	\$32,847.00	3.00%
2/16/2012	NW84THAVE	10	Milling & Resurfacing (1-inch)	65.97	18,117.00	\$36,235.00	3.00%
2/16/2012	NW84THAVE	20	Milling & Resurfacing (1-inch)	62.5	32,681.00	\$65,362.00	3.00%
2/16/2012	NW84THAVE	140	Milling & Resurfacing (1-inch)	65.97	10,472.00	\$20,944.00	3.00%
2/16/2012	NW84THAVE	150	Milling & Resurfacing (1-inch)	70.68	14,818.00	\$29,132.00	4.78%
2/16/2012	NW84THAVE	170	Milling & Resurfacing (1-inch)	62.48	13,371.00	\$26,742.00	
2/16/2012	NW88THCT	10	Milling & Resurfacing (1-inch)	69.12	20,285.00	\$40,570.00	
2/16/2012	NW88THCT	30	Milling & Resurfacing (1-inch)	59.93	13,466.00	\$26,932.00	3.00%
2/16/2012	<u>NW89THCT</u>	10	Milling & Resurfacing (1-inch)	62.21	6,549.00	\$13,097.00	3.00%
2/16/2012	NW92NDAVE	10	Milling & Resurfacing (1-inch)	68.29	18,868.00	\$37,736.00	3.00%
2/16/2012	NW99THAVE	20	Milling & Resurfacing (1-inch)	59.07	19,968.00	\$39,935.00	3.00%
2/16/2012	NW99THAVE	50	Milling & Resurfacing (1-inch)	65.65	37,184.00	\$74,367.00	3.00%

.

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2013	NW100THAVE	60	Milling & Resurfacing (1-inch)	77.47	4,571.00	\$7,658.00	4.87%
2/16/2013	NW102NDAVE	140	Milling & Resurfacing (1-inch)	67.95	2,345.00	\$4,831.00	3.00%
	NW102NDAVE	150	Milling & Resurfacing (1-inch)	67.95	5,159.00	\$10,627.00	3.00%
2/16/2013	NW102NDAVE	160	Milling & Resurfacing (1-inch)	69.86	5,822.00	\$11,993.00	3.00%
2/16/2013	NW102NDAVE	190	Milling & Resurfacing (1-inch)	73.74	14,723.00	\$27,493.00	13.629
2/16/2013	NW102NDPL	10	Milling & Resurfacing (1-inch)	79.39	36,692.00	\$57,842.00	7.37%
2/16/2013	NW104THAVE	10	Milling & Resurfacing (1-inch)	74.25	11,007.00	\$20,265.00	10.179
2/16/2013	NW104THAVE	20	1-inch Overlay	80.12	25,518.00	\$39,425.00	7.779
2/16/2013	NW109THAVE	10	1-inch Overlay	80.12	27,237.00	\$42,081.00	7.779
	NW109THAVE	70	Milling & Resurfacing (1-inch)	74.25	31,548.00		10.179
2/16/2013	NW109THAVE		1-inch Overlay	80.51	3,144.00	\$4,857.00	6.789
2/16/2013	NW110THAVE	10	1-inch Overlay	81.66	4,539.00	\$7,012.00	3.769
2/16/2013	NW110THAVE	20	1-inch Overlay	80.51	11,860.00	\$18,324.00	6.789
2/16/2013	NW110THPL	1	1-inch Overlay	80.51	10,700.00	\$16,532.00	6.789
	NW111THCT	5	1-inch Overlay	80.51	9,860.00		6.789
	NW112THAVE	60	Milling & Resurfacing (1-inch)	79.39	7,981.00	\$12,582.00	7.379
2/16/2013	NW112THAVE	70	Milling & Resurfacing (1-inch)	76.96	5,053.00	\$8,598.00	3.979
	NW112THAVE	100	Milling & Resurfacing (1-inch)	78.7	5,500.00	\$8,865.00	6.559
2/16/2013	NW112THAVE	140	1-inch Overlay	80.12	4,737.00	\$7,319.00	7.779
	NW112THAVE	270	Milling & Resurfacing (1-inch)	76.61	9,151.00		3.129
2/16/2013	NW112THPL	1	Milling & Resurfacing (1-inch)	75.62	5,502.00	\$9,742.00	11.999
	NW113THPL	1	1-inch Overlay	80.51	8,120.00		6.789
2/16/2013	NW114THAVE	160	Milling & Resurfacing (1-inch)	74.25	12,432.00	\$22,889.00	10.155
2/16/2013	NW114THAVE		1-inch Overlay	80.13	6,659.00	\$10,288.00	7.779
2/16/2013	NW114THAVE	180	Milling & Resurfacing (1-inch)	79.4	11,210.00	\$17,665.00	7.419
2/16/2013	NW114THAVE	220	Milling & Resurfacing (1-inch)	77.03	2,851.00	\$4,842.00	4.099
2/16/2013	NW114THAVE	280	Milling & Resurfacing (1-inch)	77.47	15,298.00	\$25,629.00	4.879
2/16/2013	NW117THAVE	30	1-inch Overlay	80.88	15,095.00	\$23,321.00	5.829
2/16/2013	NW13THTER		Milling & Resurfacing (1-inch)	71.81	22,573.00	\$44,397.00	7.889
	NW13THTER	30	Milling & Resurfacing (1-inch)	71.81	15,911.00		7.889
	NW14THST		1-inch Overlay	81.67	22,757.00		3.729
2/16/2013	NW14THST	30	1-inch Overlay	80.89	46,443.00		5.829
	NW15THST		Milling & Resurfacing (1-inch)	71.81			7.885
	NW17THST	1	Milling & Resurfacing (1-inch)	76.02			6.185
	NW17THST		1-inch Overlay	80.12			7.775

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2013	NW21STST	20	1-inch Overlay	80.87	11,758.00	\$18,166.00	5.85%
2/16/2013	NW21STST	80	Milling & Resurfacing (1-inch)	79.39	13,694.00	\$21,587.00	7.37%
2/16/2013	NW21STST	90	Milling & Resurfacing (1-inch)	79.39	25,148.00	\$39,643.00	7.37%
2/16/2013	NW21STTER	10	Milling & Resurfacing (1-inch)	78.05	9,381.00	\$15,435.00	5.71%
2/16/2013	NW23RDST	10	Milling & Resurfacing (1-inch)	71.81	28,622.00	\$56,293.00	7.88%
2/16/2013	NW24THTER	10	1-inch Overlay	81.04	21,529.00	\$33,263.00	3.00%
2/16/2013	NW26THST	30	1-inch Overlay	80.87	12,944.00	\$19,999.00	5.85%
2/16/2013	NW26THST	40	1-inch Overlay	81.66	13,036.00	\$20,141.00	3.76%
2/16/2013	NW27THST	120	1-inch Overlay	80.12	12,988.00	\$20,066.00	7.77%
2/16/2013	NW29THST	20	Milling & Resurfacing (1-inch)	76.61	39,410.00	\$67,769.00	
2/16/2013	NW29THST	90	Milling & Resurfacing (1-inch)	78.05	18,984.00	\$31,237.00	5.71%
2/16/2013	NW33RDST	10	Milling & Resurfacing (1-inch)	78.15	21,187.00	\$34,753.00	12.12%
2/16/2013	NW33RDST	20	Milling & Resurfacing (1-inch)	71.92	18,676.00	\$36,625.00	8.19%
2/16/2013	NW33RDST	60	1-inch Overlay	80.13	13,917.00	\$21,502.00	7.77%
2/16/2013	NW33RDST	110	Milling & Resurfacing (1-inch)	67.98	40,026.00	\$82,453.00	3.00%
2/16/2013	NW35THLN	10	Milling & Resurfacing (1-inch)	77.47	41,860.00	\$70,128.00	4.87%
2/16/2013	NW40THST	20	Milling & Resurfacing (1-inch)	67.98	10,592.00	\$21,820.00	3.00%
2/16/2013	NW50THST	10	Milling & Resurfacing (1-inch)	78.7	26,440.00	\$42,620.00	6.55%
2/16/2013	NW52NDST	70	Milling & Resurfacing (1-inch)	67.97	10,753.00	\$22,151.00	3.00%
2/16/2013	NW52NDST	120	Milling & Resurfacing (1-inch)	78.06	6,444.00	\$10,601.00	5.74%
2/16/2013	NW52NDST	130	Milling & Resurfacing (1-inch)	76.57	2,335.00	\$4,021.00	3.34%
2/16/2013	NW52NDST	150	Milling & Resurfacing (1-inch)	67.97	13,431.00	\$27,667.00	3.00%
2/16/2013	NW52NDST	170	Milling & Resurfacing (1-inch)	68.1	6,944.00	\$14,305.00	3.00%
2/16/2013	NW52NDST	210	1-inch Overlay	81.09	24,122.00	\$37,268.00	5.71%
2/16/2013	NW52NDST	230	Milling & Resurfacing (1-inch)	69.87	6,039.00	\$12,440.00	3.00%
2/16/2013	NW52NDTER	10	Milling & Resurfacing (1-inch)	76.57	3,248.00	\$5,591.00	3.34%
2/16/2013	NW52NDTER	20	Milling & Resurfacing (1-inch)	78.7	26,968.00	\$43,471.00	6.55%
2/16/2013	NW53RDST	20	Milling & Resurfacing (1-inch)	67.97	13,540.00	\$27,893.00	3.00%
2/16/2013	NW53RDST	100	Milling & Resurfacing (1-inch)	76.61	11,401.00	\$19,604.00	3.12%
2/16/2013	NW53RDST	120	Milling & Resurfacing (1-inch)	79.39	4,295.00	\$6,771.00	7.37%
2/16/2013	NW53RDTER	10	1-inch Overlay	80.12	24,809.00	\$38,329.00	7.77%
2/16/2013	NW56THST	10	1-inch Overlay	80.88	29,212.00	\$45,132.00	5.82%
2/16/2013	NW56THST	20	Milling & Resurfacing (1-inch)	69.87	28,912.00	\$59,559.00	3.00%
2/16/2013	NW56THST	40	1-inch Overlay	81.67	14,634.00	\$22,610.00	3.72%
2/16/2013	NW66THST	10	Milling & Resurfacing (1-inch)	77.03	18,336.00	\$31,134.00	4.09%
2/16/2013	NW77THCT	40	Milling & Resurfacing (1-inch)	71.91	6,953.00	\$13,640.00	8.17%
2/16/2013	NW78THAVE	10	1-inch Overlay	80.88	7,199.00	\$11,122.00	5.829
2/16/2013	NW82NDAVE	10	Milling & Resurfacing (1-inch)	76.61	15,939.00	\$27,409.00	3.129
2/16/2013	NW82NDAVE	50	Milling & Resurfacing (1-inch)	70.89	24,586.00	\$49,519.00	5.34%
2/16/2013	NW82NDAVE	80	Milling & Resurfacing (1-inch)	79.65	16,777.00	\$26,223.00	10.97%

.

2013 RECOMMENDED PROJECTS FOR MINIMUM PCI METHOD

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2013	NW82NDAVE	90	Milling & Resurfacing (1-inch)	76.68	34,473.00	\$59,155.00	13.08%
2/16/2013	NW82NDAVE	150	Milling & Resurfacing (1-inch)	69.49	10,160.00	\$20,929.00	3.00%
2/16/2013	NW82NDAVE	180	Milling & Resurfacing (1-inch)	78.17	22,529.00	\$36,931.00	12.13%
2/16/2013	NW84THAVE	100	Milling & Resurfacing (1-inch)	76.57	2,879.00	\$4,957.00	3.34%
2/16/2013	NW84THST	3	1-inch Overlay	80.51	5,340.00	\$8,250.00	6.78%
2/16/2013	NW86THST	10	Milling & Resurfacing (1-inch)	78.06	8,102.00	\$13,328.00	5.74%
2/16/2013	NW86THST	50	1-inch Overlay	80.12	8,196.00	\$12,663.00	7.77%
2/16/2013	NW88THAVE	20	1-inch Overlay	80.41	18,985.00	\$29,332.00	3.89%
2/16/2013	NW88THST	1	1-inch Overlay	80.02	26,520.00	\$40,973.00	8.01%
2/16/2013	NW89THCT	20	1-inch Overlay	80.89	20,993.00	\$32,434.00	5.82%
2/16/2013	NW89THCT	30	Milling & Resurfacing (1-inch)	79.39	16,602.00	\$26,171.00	7.37%
2/16/2013	NW89THPL	40	Milling & Resurfacing (1-inch)	66.44	2,043.00	\$4,208.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2014	NW100THAVE	10	1-inch Overlay	86.04	5,347.00	\$8,509.00	3.00%
2/16/2014	NW100THAVE	50	1-inch Overlay	84.24	19,681.00	\$31,319.00	3.00%
2/16/2014	NW102NDAVE	200	1-inch Overlay	82.44	3,656.00	\$5,818.00	3.00%
2/16/2014	NW102NDAVE	210	1-inch Overlay	85.16	22,270.00	\$35,439.00	3.00%
2/16/2014	NW104THCT	10	1-inch Overlay	85.98	19,376.00	\$30,834.00	3.00%
2/16/2014	NW105THAVE	10	1-inch Overlay	85.12	12,582.00	\$20,022.00	3.00%
2/16/2014	NW108THAVE	20	1-inch Overlay	82.94	19,232.00	\$30,605.00	3.00%
2/16/2014	NW109THAVE	20	1-inch Overlay	86.05	28,153.00	\$44,802.00	3.00%
2/16/2014	NW109THAVE	180	1-inch Overlay	80.46	4,320.00	\$6,875.00	6.91%
2/16/2014	NW109THAVE	190	1-inch Overlay	80.46	8,100.00	\$12,890.00	6.91%
2/16/2014	NW109THAVE	200	1-inch Overlay	80.46	5,136.00	\$8,173.00	6.91%
2/16/2014	NW109THAVE	220	1-inch Overlay	80.46	5,232.00	\$8,326.00	6.91%
2/16/2014	NW109THAVE	230	1-inch Overlay	80.46	2,928.00	\$4,659.00	6.91%
2/16/2014	NW112THAVE	10	1-inch Overlay	84.24	9,072.00	\$14,437.00	3.00%
2/16/2014	NW112THAVE	40	1-inch Overlay	84.24	5,747.00	\$9,145.00	3.00%
2/16/2014	NW112THAVE	120	1-inch Overlay	86.05	17,936.00	\$28,542.00	3.00%
2/16/2014	NW112THAVE	220	1-inch Overlay	86.05	5,140.00	\$8,180.00	3.00%
2/16/2014	NW112THAVE	240	1-inch Overlay	84.24	13,439.00	\$21,387.00	3.00%
2/16/2014	NW114THAVE	90	1-inch Overlay	85.13	18,876.00	\$30,039.00	3.00%
2/16/2014	NW114THAVE	100	1-inch Overlay	81.85	8,903.00	\$14,168.00	3.24%
2/16/2014	NW114THAVE	260	1-inch Overlay	86.05	6,588.00	\$10,484.00	3.00%
2/16/2014	NW13THTER	10	1-inch Overlay	83.64	6,157.00	\$9,798.00	3.00%
2/16/2014	NW17THST	10	1-inch Overlay	85.11	28,781.00	\$45,801.00	3.00%
2/16/2014	NW17THST	40	1-inch Overlay	83.41	23,476.00	\$37,359.00	3.00%
2/16/2014	NW18THTER	10	1-inch Overlay	85.16	41,619.00	\$66,231.00	3.00%
2/16/2014	NW18THTER	20	1-inch Overlay	84.37	14,976.00	\$23,832.00	3.00%
2/16/2014	NW21STST	10	1-inch Overlay	81.12	16,212.00	\$25,799.00	5.20%
2/16/2014	NW21STST	70	1-inch Overlay	80.43	5,772.00	\$9,185.00	6.98%
2/16/2014	NW21STST	100	1-inch Overlay	81.68	5,222.00	\$8,310.00	3.00%
2/16/2014	NW21STST	120	1-inch Overlay	81.68	9,058.00	\$14,414.00	3.00%
2/16/2014	NW23RDST	20	1-inch Overlay	80.43	22,709.00	\$36,138.00	6.98%
2/16/2014	NW26THST	10	1-inch Overlay	85.16	13,716.00	\$21,828.00	3.00%
2/16/2014	NW26THST	20	1-inch Overlay	80.43	30,935.00	\$49,229.00	6.98%
2/16/2014	NW26THST	50	1-inch Overlay	83.4	13,311.00	\$21,183.00	3.00%
2/16/2014	NW27THST	50	1-inch Overlay	84.24	13,027.00	\$20,731.00	3.00%
2/16/2014	NW27THST	80	1-inch Overlay	80.43	13,474.00	\$21,442.00	6.98%
2/16/2014	NW29THST	30	1-inch Overlay	80.43	17,267.00	\$27,478.00	6.98%
2/16/2014	NW29THST	50	1-inch Overlay	85.16	28,032.00	\$44,609.00	3.00%
2/16/2014	NW29THST	60	1-inch Overlay	82.29	21,023.00	\$33,456.00	3.00%
2/16/2014	NW29THST	80	1-inch Overlay	85.13	39,117.00	\$62,248.00	3.00%
2/16/2014	NW31STST	10	1-inch Overlay	84.24	29,029.00	\$46,196.00	3.00%
2/16/2014	NW31STTER	10	1-inch Overlay	86.05	20,529.00	\$32,669.00	3.00%
2/16/2014	NW33RDST	120	1-inch Overlay	85.11	18,059.00	\$28,738.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2014	NW33RDST	130	1-inch Overlay	86.04	37,046.00	\$58,954.00	3.00%
2/16/2014	NW33RDST	150	1-inch Overlay	84.41	10,119.00	\$16,104.00	3.00%
2/16/2014	NW33RDST	170	1-inch Overlay	83.55	18,218.00	\$28,991.00	3.00%
2/16/2014	NW33RDST	180	1-inch Overlay	80.97	39,797.00	\$63,331.00	6.23%
2/16/2014	NW36THTER	10	1-inch Overlay	83.4	14,919.00	\$23,742.00	3.00%
2/16/2014	NW50THST	30	1-inch Overlay	83.4	26,988.00	\$42,947.00	3.00%
2/16/2014	NW52NDST	50	1-inch Overlay	86.05	2,740.00	\$4,361.00	3.00%
2/16/2014	NW52NDST	160	1-inch Overlay	85.84	6,883.00	\$10,953.00	3.00%
2/16/2014	NW53RDST	80	1-inch Overlay	86.05	5,539.00	\$8,815.00	3.00%
2/16/2014	NW53RDST	90	1-inch Overlay	81.85	19,322.00	\$30,749.00	3.24%
2/16/2014	NW53RDST	110	1-inch Overlay	85.12	32,164.00	\$51,184.00	3.00%
2/16/2014	NW53RDST	130	1-inch Overlay	80.44	4,967.00	\$7,904.00	6.98%
2/16/2014	NW54THST	20	1-inch Overlay	83.4	13,355.00	\$21,253.00	3.00%
2/16/2014	NW54THST	30	1-inch Overlay	81.85	10,884.00	\$17,320.00	3.24%
2/16/2014	NW5STHST	10	1-inch Overlay	83.4	10,854.00	\$17,272.00	3.00%
2/16/2014	NW55THST	20	1-inch Overlay	82.61	13,244.00	\$21,076.00	3.00%
2/16/2014	NW66THST	20	1-inch Overlay	86.04	51,836.00	\$82,489.00	3.00%
2/16/2014	NW78THAVE	70	1-inch Overlay	82.61	7,277.00	\$11,579.00	3.00%
2/16/2014	NW82NDAVE	20	1-inch Overlay	82.44	16,236.00	\$25,837.00	3.00%
2/16/2014	NW82NDAVE	30	1-inch Overlay	83.4	15,832.00	\$25,195.00	3.00%
2/16/2014	NW82NDAVE	100	1-inch Overlay	85.16	20,885.00	\$33,236.00	3.00%
2/16/2014	NW82NDAVE	160	1-inch Overlay	<u>8</u> 5.84	5,806.00	\$9,239.00	3.00%
2/16/2014	NW82NDST	10	1-inch Overlay	86.86	48,605.00	\$77,347.00	3.00%
2/16/2014	NW84THAVE	30	1-inch Overlay	86.04	16,495.00	\$26,249.00	3.00%
2/16/2014	NW84THAVE	40	1-inch Overlay	81.84	39,571.00	\$62,972.00	3.27%
2/16/2014	NW84THAVE	50	1-inch Overlay	81.12	4,449.00	\$7,080.00	5.20%
2/16/2014	NW84THAVE	70	1-inch Overlay	80.43	32,772.00	\$52,151.00	6.98%
2/16/2014	NW84THAVE	80	1-inch Overlay	81.85	8,045.00	\$12,803.00	3.24%
2/16/2014	NW84THAVE	90	1-inch Overlay	81.12	22,450.00	\$35,726.00	5.20%
2/16/2014	NW84THAVE	130	1-inch Overlay	85.11	12,726.00	\$20,251.00	3.00%
2/16/2014	NW84THAVE	160	1-inch Overlay	84.24	24,225.00	\$38,550.00	3.00%
2/16/2014	NW86THAVE	10	1-inch Overlay	80.43	12,162.00	\$19,354.00	6.98%
2/16/2014	NW86THST	30	1-inch Overlay	85.12	17,895.00	\$28,477.00	3.00%
2/16/2014	NW87THCT	10	1-inch Overlay	80.43	17,076.00	\$27,174.00	6.98%
2/16/2014	NW88THAVE	10	1-inch Overlay	86.86	5,787.00	\$9,210.00	3.00%
2/16/2014	NW88THCT	20	1-inch Overlay	81.11	14,460.00	\$23,011.00	3.00%
2/16/2014	NW89THCT	50	1-inch Overiay	83.64	18,990.00	\$30,219.00	3.00%
2/16/2014	NW89THCT	60	1-inch Overlay	82.29	15,375.00	\$24,467.00	3.00%
2/16/2014	NW89THPL	20	1-inch Overlay	85.98	18,244.00	\$29,033.00	3.00%
2/16/2014	NW89THPL	30	1-inch Overlay	85.98	27,925.00	\$44,438.00	3.00%
2/16/2014	NW91STAVE	10	1-inch Overlay	81.13	17,737.00	\$28,225.00	5.16%
2/16/2014	NW92NDAVE	30	1-inch Overlay	81.12	12,764.00	\$20,313.00	5.20%
2/16/2014	NW92NDAVE	40	1-inch Overlay	83.4	16,652.00	\$26,500.00	3.00%

•

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2014	NW92NDAVE	50	1-inch Overlay	80.43	12,709.00	\$20,225.00	6.98%
2/16/2014	NW98THCT	10	1-inch Overlay	86.04	36,239.00	\$57,668.00	3.00%
2/16/2014	NW99THAVE	90	1-inch Overlay	81.85	8,935.00	\$14,218.00	3.24%

.

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2015	NW102NDAVE	90	1-inch Overlay	85.27	26,224.00	\$42,984.00	3.00%
2/16/2015	NW102NDAVE	100	1-inch Overlay	87.46	26,913.00	\$44,113.00	3.00%
2/16/2015	NW102NDAVE	170	1-inch Overlay	90.19	5,549.00	\$9,095.00	3.00%
2/16/2015	NW102NDAVE	250	1-inch Overlay	86.3	1,911.00	\$3,132.00	3.00%
2/16/2015	NW102NDAVE	260	1-inch Overlay	86.59	38,921.00	\$63,796.00	3.00%
2/16/2015	NW104THAVE	40	1-inch Overlay	86.31	21,446.00	\$35,151.00	3.00%
2/16/2015	NW105THAVE	20	1-inch Overlay	87.33	8,888.00	\$14,569.00	3.00%
2/16/2015	NW105THAVE	30	1-inch Overlay	88.43	10,306.00	\$16,892.00	3.00%
2/16/2015	NW109THAVE	30	1-inch Overlay	88.78	18,020.00	\$29,537.00	3.00%
2/16/2015	NW109THAVE	40	1-inch Overlay	88.78	8,756.00	\$14,352.00	3.00%
2/16/2015	NW109THAVE	100	1-inch Overlay	86.31	8,973.00	\$14,707.00	3.00%
2/16/2015	NW109THAVE	110	1-inch Overlay	88.78	8,859.00	\$14,521.00	3.00%
2/16/2015	NW109THAVE	120	1-inch Overlay	87.46	18,604.00	\$30,494.00	3.00%
2/16/2015	NW109THAVE	140	1-inch Overlay	89.8	2,860.00	\$4,688.00	3.00%
2/16/2015	NW109THAVE	150	1-inch Overlay	87.39	4,280.00	\$7,015.00	3.00%
2/16/2015	NW109THAVE	160	1-inch Overlay	87.39	7,120.00	\$11,670.00	3.00%
2/16/2015	NW109THAVE	170	1-inch Overlay	87.39	6,748.00	\$11,061.00	3.00%
2/16/2015	NW111THCT	1	1-inch Overlay	87.39	5,000.00	\$8,195.00	3.00%
2/16/2015	NW111THCT	2	1-inch Overlay	87.39	5,320.00	\$8,720.00	3.00%
2/16/2015	NW111THCT	3	1-inch Overlay	87.39	5,440.00	\$8,917.00	3.00%
2/16/2015	NW111THCT	4	1-inch Overlay	87.39	4,820.00	\$7,900.00	3.00%
2/16/2015	NW112THAVE	20	1-inch Overlay	86.31	41,389.00	\$67,841.00	3.00%
2/16/2015	NW112THAVE	130	1-inch Overlay	85.28	8,219.00	\$13,472.00	3.00%
2/16/2015	NW112THAVE	150	1-inch Overlay	88.78	6,340.00	\$10,393.00	3.00%
2/16/2015	NW112THAVE	160	1-inch Overlay	86.31	19,395.00	\$31,790.00	3.00%
2/16/2015	NW112THAVE	230	1-inch Overlay	85.28	19,895.00	\$32,611.00	3.00%
2/16/2015	NW112THCT	10	1-inch Overlay	88.78	43,567.00	\$71,411.00	3.00%
2/16/2015	NW112THPL	2	1-inch Overlay	87.39	5,880.00	\$9,638.00	3.00%
2/16/2015	NW112THPL	3	1-inch Overlay	87.39	5,628.00	\$9,225.00	3.00%
2/16/2015	NW113THAVE	1	1-inch Overlay	89.91	5,588.00	\$9,159.00	3.00%
2/16/2015	NW114THAVE	50	1-inch Overlay	88.78	25,359.00	\$41,565.00	3.00%
2/16/2015	NW114THAVE	80	1-inch Overlay	88.78	7,968.00	\$13,060.00	3.00%
2/16/2015	NW114THAVE	110	1-inch Overlay	87.46	27,464.00	\$45,017.00	3.00%
2/16/2015	NW114THAVE	190	1-inch Overlay	88.78	19,282.00	\$31,606.00	3.00%
2/16/2015	NW114THAVE	200	1-inch Overlay	84.33	15,947.00	\$26,139.00	3.00%
2/16/2015	NW114THAVE	270	1-inch Overlay	86.31	27,826.00	\$45,610.00	3.00%
2/16/2015	NW114THAVE	320	1-inch Overlay	88.78	11,797.00	\$19,337.00	3.00%
2/16/2015	NW15THST	40	1-inch Overlay	85.47	16,093.00	\$26,378.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2015	NW19THST	10	1-inch Overlay	88.77	10,962.00	\$17,968.00	3.00%
2/16/2015	NW19THST	20	1-inch Overlay	85.27	59,896.00	\$98,175.00	3.00%
2/16/2015	NW21STST	40	1-inch Overlay	85.27	17,926.00	\$29,383.00	3.00%
2/16/2015	NW21STST	110	1-inch Overlay	85.28	23,074.00	\$37,820.00	3.00%
2/16/2015	NW25THTER	20	1-inch Overlay	86.3	11,840.00	\$19,407.00	3.00%
2/16/2015	NW27THST	10	1-inch Overlay	88.43	34,137.00	\$55,954.00	3.00%
2/16/2015	NW28THST	10	1-inch Overlay	88.43	13,548.00	\$22,207.00	3.00%
2/16/2015	NW29THST	40	1-inch Overlay	86.36	14,314.00	\$23,462.00	3.00%
2/16/2015	NW33RDST	140	1-inch Overlay	85.27	26,265.00	\$43,051.00	3.00%
2/16/2015	NW33RDST	160	1-inch Overlay	87.2	19,758.00	\$32,385.00	3.00%
2/16/2015	NW39THST	1	1-inch Overlay	87.39	28,044.00	\$45,967.00	3.00%
2/16/2015	NW50THST	50	1-inch Overlay	88.78	15,801.00	\$25,900.00	3.00%
2/16/2015	NW50THST	70	1-inch Overlay	87.46	5,776.00	\$9,467.00	3.00%
2/16/2015	NW52NDST	20	1-inch Overlay	86	21,745.00	\$35,642.00	3.00%
2/16/2015	NW52NDST	30	1-inch Overlay	87.46	2,255.00	\$3,695.00	3.00%
2/16/2015	NW52NDST	40	1-inch Overlay	86.31	4,189.00	\$6,866.00	3.00%
2/16/2015	NW52NDST	90	1-inch Overlay	87.86	22,079.00	\$36,190.00	3.00%
2/16/2015	NW52NDST	200	1-inch Overlay	87.2	11,106.00	\$18,204.00	3.00%
2/16/2015	NW56THST	50	1-inch Overlay	85.28	11,017.00	\$18,058.00	3.00%
2/16/2015	NW77THTER	1	1-inch Overlay	87.39	6,660.00	\$10,916.00	3.00%
2/16/2015	NW77THTER	2	1-inch Overlay	87.39	6,080.00	\$9,966.00	3.00%
2/16/2015	NW77THTER	3	1-inch Overlay	87.39	5,860.00	\$9,605.00	3.00%
2/16/2015	NW78THAVE	40	1-inch Overlay	88.78	6,642.00	\$10,887.00	3.00%
2/16/2015	NW78THLN	1	1-inch Overlay	87.39	5,586.00	\$9,156.00	3.00%
2/16/2015	NW78THLN	2	1-inch Overlay	87.39	6,132.00	\$10,051.00	3.00%
2/16/2015	NW78THST	1	1-inch Overlay	86.32	26,900.00	\$44,092.00	3.00%
2/16/2015	NW78THST	2	1-inch Overlay	86.32	22,000.00	\$36,060.00	3.00%
2/16/2015	NW78THST	3	1-inch Overlay	86.32	6,321.00	\$10,361.00	3.00%
2/16/2015	NW78THST	4	1-inch Overlay	86.32	5,880.00	\$9,638.00	3.00%
2/16/2015	NW78THST	5	1-inch Overlay	86.32	7,119.00	\$11,669.00	3.00%
	NW78THST		1-inch Overlay	86.32	8,652.00	\$14,181.00	3.00%
2/16/2015	NW78THST	7	1-inch Overlay	86.32	4,074.00	\$6,678.00	3.00%
2/16/2015	NW79THLN	1	1-inch Overlay	87.39	11,680.00	\$19,145.00	3.00%
2/16/2015	NW79THLN	2	1-inch Overlay	87.39	5,840.00	\$9,572.00	3.00%
2/16/2015	NW79THLN	3	1-inch Overlay	87.39	5,500.00	\$9,015.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2015	NW80THLN	1	1-inch Overlay	87.39	19,200.00	\$31,471.00	3.00%
2/16/2015	NW80THLN	2	1-inch Overlay	87.39	22,040.00	\$36,126.00	3.00%
2/16/2015	NW82NDAVE	60	1-inch Overlay	86.59	10,566.00	\$17,318.00	3.00%
2/16/2015	NW82NDAVE	110	1-inch Overlay	87.21	19,667.00	\$32,236.00	3.00%
2/16/2015	NW82NDAVE	190	1-inch Overlay	86	19,521.00	\$31,996.00	3.00%
2/16/2015	NW82NDST	20	1-inch Overlay	85.48	42,487.00	\$69,640.00	3.00%
2/16/2015	NW82NDST	30	1-inch Overlay	89.72	74,357.00	\$121,879.00	3.00%
2/16/2015	NW84THAVE	110	1-inch Overlay	87.46	15,730.00	\$25,782.00	3.00%
2/16/2015	NW84THST	1	1-inch Overlay	87.39	13,620.00	\$22,324.00	3.00%
2/16/2015	NW84THST	2	1-inch Overlay	87.39	5,280.00	\$8,654.00	3.00%
2/16/2015	NW84THST	4	1-inch Overlay	87.39	3,100.00	\$5,081.00	3.00%
2/16/2015	NW86THST	40	1-inch Overlay	88.78	4,517.00	\$7,403.00	3.00%
2/16/2015	NW88THST	2	1-inch Overlay	87.39	20,085.00	\$32,921.00	3.00%
2/16/2015	NW89THCT	40	1-inch Overlay	84.33	13,944.00	\$22,855.00	3.00%
2/16/2015	NW89THPL	10	1-inch Overlay	85.47	21,483.00	\$35,212.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2016	NW102NDAVE	120	1-inch Overlay	89.91	36,792.00	\$62,114.00	
2/16/2016	NW102NDAVE	180	1-inch Overlay	87.47	25,161.00	\$42,478.00	
2/16/2016	NW102NDAVE	270	1-inch Overlay	90.55	10,774.00	\$18,190.00	
2/16/2016	NW102NDAVE	280	1-inch Overlay	90.55	11,839.00	\$19,987.00	
2/16/2016	NW102NDAVE	290	1-inch Overlay	90.55	27,521.00	\$46,462.00	
2/16/2016	NW109THAVE	60	1-inch Overlay	89.91	7,286.00	\$12,300.00	
2/16/2016	NW109THAVE	80	1-inch Overlay	89.91	18,877.00	\$31,870.00	
2/16/2016	NW109THAVE	90	1-inch Overlay	89.91	11,260.00	\$19,009.00	
2/16/2016	NW109THAVE	130	1-inch Overlay	87.47	9,918.00	\$16,744.00	
2/16/2016	NW112THAVE	90	1-inch Overlay	87.47	21,184.00	\$35,764.00	
2/16/2016	NW112THAVE	110	1-inch Overlay	89.92	25,050.00	\$42,292.00	
2/16/2016	NW112THAVE	170	1-inch Overlay	89.92	11,655.00	\$19,677.00	
2/16/2016	NW112THAVE	180	1-inch Overlay	87.47	7,830.00	\$13,219.00	
2/16/2016	NW112THAVE	190	1-inch Overlay	89.91	18,818.00	\$31,769.00	
2/16/2016	NW112THAVE	200	1-inch Overlay	89.92	9,715.00	\$16,402.00	
2/16/2016	NW112THAVE	250	1-inch Overlay	89.92	5,142.00	\$8,681.00	
2/16/2016	NW112THAVE	260	1-inch Overlay	89.91	21,415.00	\$36,154.00	
2/16/2016	NW112THAVE	280	1-inch Overlay	87.47	25,963.00	\$43,833.00	
2/16/2016	NW113THCT	10	1-inch Overlay	87.47	25,385.00	\$42,856.00	
2/16/2016	NW113THPSG	126	1-inch Overlay	90.8	3,297.00	\$5,566.00	
2/16/2016	NW114THAVE	60	1-inch Overlay	89.93	19,568.00	\$33,035.00	
2/16/2016	NW114THAVE	70	1-inch Overlay	89.93	7,998.00	\$13,503.00	
2/16/2016	NW114THAVE	130	1-inch Overlay	89.93	11,874.00	\$20,046.00	
2/16/2016	NW114THAVE	250	1-inch Overlay	89.92	18,816.00	\$31,766.00	
2/16/2016	NW114THAVE	330	1-inch Overlay	89.93	60,030.00	\$101,347.00	
2/16/2016	NW117THAVE	10	1-inch Overlay	89.92	47,359.00	\$79,955.00	
2/16/2016	NW14THST	10	1-inch Overlay	87.47	32,484.00	\$54,841.00	
2/16/2016	NW15THTER	10	1-inch Overlay	89.91	19,076.00	\$32,205.00	
2/16/2016	NW21STST	60	1-inch Overlay	89.91	13,092.00	\$22,102.00	
2/16/2016	NW27THST	110	1-inch Overlay	89.91	28,512.00	\$48,135.00	
2/16/2016	NW30THST	10	1-inch Overlay	87.47	26,603.00	\$44,912.00	
2/16/2016	NW30THST	20	1-inch Overlay	87.47	36,576.00	\$61,751.00	
2/16/2016	NW33RDST	80	1-inch Overlay	89.41	28,465.00	\$48,056.00	
2/16/2016	NW36THST	10	1-inch Overlay	89.92	39,358.00	\$66,447.00	
2/16/2016	NW50THST	20	1-inch Overlay	89.92	17,480.00	\$29,511.00	
2/16/2016	NW50THST	40	1-inch Overlay	89.92	39,291.00	\$66,334.00	
2/16/2016	NW52NDST	80	1-inch Overlay	90.55	10,052.00	\$16,971.00	
2/16/2016	NW52NDST	110	1-inch Overlay	90.55	15,899.00	\$26,842.00	
2/16/2016	NW52NDST	140	1-inch Overlay	90.55	12,037.00	\$20,322.00	
2/16/2016	NW52NDST	220	1-inch Overlay	89.41	18,636.00	\$31,463.00	
2/16/2016	NW53RDST	160	1-inch Overlay	89.92	10,725.00	\$18,107.00	
2/16/2016	NW57THST	10	1-inch Overlay	89.92	5,158.00	\$8,707.00	
2/16/2016	NW57THST	20	1-inch Overlay	89.92	14,803.00	\$24,992.00	

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2016	NW78THAVE	20	1-inch Overlay	89.92	7,402.00	\$12,497.00	
2/16/2016	NW82NDAVE	70	1-inch Overlay	90.55	13,699.00	\$23,128.00	
2/16/2016	NW82NDAVE	170	1-inch Overlay	90.55	9,345.00	\$15,778.00	
2/16/2016	NW84THAVE	60	1-inch Overlay	89.92	15,941.00	\$26,913.00	
2/16/2016	NW84THAVE	120	1-inch Overlay	89.91	5,586.00	\$9,431.00	
2/16/2016	NW86THST	20	1-inch Overlay	89.92	4,367.00	\$7,372.00	
2/16/2016	NW86THST	60	1-inch Overlay	89.92	8,749.00	\$14,770.00	
2/16/2016	NW86THST	70	1-inch Overlay	89.92	13,017.00	\$21,976.00	
2/16/2016	NW98THCT	20	1-inch Overlay	89.91	36,546.00	\$61,700.00	



SCOPE OF SERVICE







WORK ORDER FOR PROFESSIONAL SERVICES

Engineers Architects Planners TO:

City of Doral 8300 N.W. 53rd Street Suite 200 Doral, Florida 33166

DATE: 7/26/11 FILE: 426-00

ATTENTION: Eric Carpenter, P.E. Public Works Director

PROJECT NAME: Citywide Pavement Evaluation and Five-year Pavement Maintenance and Rehabilitation Plan Doral, Florida

EB0005022 SCOPE OF SERVICES:

- 1. Review, confirm and update the GIS city-owned roadway network segments and AutoCad map.
- 2. Update maintenance and construction history (2007 through present).
- 3. Input 2007 PCI values for the city-owned roadway segments into GIS database.
- 4. ERoadInfo to perform automated filed data collection along all city-owned roadways, in addition to image capture photos every 50 ft, for potential city asset management use.
- 5. ERoadInfo to Perform Pavement rating PCI based on current conditions. Data provided will be imported into GIS.
- 6. Populate GIS Database into MicroPaver ver. 6.5.
- 7. Comparison of 2011 and 2007 PCI values.
- 8. Development of deterioration models, and ranking and prioritization of repair and rehabilitation needs.
- 9. Engineering Analysis of repair and rehabilitation options for the various roadways. Develop unit cost information, develop routine maintenance requirements.
- 10. Perform limited pavement cores in specific areas where pavement distress is such that pavement reconstruction or milling is likely to be needed.
- 11. Prepare a report documenting pavement conditions and identifying future five-year pavement maintenance and rehabilitation plan.

We estimate that 120 days will be needed to complete this assignment.

W.O. for Professional Services July 26, 2011 Page 2

FEES:

.

All terms and conditions shall be per our E/A Services Contract – Master Agreement. Our fees for the above services shall be as follows:

Doral-owned Roadways	\$49,798
MDCPW Roads (Image Capture only)	. \$6,320

We are ready to begin working on this assignment upon your authorization to proceed. If acceptable to you, we will accept a signed copy of this form as your written authorization to proceed with the assignment.

Thank you.

Corzo Castella Carballo Thompson Salman, P.A.

Ramon Castella, P.E. Principal RC/er

City of Doral

Approved by:

Date

t/00426-000 Doral/W.O. Proposals/W.O. 072611 Citywido Pvmt..doc

* Corzo Castella Carballo Thompson Salman, P.A.

FEE WORKSHEET

DATE:

.

• • • . 1

26-Jul-11

PROJECT:

Citywide Pavement Evaluation & Pavmnt Maint/Rehab Plan Doral, Florida

<u>C3TS</u>

	Ren a	EERA	REVAN	Simuch		Concal
Review, confirm & update GIS & Acad map						
of City-owned Roads	2			4	4	
Update maintenance & construction history	1	4	6	2		
Input 2007 PCI's into GIS			2		6	
Coordinate ERoadInfo tasks	2	4	8	6		4
Populate GIS Database into MicoPaver		2	4	4		
PCI Comparison 2007 to present		2	4			
Develop deterioration models, and ranking	2	8	24	16	8	
Engineering Analysis of Options	2	6	12			
Develop Unit Cost Information	1	2	6	2		
Develop Routine Maintenance Regrmts	2	4	8			
Coordination of pavement cores		2	4	•	2	
Develop Project Areas & Scopes	2	4	8	6	12	
Develop Five Year Plan	2	4	8	4		
Report Preparation (DRAFT)	1	6	12	8	16	12
Report (FINAL)	. 1	2	2	2	4	2
Sub-Total Hours	18					18
Billing Rate		135	98	85	77.5	
Labor Cost	\$3,330	\$7,830	\$10,584	\$4,590	\$4,030	\$1,044
				Labo	r Sub-Total	\$31,408

Printing & Reproduction Pavement Cores \$500 \$850

Total \$32,758

EROAD INFO (CITY - OWNED ROADS)

Jask		eoŋŋi溪世	TINE HEALEN	6-1013
System Setup	LS	1	2000	2000
Image Capture	Miles	52	140	7280
System Mobilization	Miles	15	220	3300
Lodging	Man-days	10	150	1500
Pavement Database Preparation	hours	8	110	880
Pavement Rating	Miles	52	40	2080

Total

Total \$17,040

EROAD INFO (MDCPW ROADS - IMAGE CAPTURE ONLY)

Task	UDH	Counter Un	It Rhoal Su	b-total
Image Capture	Miles	34	140	4760
Lodging	Man-days	6	150	900
Database Preparation	hours	6	110	660

\$6,320

Total

•

APPENDIX E

REQUESTED DORAL PROJECTS FOR 2011/2012





NetworkID	BranchID	SectionID	Last Constr	SURFACE	Rank	Area (SF)	Last Insp Date	PCI
CITYROAD	NW13THTER	10	1/1/2002	AC	Т	6,157 SqFt	9/22/2011	89
CITYROAD	NW13THTER	20	1/1/2002	AC	Т	22,573 SqF	9/22/2011	76
CITYROAD	NW13THTER	30	1/1/2002	AC	Т	15,911 SqF	9/22/2011	76
CITYROAD	NW14THST	20	1/1/1997	AC	S	22,757 SqF	9/24/2011	85
CITYROAD	NW17THST	30	1/1/1995	AC	S	44,154 SqF	9/22/2011	83
CITYROAD	NW18THTER	10	1/1/1997	AC	Т	41,619 SqF	9/22/2011	91
CITYROAD	NW18THTER	20	1/1/1997	AC	Т	14,976 SqF	9/22/2011	90
CITYROAD	NW21STST	30	1/1/1997	AC	S	20,351 SqF	9/24/2011	60
CITYROAD	NW21STST	50	1/1/1997	AC	S	26,289 SqF	9/24/2011	51
CITYROAD	NW21STST	60	1/1/1997	AC	S	13,092 SqF	9/22/2011	100
CITYROAD	NW21STST	70	1/1/1997	AC	S	5,772 SqFt	9/22/2011	86
CITYROAD	NW21STST	90	1/1/1997	AC	S	25,148 SqF	9/22/2011	82
CITYROAD	NW21STST	100	1/1/1997	AC	TT	5,222 SqFt	9/22/2011	86
CITYROAD	NW21STST	120	1/1/1997	AC	Т	9,058 SqFt	9/22/2011	86
CITYROAD	NW29THST	20	1/1/1999	AC	S	39,410 SqF	9/22/2011	77
CITYROAD	NW29THST	30	1/1/1999	AC	S	17,267 SqF	9/22/2011	86
CITYROAD	NW29THST	90	1/1/1999	AC	S	18,984 SqF	9/22/2011	80
CITYROAD	NW31STST	10	1/1/1995		S	29,029 SqF	9/22/2011	91
CITYROAD	NW37THST	10	1/1/2002	AC	S	13,206 SqF	9/24/2011	52
CITYROAD	NW37THST	20	1/1/2002	AC	S	5,597 SqFt	9/24/2011	50
CITYROAD	NW38THST	10	1/1/2002	AC	S	13,274 SqF	9/24/2011	36
CITYROAD	NW77THCT	50	1/1/2003	AC	S	19,197 SqF	9/22/2011	71
CITYROAD	NW78THAVE	30	1/1/2003	AC	Т	59,595 SqF	9/24/2011	68
CITYROAD	NW84THAVE	20	1/1/1997	AC	S	32,681 SqF	9/24/2011	65
CITYROAD	NW88THCT	30	1/1/1997	AC	Т	13,466 SqF	9/22/2011	63
CITYROAD	NW89THCT	50	1/1/1992	AC	Т	18,990 SqF	9/22/2011	89
CITYROAD	NW89THCT	60	1/1/1992	AC	Т	15,375 SqF	9/22/2011	87
CITYROAD	NW91STAVE	10	1/1/1999	AC	S	17,737 SqF	9/24/2011	87

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2012	NW100THAVE	20	Milling & Resurfacing (1-inch)	65.94	4,741.00	\$9,481.00	3.00%
2/16/2012	NW100THAVE	60	Milling & Resurfacing (1-inch)	77.47	4,571.00	\$7,658.00	4.87%
2/16/2012	NW100THAVE	30	Milling & Resurfacing (1-inch)	68.28	4,729.00	\$9,459.00	3.00%
2/16/2012	NW100THAVE	10	1-inch Overlay	86.04	5,347.00	\$8,509.00	3.00%
2/16/2012	NW102NDAVE	140	Milling & Resurfacing (1-inch)	67.95	2,345.00	\$4,831.00	3.00%
2/16/2012	NW102NDAVE	150	Milling & Resurfacing (1-inch)	67.95	5,159.00	\$10,627.00	3.00%
2/16/2012	NW102NDAVE	160	Milling & Resurfacing (1-inch)	69.86	5,822.00	\$11,993.00	3.00%
2/16/2012	NW102NDAVE	110	Milling & Resurfacing (1-inch)	65.94	6,111.00	\$12,222.00	3.00%
2/16/2012	NW102NDAVE	130	Milling & Resurfacing (1-inch)	53.34	5,818.00	\$11,636.00	3.00%
2/16/2012	NW102NDAVE	250	1-inch Overlay	86.3	1,911.00	\$3,132.00	3.00%
2/16/2012	NW104THAVE	50	Milling & Resurfacing (1-inch)	68.93	23,394.00	\$46,788.00	3.00%
2/16/2012	NW114THAVE	10	Milling & Resurfacing (1-inch)	55.66	4,168.00	\$8,337.00	3.00%
2/16/2012	NW114THAVE	180	Milling & Resurfacing (1-inch)	79.4	11,210.00	\$17,665.00	7.41%
2/16/2012	NW114THAVE	220	Milling & Resurfacing (1-inch)	77.03	2,851.00	\$4,842.00	4.09%
2/16/2012	NW114THAVE	280	Milling & Resurfacing (1-inch)	77.47	15,298.00	\$25,629.00	4.87%
2/16/2012	NW114THAVE	20	Milling & Resurfacing (1-inch)	62.5	8,926.00	\$17,852.00	3.00%
2/16/2012	NW114THAVE	30	Milling & Resurfacing (1-Inch)	62.5	12,018.00	\$24,037.00	3.00%
2/16/2012	NW114THAVE	40	Milling & Resurfacing (1-inch)	62.5	11,430.00	\$22,861.00	3.00%
2/16/2012	NW114THAVE	130	1-inch Overlay	89.93	11,874.00	\$20,046.00	
2/16/2012	NW114THAVE	120	Milling & Resurfacing (1-inch)	68.3	15,358.00	\$30,716.00	3.00%
2/16/2012	NW114THAVE	140	Milling & Resurfacing (1-inch)	62.5	14,879.00	\$29,757.00	3.00%
2/16/2012	NW114THAVE	150	Milling & Resurfacing (1-inch)	68.3	8,365.00	\$16,729.00	3.00%
2/16/2012	NW114THAVE	210	Milling & Resurfacing (1-inch)	60.21	13,833.00	\$27,666.00	3.00%
2/16/2012	NW114THAVE	230	Milling & Resurfacing (1-inch)	61.35	11,702.00	\$23,403.00	3.00%
2/16/2012	NW114THAVE	240	Milling & Resurfacing (1-inch)	62.5	8,832.00	\$17,663.00	3.00%
2/16/2012	NW114THAVE	300	Milling & Resurfacing (1-inch)	65.97	18,548.00	\$37,096.00	3.00%
2/16/2012	NW114THAVE	310	Milling & Resurfacing (1-inch)	67.13	11,948.00	\$23,897.00	3.00%
2/16/2012	NW117THAVE	40	Milling & Resurfacing (1-inch)	60.17	54,821.00	\$109,641.00	3.00%
2/16/2012	NW117THAVE	50	Milling & Resurfacing (1-inch)	68.92	71,040.00	\$142,080.00	3.00%
2/16/2012	NW15THST	10	Milling & Resurfacing (1-inch)	60.21	12,619.00	\$25,237.00	3.00%
2/16/2012	NW20THST	10	Milling & Resurfacing (1-inch)	67.96	28,721.00	\$57,442.00	3.00%
2/16/2012	NW21STST	30	Milling & Resurfacing (1-inch)	56.79	20,351.00	\$40,702.00	3.00%
2/16/2012	NW21STST	50	Milling & Resurfacing (1-inch)	46.66	26,289.00	\$52,578.00	156.65%
2/16/2012	NW2STHTER	20	1-inch Overlay	86.3	11,840.00	\$19,407.00	3.00%
2/16/2012	NW2STHTER	10	Milling & Resurfacing (1-inch)	65.94	6,612.00	\$13,225.00	3.00%
2/16/2012	NW26THST	30	1-inch Overlay	80.87	12,944.00	\$19,999.00	5.85%
2/16/2012	NW26THST	40	1-inch Overlay	81.66	13,036.00	\$20,141.00	3.76%
2/16/2012	NW26THST	50	1-inch Overlay	83.4	13,311.00	\$21,183.00	3.00%
2/16/2012	NW27THST	120	1-inch Overlay	80.12	12,988.00	\$20,066.00	7.77%
2/16/2012	NW27THST	50	1-inch Overlay	84.24	13,027.00	\$20,731.00	3.00%
2/16/2012	NW27THST	80	1-inch Overlay	80.43	13,474.00	\$21,442.00	6.98%
2/16/2012	NW33RDST	70	Milling & Resurfacing (1-inch)	63.65	14,418.00	\$28,837.00	3.00%
2/16/2012	NW33RDST	90	Milling & Resurfacing (1-inch)	64.81	12,641.00	\$25,282.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2012	NW38THST	20	Milling & Resurfacing (1-inch)	63.65	20,628.00	\$41,257.00	3.00%
2/16/2012	NW40THST	20	Milling & Resurfacing (1-inch)	67.98	10,592.00	\$21,820.00	3.00%
2/16/2012	NW40THST	10	Milling & Resurfacing (1-inch)	61.35	15,327.00	\$30,654.00	3.00%
2/16/2012	NW50THST	60	Milling & Resurfacing (1-inch)	61.33	21,930.00	\$43,859.00	3.00%
2/16/2012	NW54THST	10	Milling & Resurfacing (1-inch)	54.5	26,495.00	\$52,990.00	3.00%
2/16/2012	NW54THST	40	Milling & Resurfacing (1-inch)	64.79	26,373.00	\$52,745.00	3.00%
2/16/2012	NW54THST	50	Milling & Resurfacing (1-inch)	70.67	26,276.00	\$51,672.00	4.75%
2/16/2012	NW56THST	30	Milling & Resurfacing (1-inch)	61.33	29,143.00	\$58,286.00	3.00%
2/16/2012	NW77THCT	40	Milling & Resurfacing (1-inch)	71.91	6,953.00	\$13,640.00	8.17%
2/16/2012	NW77THCT	10	Milling & Resurfacing (1-inch)	59.04	6,416.00	\$12,833.00	3.00%
2/16/2012	NW77THCT	20	Milling & Resurfacing (1-inch)	61.33	6,624.00	\$13,247.00	3.00%
2/16/2012	NW77THCT	30	Milling & Resurfacing (1-inch)	63.63	6,911.00	\$13,823.00	3.00%
2/16/2012	NW77THCT	50	Milling & Resurfacing (1-inch)	69.46	19,197.00	\$38,395.00	3.00%
2/16/2012	NW78THAVE	30	Milling & Resurfacing (1-inch)	65.68	59,595.00	\$119,189.00	3.00%
2/16/2012	NW82NDAVE	190	1-inch Overlay	86	19,521.00	\$31,996.00	3.00%
2/16/2012	NW82NDAVE	40	Milling & Resurfacing (1-inch)	52.01	23,366.00	\$46,733.00	3.00%
2/16/2012	NW82NDAVE	120	Milling & Resurfacing (1-inch)	67.99	21,628.00	\$43,256.00	3.00%
2/16/2012	NW82NDAVE	140	Milling & Resurfacing (1-inch)	60.56	16,424.00	\$32,847.00	3.00%
2/16/2012	NW84THAVE	10	Milling & Resurfacing (1-inch)	65.97	18,117.00	\$36,235.00	3.00%
2/16/2012	NW84THAVE	20	Milling & Resurfacing (1-inch)	62.5	32,681.00	\$65,362.00	3.00%
2/16/2012	NW84THAVE	140	Milling & Resurfacing (1-inch)	65.97	10,472.00	\$20,944.00	3.00%
2/16/2012	NW84THAVE	150	Milling & Resurfacing (1-inch)	70.68	14,818.00	\$29,132.00	4.78%
2/16/2012	NW88THCT	20	1-inch Overlay		14,460.00	\$23,011.00	3.00%
2/16/2012	NW88THCT	10	Milling & Resurfacing (1-inch)	69.12	20,285.00	\$40,570.00	3.00%
2/16/2012	NW88THCT	30	Milling & Resurfacing (1-inch)	59.93	13,466.00	\$26,932.00	3.00%
2/16/2012	NW92NDAVE	10	Milling & Resurfacing (1-inch)	68.29	18,868.00	\$37,736.00	3.00%
2/16/2012	NW99THAVE	90	1-inch Overlay	81.85	8,935.00	\$14,218.00	3.24%
2/16/2012	NW99THAVE	20	Milling & Resurfacing (1-inch)	59.07	19,968.00	\$39,935.00	3.00%
2/16/2012	NW99THAVE	50	Milling & Resurfacing (1-inch)	65.65	37,184.00	\$74,367.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2013	NW102NDPL	10	Milling & Resurfacing (1-inch)	79.39	36,692.00	\$57,842.00	7.37%
2/16/2013	NW104THAVE	10	Milling & Resurfacing (1-inch)	74.25	11,007.00	\$20,265.00	10.17%
2/16/2013	NW104THAVE	20	1-inch Overlay	80.12	25,518.00	\$39,425.00	7.77%
2/16/2013	NW109THAVE	30	1-inch Overlay	88.78	18,020.00	\$29,537.00	3.00%
2/16/2013	NW109THAVE	40	1-inch Overlay	88.78	8,756.00	\$14,352.00	3.00%
2/16/2013	NW109THAVE	110	1-inch Overlay	88.78	8,859.00	\$14,521.00	3.00%
2/16/2013	NW109THAVE	10	1-inch Overlay	80.12	27,237.00	\$42,081.00	7.77%
2/16/2013	NW109THAVE	70	Milling & Resurfacing (1-inch)	74.25	31,548.00	\$58,084.00	10.17%
2/16/2013	NW110THAVE	20	1-inch Overlay	80.51	11,860.00	\$18,324.00	6.78%
2/16/2013	NW110THPL	1	1-inch Overlay	80.51	10,700.00	\$16,532.00	6.78%
2/16/2013	NW111THCT	S	1-inch Overlay	80.51	9,860.00	\$15,234.00	6.78%
2/16/2013	NW112THAVE	210	Milling & Resurfacing (1-inch)	70.67	4,807.00	\$9,453.00	4.75%
2/16/2013	NW112THAVE	10	1-inch Overlay	84.24	9,072.00	\$14,437.00	3.00%
2/16/2013	NW112THAVE	40	1-inch Overlay	84.24	5,747.00	\$9,145.00	3.00%
2/16/2013	NW112THAVE	130	1-inch Overlay	85.28	8,219.00	\$13,472.00	3.00%
2/16/2013	NW112THAVE	60	Milling & Resurfacing (1-inch)	79.39	7,981.00	\$12,582.00	7.37%
2/16/2013	NW112THAVE	70	Milling & Resurfacing (1-inch)	76.96	5,053.00	\$8,598.00	3.97%
2/16/2013	NW112THAVE	100	Milling & Resurfacing (1-inch)	78.7	5,500.00	\$8,865.00	6.55%
2/16/2013	NW112THAVE	140	1-inch Overlay	80.12	4,737.00	\$7,319.00	7.77%
2/16/2013	NW117THAVE	20	Milling & Resurfacing (1-inch)	60.19	38,184.00	\$76,368.00	3.00%
2/16/2013	NW117THAVE	30	1-inch Overlay	80.88	15,095.00	\$23,321.00	5.82%
2/16/2013	NW13THTER	20	Milling & Resurfacing (1-inch)	71.81	22,573.00	\$44,397.00	7.88%
2/16/2013	NW13THTER	30	Milling & Resurfacing (1-Inch)	71.81	15,911.00	\$31,294.00	7.88%
2/16/2013	NW14THST	20	1-inch Overlay	81.67	22,757.00	\$35,160.00	3.72%
2/16/2013	NW14THST	30	1-inch Overlay	80.89	46,443.00	\$71,755.00	5.82%
2/16/2013	NW15THST	40	1-inch Overlay	85.47	16,093.00	\$26,378.00	3.00%
2/16/2013	NW1STHST	30	Milling & Resurfacing (1-inch)	71.81	16,374.00	\$32,203.00	7.88%
2/16/2013	NW17THST	20	Milling & Resurfacing (1-inch)	76.02	19,727.00	\$34,521.00	6.18%
2/16/2013	NW17THST	30	1-inch Overlay	80.12	44,154.00	\$68,219.00	7.77%
2/16/2013	NW21STST	80	Milling & Resurfacing (1-inch)	79.39	13,694.00	\$21,587.00	7.37%
2/16/2013	NW21STST	90	Milling & Resurfacing (1-inch)	79.39	25,148.00	\$39,643.00	7.37%
2/16/2013	NW23RDST	10	Milling & Resurfacing (1-inch)	71.81	28,622.00	\$56,293.00	7.88%
2/16/2013	NW24THTER	10	1-inch Overlay	81.04	21,529.00	\$33,263.00	3.00%
2/16/2013	NW29THST	30	1-inch Overlay	80.43	17,267.00	\$27,478.00	6.98%
2/16/2013	NW29THST	20	Milling & Resurfacing (1-inch)	76.61	39,410.00	\$67,769.00	3.12%
2/16/2013	NW29THST	90	Milling & Resurfacing (1-inch)	78.05	18,984.00	\$31,237.00	5.71%
2/16/2013	NW33RDST	10	Milling & Resurfacing (1-inch)	78.15	21,187.00	\$34,753.00	12.12%
2/16/2013	NW33RDST	20	Milling & Resurfacing (1-inch)	71.92	18,676.00	\$36,625.00	8.19%
2/16/2013	NW33RDST	60	1-inch Overlay	80.13	13,917.00	\$21,502.00	7.77%
2/16/2013	NW35THLN	10	Milling & Resurfacing (1-inch)	77.47	41,860.00	\$70,128.00	4.87%
2/16/2013	NW37THST	10	Milling & Resurfacing (1-inch)	47.78	13,206.00	\$26,413.00	122.81%
2/16/2013	NW37THST	20	Milling & Resurfacing (1-inch)	45.54	5,597.00	\$11,193.00	190.49%
2/16/2013	NW38THST	10	Reconstruction (8" Base, 2" AC}	29.99	13,274.00	\$86,280.00	3.00%
2/16/2013	NW50THST	10	Milling & Resurfacing (1-inch)	78.7	26,440.00	\$42,620.00	6.55%
2/16/2013	NW52NDST	70	Milling & Resurfacing (1-inch)	67.97	10,753.00	\$22,151.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2013	NW52NDST	150	Milling & Resurfacing (1-inch)	67.97	13,431.00	\$27,667.00	3.00%
2/16/2013	NW53RDST	20	Milling & Resurfacing (1-inch)	67.97	13,540.00	\$27,893.00	3.00%
2/16/2013	NW56THST	50	1-inch Overlay	85.28	11,017.00	\$18,058.00	3.00%
2/16/2013	NW56THST	10	1-inch Overlay	80.88	29,212.00	\$45,132.00	5.82%
2/16/2013	NW56THST	20	Milling & Resurfacing (1-inch)	69.87	28,912.00	\$59,559.00	3.00%
2/16/2013	NW56THST	40	1-inch Overlay	81.67	14,634.00	\$22,610.00	3.72%
2/16/2013	NW82NDAVE	10	Milling & Resurfacing (1-inch)	76.61	15,939.00	\$27,409.00	3.12%
2/16/2013	NW82NDAVE	50	Milling & Resurfacing (1-inch)	70.89	24,586.00	\$49,519.00	5.34%
2/16/2013	NW82NDAVE	80	Milling & Resurfacing (1-inch)	79.65	16,777.00	\$26,223.00	10.97%
2/16/2013	NW82NDAVE	150	Milling & Resurfacing (1-inch)	69.49	10,160.00	\$20,929.00	3.00%
2/16/2013	NW88THAVE	10	1-inch Overlay	86.86	5,787.00	\$9,210.00	3.00%
2/16/2013	NW88THAVE	20	1-inch Overlay	80.41	18,985.00	\$29,332.00	3.89%
2/16/2013	NW88THST	11	1-inch Overlay	80.02	26,520.00	\$40,973.00	8.01%
2/16/2013	NW89THCT	20	1-inch Overlay	80.89	20,993.00	\$32,434.00	5.82%

.

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2014	NW102NDAVE	200	1-inch Overlay	82.44	3,656.00	\$5,818.00	3.00%
2/16/2014	NW102NDAVE	210	1-inch Overlay	85.16	22,270.00	\$35,439.00	3.00%
2/16/2014	NW105THAVE	10	1-inch Overlay	85.12	12,582.00	\$20,022.00	3.00%
2/16/2014	NW109THAVE	20	1-inch Overlay	86.05	28,153.00	\$44,802.00	3.00%
2/16/2014	NW109THAVE	180	1-inch Overlay	80.46	4,320.00	\$6,875.00	6.91%
2/16/2014	NW109THAVE	190	1-inch Overlay	80.46	8,100.00	\$12,890.00	6.91%
2/16/2014	NW109THAVE	120	1-inch Overlay	87.46	18,604.00	\$30,494.00	3.00%
2/16/2014	NW109THAVE	200	1-inch Overlay	80.46	5,136.00	\$8,173.00	6.91%
2/16/2014	NW109THAVE	210	1-inch Overlay	80.51	3,144.00	\$4,857.00	6.78%
2/16/2014	NW109THAVE	220	1-inch Overlay	80.46	5,232.00	\$8,326.00	6.91%
2/16/2014	NW109THAVE	230	1-inch Overlay	80.46	2,928.00	\$4,659.00	6.91%
2/16/2014	NW13THTER	10	1-inch Overlay	83.64	6,157.00	\$9,798.00	3.00%
2/16/2014	NW17THST	40	1-inch Overlay	83.41	23,476.00	\$37,359.00	3.00%
2/16/2014	NW18THTER	10	1-inch Overlay	85.16	41,619.00	\$66,231.00	3.00%
2/16/2014	NW18THTER	20	1-inch Overlay	84.37	14,976.00	\$23,832.00	3.00%
2/16/2014	NW21STST	20	1-inch Overlay	80.87	11,758.00	\$18,166.00	5.85%
2/16/2014	NW21STST	40	1-inch Overlay	85.27	17,926.00	\$29,383.00	3.00%
2/16/2014	NW21STST	60	1-inch Overlay	89.91	13,092.00	\$22,102.00	
2/16/2014	NW21STST	10	1-inch Overlay	81.12	16,212.00	\$25,799.00	5.20%
2/16/2014	NW21STST	70	1-inch Overlay	80.43	5,772.00	\$9,185.00	6.98%
2/16/2014	NW21STST	100	1-inch Overlay	81.68	5,222.00	\$8,310.00	3.00%
2/16/2014	NW21STST	120	1-inch Overlay	81.68	9,058.00	\$14,414.00	3.00%
2/16/2014	NW21STTER	10	Milling & Resurfacing (1-inch)	78.05	9,381.00	\$15,435.00	5.71%
2/16/2014	NW23RDST	20	1-inch Overlay	80.43	22,709.00	\$36,138.00	6.98%
2/16/2014	NW26THST	20	1-inch Overlay	80.43	30,935.00	\$49,229.00	6.98%
2/16/2014	NW29THST	80	1-inch Overlay	85.13	39,117.00	\$62,248.00	3.00%
2/16/2014	NW315TST	10	1-inch Overlay	84.24	29,029.00	\$46,196.00	3.00%
2/16/2014	NW31STTER	10	1-inch Overlay	86.05	20,529.00	\$32,669.00	3.00%
2/16/2014	NW33RDST	80	1-inch Overlay	89.41	28,465.00	\$48,056.00	
2/16/2014	NW33RDST	110	Milling & Resurfacing (1-inch)	67.98	40,026.00	\$82,453.00	3.00%
2/16/2014	NW33RDST	140	1-inch Overlay	85.27	26,265.00	\$43,051.00	3.00%
2/16/2014	NW33RDST	160	1-inch Overlay	87.2	19,758.00	\$32,385.00	3.00%
2/16/2014	NW33RDST	120	1-inch Overlay	85.11	18,059.00	\$28,738.00	3.00%
2/16/2014	NW33RDST	130	1-inch Overlay	86.04	37,046.00	\$58,954.00	3.00%
2/16/2014	NW33RDST	150	1-inch Overlay	84.41	10,119.00	\$16,104.00	3.00%
2/16/2014	NW33RDST	170	1-inch Overlay	83.55	18,218.00	\$28,991.00	3.00%
2/16/2014	NW33RDST	180	1-inch Overlay	80.97	39,797.00	\$63,331.00	6.23%
2/16/2014	NWSOTHST	30	1-inch Overlay	83.4	26,988.00	\$42,947.00	3.00%
2/16/2014	NW54THST	20	1-inch Overlay	83.4	13,355.00		3.00%
2/16/2014	NW54THST	30	1-inch Overlay	81.85	10,884.00	\$17,320.00	3.24%
2/16/2014	NW55THST	10	1-inch Overlay	83.4	10,854.00	\$17,272.00	3.00%
2/16/2014	NW55THST	20	1-inch Overlay	82.61	13,244.00	\$21,076.00	3.00%
2/16/2014	NW66THST	20	1-inch Overlay	86.04	51,836.00	\$82,489.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2014	NW78THAVE	10	1-inch Overlay	80.88	7,199.00	\$11,122.00	5.82%
2/16/2014	NW78THAVE	70	1-inch Overlay	82.61	7,277.00	\$11,579.00	3.00%
2/16/2014	NW82NDAVE	30	1-inch Overlay	83.4	15,832.00	\$25,195.00	3.00%
2/16/2014	NW84THAVE	120	1-inch Overlay	89.91	5,586.00	\$9,431.00	
2/16/2014	NW84THAVE	30	1-inch Overlay	86.04	16,495.00	\$26,249.00	3.00%
2/16/2014	NW84THAVE	40	1-inch Overlay	81.84	39,571.00	\$62,972.00	3.27%
2/16/2014	NW84THAVE	70	1-inch Overlay	80.43	32,772.00	\$52,151.00	6.98%
2/16/2014	NW84THAVE	90	1-inch Overlay	81.12	22,450.00	\$35,726.00	5.20%
2/16/2014	NW84THAVE	130	1-inch Overlay	85.11	12,726.00	\$20,251.00	3.00%
2/16/2014	NW84THAVE	160	1-inch Overlay	84.24	24,225.00	\$38,550.00	3.00%
2/16/2014	NW86THAVE	10	1-inch Overlay	80.43	12,162.00	\$19,354.00	6.98%
2/16/2014	NW87THCT	10	1-inch Overlay	80.43	17,076.00	\$27,174.00	6.98%
2/16/2014	NW89THCT	10	Milling & Resurfacing (1-inch)	62.21	6,549.00	\$13,097.00	3.00%
2/16/2014	NW89THCT	30	Milling & Resurfacing (1-inch)	79.39	16,602.00	\$26,171.00	7.37%
2/16/2014	NW89THCT	50	1-inch Overlay	83.64	18,990.00	\$30,219.00	3.00%
2/16/2014	NW89THCT	40	1-inch Overlay	84.33	13,944.00	\$22,855.00	3.00%
2/16/2014	NW89THCT	60	1-inch Overlay	82.29	15,375.00	\$24,467.00	3.00%
2/16/2014	NW89THPL	40	Milling & Resurfacing (1-inch)	66.44	2,043.00	\$4,208.00	3.00%
2/16/2014	NW89THPL	10	1-inch Overlay	85.47	21,483.00	\$35,212.00	3.00%
2/16/2014	NW89THPL	20	1-inch Overlay	85.98	18,244.00	\$29,033.00	3.00%
2/16/2014	NW89THPL	30	1-inch Overlay	85.98	27,925.00	\$44,438.00	3.00%
2/16/2014	NW91STAVE	10	1-inch Overlay	81.13	17,737.00	\$28,225.00	5.16%
2/16/2014	NW98THCT	10	1-inch Overlay	86.04	36,239.00	\$57,668.00	3.00%


Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2015	NW102NDAVE	100	1-inch Overlay	87.46	26,913.00	\$44,113.00	3.00%
2/16/2015	NW102NDAVE	260	1-inch Overlay	86.59	38,921.00	\$63,796.00	3.00%
2/16/2015	NW102NDAVE	190	Milling & Resurfacing (1-inch)	73.74	14,723.00	\$27,493.00	13.62%
2/16/2015	NW104THAVE	40	1-inch Overlay	86.31	21,446.00	\$35,151.00	3.00%
2/16/2015	NW104THAVE	30	Milling & Resurfacing (1-inch)	69.48	6,721.00	\$13,441.00	3.00%
2/16/2015	NW104THCT	10	1-inch Overlay	85.98	19,376.00	\$30,834.00	3.00%
2/16/2015	NW105THAVE	20	1-inch Overlay	87.33	8,888.00	\$14,569.00	3.00%
2/16/2015	NW105THAVE	30	1-inch Overlay	88.43	10,306.00	\$16,892.00	3.00%
2/16/2015	NW109THAVE	140	1-inch Overlay	89.8	2,860.00	\$4,688.00	3.00%
2/16/2015	NW109THAVE	150	1-inch Overlay	87.39	4,280.00	\$7,015.00	3.00%
2/16/2015	NW109THAVE	160	1-inch Overlay	87.39	7,120.00	\$11,670.00	3.00%
2/16/2015	NW109THAVE	170	1-inch Overlay	87.39	6,748.00	\$11,061.00	3.00%
2/16/2015	NW111THCT	1	1-inch Overlay	87.39	5,000.00	\$8,195.00	3.00%
2/16/2015	NW111THCT	2	1-inch Overlay	87.39	5,320.00	\$8,720.00	3.00%
2/16/2015	NW111THCT	3	1-inch Overlay	87.39	5,440.00	\$8,917.00	3.00%
2/16/2015	NW111THCT	4	1-inch Overlay	87.39	4,820.00	\$7,900.00	3.00%
2/16/2015	NW112THAVE	120	1-inch Overlay	86.05	17,936.00	\$28,542.00	3.00%
2/16/2015	NW112THAVE	20	1-inch Overlay	86.31	41,389.00	\$67,841.00	3.00%
2/16/2015	NW112THAVE	230	1-inch Overlay	85.28	19,895.00	\$32,611.00	3.00%
2/16/2015	NW112THPL	2	1-inch Overlay	87.39	5,880.00	\$9,638.00	3.00%
2/16/2015	NW112THPL	3	1-inch Overlay	87.39	5,628.00	\$9,225.00	3.00%
2/16/2015	NW113THAVE	1	1-inch Overlay	89.91	5,588.00	\$9,159.00	3.00%
2/16/2015	NW113THCT	10	1-inch Overlay	87.47	25,385.00	\$42,856.00	
2/16/2015	NW113THPL	1	1-inch Overlay	80.51	8,120.00	\$12,545.00	6.78%
2/16/2015	NW113THPSG	126	1-inch Overlay	90.8	3,297.00	\$5,566.00	
2/16/2015	NW114THAVE	160	Milling & Resurfacing (1-inch)	74.25	12,432.00	\$22,889.00	10.15%
2/16/2015	NW114THAVE	170	1-inch Overlay	BO.13	6,659.00	\$10,288.00	7.77%
2/16/2015	NW114THAVE	90	1-inch Overlay	85.13	18,876.00	\$30,039.00	3.00%
	NW114THAVE	100	1-inch Overlay	81.85	8,903.00	\$14,168.00	3.24%
2/16/2015	NW114THAVE	260	1-inch Overlay	86.05	6,588.00	\$10,484.00	3.00%
	NW114THAVE		1-inch Overlay	89.93	19,568.00	\$33,035.00	
2/16/2015	NW114THAVE		1-inch Overlay	89.93	7,998.00	\$13,503.00	
	NW114THAVE		1-inch Overlay	89.92	18,816.00	\$31,766.00	
	NW114THAVE		1-inch Overlay	88.78	25,359.00	\$41,565.00	3.00%
	NW114THAVE		1-inch Overlay	88.78	7,968.00	\$13,060.00	3.00%
	NW114THAVE		1-inch Overlay	87.46	27,464.00	\$45,017.00	3.00%
	NW114THAVE		1-inch Overlay	88.78	19,282.00	\$31,606.00	3.00%
	NW114THAVE		1-inch Overlay	84.33	15,947.00	\$26,139.00	3.00%
	NW114THAVE		1-inch Overlay	86.31	27,826.00	\$45,610.00	3.00%
	NW114THAVE		1-inch Overlay	88.78	11,797.00	\$19,337.00	3.00%
	NW17THST		1-inch Overlay	85.11	28,781.00	\$45,801.00	3.00%
	NW19THST		1-inch Overlay	88.77	10,962.00	\$17,968.00	3.00%
	NW19THST		1-inch Overlay	85.27	59,896.00	\$98,175.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2015	NW21STST	110	1-inch Overlay	85.28	23,074.00	\$37,820.00	3.00%
2/16/2015	NW26THST	10	1-inch Overlay	85.16	13,716.00	\$21,828.00	3.00%
2/16/2015	NW27THST	110	1-inch Overlay	89.91	28,512.00	\$48,135.00	
2/16/2015	NW27THST	10	1-inch Overlay	88.43	34,137.00	\$55,954.00	3.00%
2/16/2015	NW28THST	10	1-inch Overlay	88.43	13,548.00	\$22,207.00	3.00%
2/16/2015	NW36THTER	10	1-inch Overlay	83.4	14,919.00	\$23,742.00	3.00%
2/16/2015	NW39THST	1	1-inch Overlay	87.39	28,044.00	\$45,967.00	3.00%
2/16/2015	NW52NDST	210	1-inch Overlay	81.09	24,122.00	\$37,268.00	5.71%
2/16/2015	NW52NDST	90	1-inch Overlay	87.86	22,079.00	\$36,190.00	3.00%
2/16/2015	NW52NDST	200	1-inch Overlay	87.2	11,106.00	\$18,204.00	3.00%
2/16/2015	NW77THTER	1	1-inch Overlay	87.39	6,660.00	\$10,916.00	3.00%
2/16/2015	NW77THTER	2	1-inch Overlay	87.39	6,080.00	\$9,966.00	3.00%
2/16/2015	NW77THTER	3	1-inch Overlay	87.39	5,860.00	\$9,605.00	3.00%
2/16/2015	NW78THLN	1	1-inch Overlay	87.39	5,586.00	\$9,156.00	3.00%
2/16/2015	NW78THLN	2	1-inch Overlay	87.39	6,132.00	\$10,051.00	3.00%
2/16/2015	NW78THST	1	1-inch Overlay	86.32	26,900.00	\$44,092.00	3.00%
2/16/2015	NW78THST	2	1-inch Overlay	86.32	22,000.00	\$36,060.00	3.00%
2/16/2015	NW78THST	3	1-inch Overlay	86.32	6,321.00	\$10,361.00	
2/16/2015	NW78THST	4	1-inch Overlay	B6.32	5,880.00	\$9,638.00	3.00%
2/16/2015	NW78THST	5	1-inch Overlay	B6.32	7,119.00	\$11,669.00	3.00%
2/16/2015	NW78THST	6	1-inch Overlay	86.32	8,652.00	\$14,181.00	
2/16/2015	NW78THST	7	1-inch Overlay	86.32	4,074.00	\$6,678.00	3.00%
2/16/2015	NW79THLN	1	1-inch Overlay	87.39	11,680.00	\$19,145.00	3.00%
2/16/2015	NW79THLN	2	1-inch Overlay	87.39	5,840.00	\$9,572.00	3.00%
2/16/2015	NW79THLN	3	1-inch Overlay	87.39	5,500.00	\$9,015.00	3.00%
2/16/2015	NW80THLN	1	1-inch Overlay	87.39	19,200.00	\$31,471.00	3.00%
2/16/2015	NW80THLN	2	1-inch Overlay	87.39	22,040.00	\$36,126.00	3.00%
2/16/2015	NW82NDAVE	170	1-inch Overlay	90.55	9,345.00	\$15,778.00	
2/16/2015	NW82NDAVE	110	1-inch Overlay	87.21	19,667.00	\$32,236.00	3.00%
2/16/2015	NW82NDST	10	1-inch Overlay	86.86	48,605.00	\$77,347.00	3.00%
2/16/2015	NW82NDST	20	1-inch Overlay	85.48	42,487.00	\$69,640.00	3.00%
2/16/2015	NW82NDST	30	1-inch Overlay	89.72	74,357.00	\$121,879.00	3.00%
2/16/2015	NW84THAVE	110	1-inch Overlay	87.46	15,730.00	\$25,782.00	3.00%
2/16/2015	NW84TH5T	3	1-inch Overlay	80.51	5,340.00	\$8,250.00	6.78%
2/16/2015	NW84THST	1	1-inch Overlay	87.39	13,620.00	\$22,324.00	3.00%
2/16/2015	NW84THST	2	1-inch Overlay	87.39	5,280.00	\$8,654.00	3.00%
2/16/2015	NW84THST	4	1-inch Overlay	87.39	3,100.00	\$5,081.00	3.00%

•

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2014	NW100THAVE	50	1-inch Overlay_	84.24	19,681.00	\$31,319.00	3.00%
2/16/2012	NW102NDAVE	70	Milling & Resurfacing (1-inch)	69.21	12,161.00	\$24,322.00	3.00%
2/16/2015	NW102NDAVE	90	1-inch Overlay	85.27	26,224.00	\$42,984.00	3.00%
2/16/2016	NW102NDAVE	120	1-inch Overlay	89.91	36,792.00	\$62,114.00	
2/16/2015	NW102NDAVE	170	1-inch Overlay	90.19	5,549.00	\$9,095.00	3.00%
2/16/2016	NW102NDAVE	180	1-inch Overlay	87.47	25,161.00	\$42,478.00	
2/16/2016	NW102NDAVE	270	1-inch Overlay	90.55	10,774.00	\$18,190.00	
2/16/2016	NW102NDAVE	280	1-inch Overlay	90.55	11,839.00	\$19,987.00	
2/16/2016	NW102NDAVE	290	1-inch Overlay	90.55	27,521.00	\$46,462.00	
2/16/2014	NW108THAVE	20	1-inch Overlay	82.94	19,232.00	\$30,605.00	3.00%
2/16/2016	NW109THAVE	60	1-inch Overlay	89.91	7,286.00	\$12,300.00	
2/16/2016	NW109THAVE	80	1-inch Overlay	89.91	18,877.00	\$31,870.00	
2/16/2016	NW109THAVE	90	1-inch Overlay	89.91	11,260.00	\$19,009.00	
2/16/2013	NW110THAVE	10	1-inch Overlay	81.66	4,539.00	\$7,012.00	3.76%
2/16/2015	NW112THAVE	90	1-inch Overlay	87.47	21,184.00	\$35,764.00	
2/16/2016	NW112THAVE	110	1-inch Overlay	89.92	25,050.00	\$42,292.00	
2/16/2015	NW112THAVE	150	1-inch Overlay	88.78	6,340.00	\$10,393.00	3.00%
2/16/2015	NW112THAVE	160	1-inch Overlay	86.31	19,395.00	\$31,790.00	3.00%
2/16/2016	NW112THAVE	170	1-inch Overlay	89.92	11,655.00	\$19,677.00	
2/16/2016	NW112THAVE	180	1-inch Overlay	87.47	7,830.00	\$13,219.00	
2/16/2016	NW112THAVE	190	1-inch Overlay	89.91	18,818.00	\$31,769.00	
2/16/2014	NW112THAVE	220	1-inch Overlay	86.05	5,140.00	\$8,180.00	3.00%
2/16/2014	NW112THAVE	240	1-inch Overlay	84.24	13,439.00	\$21,387.00	3.00%
2/16/2016	NW112THAVE	250	1-inch Overlay	89.92	5,142.00	\$8,681.00	
2/16/2016	NW112THAVE	260	1-inch Overlay	89.91	21,415.00	\$36,154.00	
2/16/2013	NW112THAVE	270	Milling & Resurfacing (1-inch)	76.61	9,151.00	\$15,737.00	3.12%
2/16/2016	NW112THAVE	280	1-inch Overlay	87.47	25,963.00	\$43,833.00	
2/16/2015	NW112THCT	10	1-inch Overlay	88.78	43,567.00	\$71,411.00	3.00%
2/16/2016	NW115THAVE	10	1-inch Overlay	90.72	52,655.00	\$88,896.00	
2/16/2016	NW115THAVE	20	1-inch Overlay	90.72	19,507.00	\$32,932.00	
2/16/2016	NW117THAVE	10	1-inch Overlay	89.92	47,359.00	\$79,955.00	
2/16/2016	NW14THST	10	1-inch Overlay	87.47	32,484.00	\$54,841.00	
2/16/2016	NW15THTER	10	1-inch Overlay	89.91	19,076.00	\$32,205.00	
2/16/2015	NW29THST	40	1-inch Overlay	86.36	14,314.00	\$23,462.00	3.00%
2/16/2014	NW29THST	50	1-inch Overlay	85.16	28,032.00	\$44,609.00	3.00%
2/16/2014	NW29THST	60	1-inch Overlay	82.29	21,023.00	\$33,456.00	3.00%
2/16/2016	NW30THST	10	1-inch Overlay	87.47	26,603.00	\$44,912.00	
2/16/2016	NW30THST	20	1-inch Overlay	87.47	36,576.00	\$61,751.00	
2/16/2016	NW36THST	10	1-inch Overlay	89.92	39,358.00	\$66,447.00	
2/16/2016	NW50THST	20	1-inch Overlay	89.92	<u>17,</u> 480.00	\$29,511.00	
2/16/2016	NW50THST	40	1-inch Overlay	89.92	39,291.00	\$66,334.00	
2/16/2015	NW50THST	50	1-inch Overlay	88.78	15,801.00	\$25,900.00	3.00%
2/16/2015	NW50THST	70	1-inch Overlay	87.46	5,776.00	\$9,467.00	3.00%

Year	Street Name	SectionID	Recommended Work	PCI	Area (SF)	Cost	Delay Penalty
2/16/2015	NW52NDST	20	1-inch Overlay	86	21,745.00	\$35,642.00	3.00%
2/16/2016	NW52NDST	80	1-inch Overlay	90.55	10,052.00	\$16,971.00	
2/16/2016	NW52NDST	110	1-inch Overlay	90.55	15,899.00	\$26,842.00	
2/16/2016	NW52NDST	140	1-inch Overlay	90.55	12,037.00	\$20,322.00	
2/16/2014	NW52NDST	160	1-inch Overlay	85.84	6,883.00	\$10,953.00	3.00%
2/16/2013	NW52NDST	170	Milling & Resurfacing (1-inch)	68.1	6,944.00	\$14,305.00	3.00%
2/16/2016	NW52NDST	220	1-inch Overlay	89.41	18,636.00	\$31,463.00	
2/16/2016	NW53RDST	160	1-inch Overlay	89.92	10,725.00	\$18,107.00	
2/16/2016	NW57THST	10	1-inch Overlay	89.92	5,158.00	\$8,707.00	
2/16/2016	NW57THST	20	1-inch Overlay	89.92	14,803.00	\$24,992.00	
2/16/2016	NW78THAVE	20	1-inch Overlay	89.92	7,402.00	\$12,497.00	
2/16/2015	NW78THAVE	40	1-inch Overlay	88.78	6,642.00	\$10,887.00	3.00%
2/16/2014	NW82NDAVE	20	1-inch Overlay	82.44	16,236.00	\$25,837.00	3.00%
2/16/2016	NW82NDAVE	70	1-inch Overlay	90.55	13,699.00	\$23,128.00	
2/16/2013	NW82NDAVE	90	Milling & Resurfacing (1-inch)	76.68	34,473.00	\$59,155.00	13.08%
2/16/2014	NW82NDAVE	100	1-inch Overlay	85.16	20,885.00	\$33,236.00	3.00%
2/16/2014	NW82NDAVE	160	1-inch Overlay	85.84	5,806.00	\$9,239.00	3.00%
2/16/2013	NW82NDAVE	180	Milling & Resurfacing (1-inch)	78.17	22,529.00	\$36,931.00	12.13%
2/16/2016	NW84THAVE	60	1-inch Overlay	89.92	15,941.00	\$26,913.00	
2/16/2015	NW86THST	40	1-inch Overlay	88.78	4,517.00	\$7,403.00	3.00%
2/16/2016	NW86THST	60	1-inch Overlay	89.92	8,749.00	\$14,770.00	
2/16/2016	NW86THST	70	1-inch Overlay	89.92	13,017.00	\$21,976.00	
2/16/2016	NW98THCT	20	1-inch Overlay	89.91	36,546.00	\$61,700.00	



RESOLUTION NO. 12-

A RESOLUTION OF THE MAYOR AND THE CITY COUNCIL OF THE CITY OF DORAL, FLORIDA ADOPTING THE ROADWAY MAINTENANCE CAPITAL IMPROVEMENT PROGRAM (RMCIP) AS PRESENTED BY C3TS IN CONJUNCTION WITH THE PUBLIC WORKS DEPARTMENT; AND PROVIDING FOR AN EFFECTIVE DATE

WHEREAS, the Public Works Department has been implementing a 5-year Roadway Maintenance Capital Improvement Program (RMCIP) which was adopted by Council in 2007 and developed for the pavement maintenance and rehabilitation of local roads; and

WHEREAS, the City's consultants, Castella, Carballo, Thompson and Salman (C3TS), conducted an update of the RMCIP by evaluating the present condition of the pavement on our local roads; and

WHEREAS, Staff respectfully requests that the City Council adopt the RMCIP as presented by C3TS (Exhibit "A") in conjunction with the Public Works Department.

NOW, THEREFORE, BE IT RESOLVED BY THE CITY COUNCIL OF THE CITY OF DORAL AS FOLLOWS:

Section 1. The City Council of the City of Doral hereby adopts the RMCIP as presented by C3TS (Exhibit "A") in conjunction with the Public Works Department.

Section 2. This Resolution shall become effective immediately upon adoption.

The foregoing Resolution was offered by _____, who moved its adoption. The

motion was seconded by _____and upon being put to a vote, the vote was as follows:

Mayor Juan Carlos Bermudez Vice Mayor Michael DiPietro Councilmember Luigi Boria Councilmember Pete Cabrera Councilmember Ana Maria Rodriguez

PASSED AND ADOPTED this 14th day of March, 2012.

JUAN CARLOS BERMUDEZ, MAYOR

ATTEST:

BARBARA HERRERA, CITY CLERK

APPROVED AS TO FORM AND LEGAL SUFFICIENCY:

JIMMY L. MORALES, CITY ATTORNEY

EXHIBIT "A"

(Please refer to accompanying agenda documents)